## Compliance plan for Auckland Transport DUML October 2023

Deriving submission information			
Non-compliance	Description		
Audit Ref: 2.1 With: 11(1) of Schedule 15.3	The variance of wattage values between the SLV system and RAMM is calculated to be 1,243,880 kWh per annum. I have not considered this in the audit risk rating as RAMM is less accurate, but the more accurate SLV is being used for submission.		
Schedule 13.3	Over submission because of dimming being used. The impact on submission is unknown.		
	One item of load with no ICP recorded in the database.		
	18 items of load with zero or submission of 3,844 kWh per	blank wattage recorded indicati annum.	ng a potential under
	Incorrect wattages recorded i	n the database for a significant	number of LED lights.
	Incorrect ballasts applied to 1 over submission of 6,030 kWl	.30 items of load recorded resuln per annum.	ting in an estimated
	Any changes that are made during any given month take effect from the beginning of that month. This process does not account for historic changes or changes within a month.		
	Potential impact: High		
	Actual impact: High		
	Audit history: Multiple times		
From: 01-Jan-23	Controls: Moderate		
To: 02-Aug-23	Breach risk rating: 6		
Audit risk rating	Rationale for audit risk rating		
High	The controls are rated as moderate. The accuracy of the database has improved and will improve further with the SLV system being used to determine actual load for each light.		
	The audit risk rating is high due to the indicative kWh variances found for those that can be quantified.		
Actions taker	Actions taken to resolve the issue		Remedial action status
Data for submission is now being calculated from the SLV system under the HHS profile for all LED lights (approx. 93% of lights) which resolves the vast majority of issues that have been identified in relation to database and submission accuracy.		01 Sept 2023	Identified
Other wattage/ballast and ICP discrepancies are in the process of being reviewed and corrected by Auckland Transport.		28/02/2024	
Preventative actions taken to ensure no further issues will occur  Completion date			

Auckland Transport has robust controls in place to monitor and manage their streetlight network. There are daily comparisons between RAMM and SLV to ensure changes to the network are identified and any discrepancies are followed up.	Ongoing	
--	---------	--

ICP identifier and items of load			
Non-compliance	Description		
Audit Ref: 2.2	One item of load with no ICP recorded in the database.		
With: 11(2)(a) of			
Schedule 15.3	Potential impact: Low		
	Actual impact: Low		
	Audit history: Twice		
From: 01-Jan-23	Controls: Moderate		
To: 02-Aug-23	Breach risk rating: 2		
Audit risk rating	Rationale for audit risk rating		
Low	The controls are rated as moderate. ICP allocation of new load has robust controls but there is still some data cleansing to be done of historical data.		
	The impact on settlement and participants is minor; therefore, the audit risk rating is low.		
Actions taken to resolve the issue		Completion date	Remedial action status
Wattage/ballast and ICP discrepancies are in the process of being reviewed and corrected by Auckland Transport.		28/02/2024	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
Meridian will continue to made to the database.	follow up to ensure corrections are	Ongoing	

Description and capacity of load			
Non-compliance	Description		
Audit Ref: 2.4 With: 11(2)(c) and (d) of Schedule 15.3	18 items of load with zero or blank wattage recorded indicating a potential under submission of 3,844 kWh per annum.  Potential impact: Low  Actual impact: Low  Audit history: Multiple times		
From: 01-Jan-23	Controls: Moderate		
To: 02-Aug-23	Breach risk rating: 2		
Audit risk rating	Rationale for audit risk rating		
Low	The controls are rated as moderate. The accuracy of the database has improved, and processes continue to be strengthened to ensure accuracy.		
The audit risk rating is low due to pote  Actions taken to resolve the issue		Completion date	Remedial action status
Wattage/ballast and ICP discrepancies are in the process of being reviewed and corrected by Auckland Transport.		28/02/2024	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
Meridian will continue to made to the database.	follow up to ensure corrections are	Ongoing	

All load recorded in database			
Non-compliance	Description		
Audit Ref: 2.5	Four additional lights found in the field of 1,401 sampled.		
With: 11(2A) of	Potential impact: Low		
Schedule 15.3	Actual impact: Low		
	Audit history: Multiple times		
From: 01-Jan-23	Controls: Moderate		
To: 02-Aug-23	Breach risk rating: 2		
Audit risk rating	Rationale for audit risk rating		
Low	The controls are recorded as moderate as they will mitigate risk most of the time but there is room for improvement.		
	The impact is assessed to be low due to the small number of additional lights found in the field in relation to the overall count of the items of load.		
Actions taken to resolve the issue		Completion date	Remedial action status
Field audit discrepancies are in the process of being reviewed and corrected by Auckland Transport.		28/02/2024	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
Meridian will continue to follow up to ensure corrections are made to the database.		Ongoing	

Database accuracy			
Non-compliance	Description		
Audit Ref: 3.1 With: Clause 15.2 and	Incorrect wattages recorded in the database for a significant number of LED lights.		
15.37B(b)	Incorrect ballasts applied to 130 items of load recorded resulting in an estimated over submission of 6,030 kWh per annum.		
	Potential impact: High		
	Actual impact: High		
From: 01-Jan-23	Audit history: Multiple times		
To: 02-Aug-23	Controls: Moderate		
	Breach risk rating: 6		
Audit risk rating	Rationale for audit risk rating		
High	The controls are rated as moderate. The accuracy of the database has improved and will improve further with the SLV system being used to determine actual load for each light.  The impact is assessed to be high, based on the kWh differences described above.		
Actions ta	Actions taken to resolve the issue Completion Remedial action sta		
Data for submission is now being calculated from the SLV system under the HHS profile for all LED lights (approx. 93% of lights).		1 Sept 2023	Identified
Ballast discrepancies are in the process of being reviewed and corrected by Auckland Transport.		28/02/2024	
Preventative actions taken to ensure no further issues will occur		Completion date	

Volume information accuracy				
Non-compliance	Description			
Audit Ref: 3.2 With: Clause 15.2 and 15.37B(c)	The variance of wattage values between the SLV system and RAMM is calculated to be 1,243,880 kWh per annum. I have not considered this in the audit risk rating as RAMM is less accurate, but the more accurate SLV is being used for submission.			
	Over submission because of dimming being used. The impact on submission is unknown.			
	One item of load with no ICP recorded in the database.			
	18 items of load with zero or blank wattage recorded indicating a potential under submission of 3,844 kWh per annum.			
	Incorrect wattages recorded in the database for a significant number of LED lights.			
	Incorrect ballasts applied to 130 items estimated over submission of 6,030 kV		resulting in an	
	Any changes that are made during any given month take effect from the beginning of that month. This process does not account for historic changes or changes within a month.			
	Potential impact: High			
From: 01-Jan-23	Actual impact: High			
To: 02-Aug-23	Audit history: Multiple times			
10. 02 /lug 23	Controls: Moderate			
	Breach risk rating: 6			
Audit risk rating	Rationale for audit risk rating			
High	The controls are rated as moderate. The accuracy of the database has improved and will improve further with the SLV system being used to determine actual load for each light.			
	The audit risk rating is high due to the that can be quantified.	indicative kWh va	ariances found for those	
Actions taken to resolve the issue		Completion date	Remedial action status	
Data for submission is now being calculated from the SLV system under the HHS profile for all LED lights (approx. 93% of lights) which resolves the vast majority of issues that have been identified in relation to database and submission accuracy.		01 Sept 2023	Identified	
Other wattage/ballast and ICP discrepancies are in the process of being reviewed and corrected by Auckland Transport.		28/02/2024		
Preventative actions to	aken to ensure no further issues will occur	Completion date		

Auckland Transport has robust controls in place to monitor and manage their streetlight network. There are daily comparisons between RAMM and SLV to ensure changes to the network are identified and any discrepancies are followed	Ongoing	
up.		