## Compliance Plan for Genesis Energy - Tasman DC DUML 2023

| Deriving submission information   |   |                 |                        |
|---|---|-----------------|------------------------|
| Non-compliance  | Description   |                 |                        |
| Audit Ref: 2.1 With: Clause 11(1) of  | The field audit found that the database accuracy was not accurate within ±5.0%, which could result in estimated over submission of 35,700 kWh per annum.  |                 |                        |
| Schedule 15.3   | There is one missing gear wattage which could result in estimated under submission of 47 kWh per annum.   |                 |                        |
|   | Six lamp models had inaccurate total wattages recorded which could result in estimated over submission of 111 kWh per annum. This total also includes the 50W SON light described above.  The previous audit found four lamps in a new subdivision at Summerfield Boulevard that had 13W LED recorded in the database but were labelled as 28W LEDs (GIS access codes 15096, 15106, 15117 and 15121). These remain incorrect and could result in estimated under submission of 64 kWh per annum.  The database extract is provided as a snapshot, and daily changes are not reflected in the submission data.  Potential impact: Medium |                 |                        |
|   |   |                 |                        |
|   |   |                 |                        |
|   |   |                 |                        |
| Actual impact: Medium   |   |                 |                        |
|   | Audit history: Multiple times previously  |                 |                        |
| From: 12-Jun-23   | Controls: Weak  |                 |                        |
| To: 31-Jul-23   | Breach risk rating: 6   |                 |                        |
| Audit risk rating   | Rationale for audit risk rating   |                 |                        |
| Medium  | The controls are recorded as weak because database accuracy is not within ±5.0%, indicating that changes may not be being accurately captured. The impact is assessed to be medium based on the potential kWh impact.   |                 |                        |
| Actions taken to resolve the issue  |   | Completion date | Remedial action status |
| Tasman District Council has taken their database management in-house and will work with Powertech to ensure all inconsistencies captured in this report are resolved. |   | 15/10/2023      | Identified             |
| Preventative actions t  | aken to ensure no further issues will occur   | Completion date |                        |
| this report will capture  | will build a report to run routinely, all blank fields and exceptions in the vill also be run against Network   | 1/1/2024        |                        |

| Location of each item of load               |  |      |  |
|---|--|------|--|
| Non-compliance                              | Description  |      |  |
| Audit Ref: 2.3                              | 180 items of load with insufficient location details.  |      |  |
| With: Clause 11(2)(b) Potential impact: Low |  |      |  |
| of Schedule 15.3                            | Actual impact: Low   |      |  |
|   | Audit history: Multiple times  |      |  |
| From: 04-Feb-22 Controls: Moderate          |  |      |  |
| To: 31-Jul-23                               | Breach risk rating: 2  |      |  |
| Audit risk rating                           | Rationale for audit risk rating  |      |  |
| Low   | Controls are rated as moderate because most items of load have complete addresses.  The audit risk rating is recorded as low due to the small number of lights that cannot be readily located. |      |  |
| Actions to                                  | Actions taken to resolve the issue Completion Remedial action status   |      |  |
|   |  | date |  |

| Actions taken to resolve the issue   | Completion date | Remedial action status |
|--|-----------------|------------------------|
| Tasman District Council will add GPS coordinates to new connections and review the database to ensure all GPS fields are completed where possible. | 1/1/2024        | Identified             |
| Preventative actions taken to ensure no further issues will  | Completion      |                        |
| occur  | date            |                        |

| Description and capacity of load  |  |  |  |
|---|--|--|--|
| Non-compliance  | Description  |  |  |
| Audit Ref: 2.4 With: Clause 11(2)(c) and (d) of Schedule 15.3 From: 12-Jun-23 | One 50W SON light (GIS access code 14656) was recorded with 50W total but should have had 61W including gear wattage.  Potential impact: Low  Actual impact: Low  Audit history: None  Controls: Strong  Breach risk rating: 1 |  |  |
| To: 12-Jun-23   | breach his rating. 1   |  |  |
| Audit risk rating   | Rationale for audit risk rating  |  |  |
| Low   | The controls are rated as strong, because one light has a missing gear wattage. The impact is low, with estimated under submission of 47 kWh per annum.  |  |  |

| Actions taken to resolve the issue  | Completion date | Remedial action status |
|---|-----------------|------------------------|
| Tasman District Council will work with Powertech to ensure this gear wattage is corrected in the database and matching what is in the field.          | 1/10/2023       | Identified             |
| Preventative actions taken to ensure no further issues will occur   | Completion date |                        |
| Tasman District Council and Powertech will work together to establish processes to better share and receive information to ensure database integrity. | 1/1/2024        |                        |

| Database accuracy   |  |                 |                        |
|---|--|-----------------|------------------------|
| Non-compliance  | Description  |                 |                        |
| Audit Ref: 3.1 With: Clause 15.2 and  | The field audit found that the database accuracy was not accurate within ±5.0%, we could result in estimated over submission of 35,700 kWh per annum.  There is one missing gear wattage which could result in estimated under submission 47 kWh per annum.  |                 |                        |
| 15.37B(b)   |  |                 |                        |
|   | Six lamp models had inaccurate total wattages recorded which could result in estimated over submission of 111 kWh per annum. This total also includes the 50W SON light described above.   |                 |                        |
|   | The previous audit found four lamps in a new subdivision at Summerfield Boulevard that had 13W LED recorded in the database but were labelled as 28W LEDs (GIS access codes 15096, 15106, 15117 and 15121). These remain incorrect and could result in estimated under submission of 64 kWh per annum. |                 |                        |
|   | Potential impact: Medium   |                 |                        |
|   | Actual impact: Medium  Audit history: Multiple times previously  |                 |                        |
|   |  |                 |                        |
| From: 12-Jun-23   | Controls: Weak   |                 |                        |
| To: 31-Jul-23   | Breach risk rating: 6  |                 |                        |
| Audit risk rating   | Rationale for audit risk rating  |                 |                        |
| Medium  | The controls are recorded as weak because database accuracy is not within ±5.0%, indicating that changes may not be being accurately captured. The impact is assessed to be medium based on the potential kWh impact.  |                 |                        |
| Actions ta  | ken to resolve the issue   | Completion date | Remedial action status |
| Tasman District Council has taken their database management in-house and will work with Powertech to ensure all inconsistencies captured in this report are resolved. |  | 15/10/2023      | Identified             |
| Preventative actions taken to ensure no further issues will Completion occur date   |  |                 |                        |
| Tasman District Council will build a report to run routinely,   |  | 1/1/2024        |                        |

this report will capture all blank fields and exceptions in the RAMM database. This will also be run against Network

Tasman's database.

| Volume information accuracy   |  |                 |                        |
|---|--|-----------------|------------------------|
| Non-compliance  | Description  |                 |                        |
| Audit Ref: 3.2 With: Clause 15.2 and  | The field audit found that the database accuracy was not accurate within ±5.0%, which could result in estimated over submission of 35,700 kWh per annum.   |                 |                        |
| 15.37B(c)   | There is one missing gear wattage which could result in estimated under submission of 47 kWh per annum.  |                 |                        |
|   | Six lamp models had inaccurate total wattages recorded which could result in estimated over submission of 111 kWh per annum. This total also includes the 50W SON light described above.   |                 |                        |
|   | The previous audit found four lamps in a new subdivision at Summerfield Boulevard that had 13W LED recorded in the database but were labelled as 28W LEDs (GIS access codes 15096, 15106, 15117 and 15121). These remain incorrect and could result in estimated under submission of 64 kWh per annum. |                 |                        |
|   | The database extract is provided as a snapshot, and daily changes are not reflected in the submission data.  |                 |                        |
|   | Potential impact: Medium   |                 |                        |
|   | Actual impact: Medium  |                 |                        |
|   | Audit history: Multiple times previously   |                 |                        |
| From: 12-Jun-23   | Controls: Weak   |                 |                        |
| To: 31-Jul-23   | Breach risk rating: 6  |                 |                        |
| Audit risk rating   | Rationale for audit risk rating  |                 |                        |
| Medium  | The controls are recorded as weak because database accuracy is not within ±5.0%, indicating that changes may not be being accurately captured. The impact is assessed to be medium based on the potential kWh impact.  |                 |                        |
| Actions taken to resolve the issue  |  | Completion date | Remedial action status |
| Tasman District Council has taken their database management in-house and will work with Powertech to ensure all inconsistencies captured in this report are resolved.                                 |  | 15/10/2023      | Identified             |
| Preventative actions taken to ensure no further issues will occur   |  | Completion date |                        |
| Tasman District Council will build a report to run routinely, this report will capture all blank fields and exceptions in the RAMM database. This will also be run against Network Tasman's database. |  | 1/1/2024        |                        |