

Actions taken to resolve the issue	Completion date	Remedial action status
<p>Meridian is working with Auckland Transport to determine whether eligibility criteria for recently approved profiles can be met with the SLV system or whether a further profile for the dimming lights will be necessary.</p> <p>Meridian has notified Auckland Transport of the discrepancies and required corrections. Auckland Transport has advised that they will be conducting site visits and will work on corrections over the next 2 months. There has been a dedicated resource allocated.</p>	<p>Ongoing</p> <p>1/7/2022</p>	<p>Identified</p>
Preventative actions taken to ensure no further issues will occur	Completion date	
<p>Meridian will continue to work with Auckland Transport regularly to ensure continued improvements on the database and that corrections are up to date.</p> <p>Once there is an approved profile for the dimming lights and the SLV System Output is used for submission, there will be significant improvement on accuracy</p>	<p>Ongoing</p>	

ICP identifier and items of load		
Non-compliance	Description	
<p>Audit Ref: 2.2</p> <p>With: 11(2)(a) of Schedule 15.3</p> <p>From: 30-Apr-21</p> <p>To: 05-Apr-22</p>	<p>No load associated with ICP 0000041244WE13A resulting in an estimated 20,586.11 kWh being reconciled to the incorrect ICP and network.</p> <p>Potential impact: Medium</p> <p>Actual impact: Medium</p> <p>Audit history: None</p> <p>Controls: Weak</p> <p>Breach risk rating: 6</p>	
Audit risk rating	Rationale for audit risk rating	
Medium	<p>The controls are rated as weak as the accuracy of load associated with ICPs is not managed.</p> <p>The audit risk rating is medium due to potential submission against the incorrect NSP and balancing area having a direct impact on settlement</p>	
Actions taken to resolve the issue		Completion date
<p>Meridian has notified Auckland Transport of the discrepancies and required corrections. Auckland Transport has advised that they will be conducting site visits and will work on corrections over the next 2 months. There has been a dedicated resource allocated.</p>		1/7/2022
Preventative actions taken to ensure no further issues will occur		Completion date
<p>Meridian will continue to work with Auckland Transport regularly to ensure continued improvements on the database and that corrections are up to date.</p> <p>Once there is an approved profile for the dimming lights and the SLV System Output is used for submission, there will be significant improvement on accuracy</p>		Ongoing
Remedial action status		
Identified		

Description and capacity of load		
Non-compliance	Description	
<p>Audit Ref: 2.4</p> <p>With: 11(2)(c) and (d) of Schedule 15.3</p> <p>From: 03-May-21</p> <p>To: 31-Mar-22</p>	<p>185 items of load with blank or zero wattage recorded. 173 of these have no lamp description resulting in an estimated annual under submission of 39,507 kWh.</p> <p>134 items of load with invalid descriptions.</p> <p>Potential impact: High</p> <p>Actual impact: Medium</p> <p>Audit history: Multiple times</p> <p>Controls: Moderate</p> <p>Breach risk rating: 4</p>	
Audit risk rating	Rationale for audit risk rating	
Medium	<p>The controls are rated as moderate. Meridian are working with Auckland Transport to align the data in RAMM with SLV and SLV is expected to be used for the LED lighting load which will move the controls to strong.</p> <p>The audit risk rating is medium due to potential under submission of 39,507 kWh per annum.</p>	
Actions taken to resolve the issue	Completion date	Remedial action status
Meridian has notified Auckland Transport of the discrepancies and required corrections. Auckland Transport has advised that they will be conducting site visits and will work on corrections over the next 2 months. There has been a dedicated resource allocated.	1/7/2022	Identified
Preventative actions taken to ensure no further issues will occur	Completion date	
<p>Meridian will continue to work with Auckland Transport regularly to ensure continued improvements on the database and that corrections are up to date.</p> <p>Once there is an approved profile for the dimming lights and the SLV System Output is used for submission, there will be significant improvement on accuracy</p>	Ongoing	

All load recorded in database			
Non-compliance	Description		
<p>Audit Ref: 2.5</p> <p>With: 11(2A) of Schedule 15.3</p> <p>From: 01-Aug-20</p> <p>To: 30-Apr-21</p>	<p>48 additional lights found in the field or 5.5% of the load sampled.</p> <p>Potential impact: High</p> <p>Actual impact: Medium</p> <p>Audit history: Multiple times</p> <p>Controls: Moderate</p> <p>Breach risk rating: 4</p>		
Audit risk rating	Rationale for audit risk rating		
Medium	<p>The controls are recorded as moderate as they will mitigate risk most of the time but there is room for improvement.</p> <p>The audit risk rating is medium as the number of additional lights found in the field was 5% of the overall sample checked which would potentially have a medium impact on reconciliation accuracy for this large database.</p>		
Actions taken to resolve the issue		Completion date	Remedial action status
<p>Meridian has notified Auckland Transport of the discrepancies and required corrections. Auckland Transport has advised that they will be conducting site visits and will work on corrections over the next 2 months. There has been a dedicated resource allocated.</p>		1/7/2022	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
<p>Meridian will continue to work with Auckland Transport regularly to ensure continued improvements on the database and that corrections are up to date.</p> <p>Once there is an approved profile for the dimming lights and the SLV System Output is used for submission, there will be significant improvement on accuracy</p>		Ongoing	

Actions taken to resolve the issue	Completion date	Remedial action status
No comment provided		Identified
Preventative actions taken to ensure no further issues will occur	Completion date	
<p>Meridian will continue to work with Auckland Transport regularly to ensure continued improvements on the database and that corrections are up to date.</p> <p>Once there is an approved profile for the dimming lights and the SLV System Output is used for submission, there will be significant improvement on accuracy</p>	Ongoing	

Actions taken to resolve the issue	Completion date	Remedial action status
<p>Meridian is working with Auckland Transport to determine whether eligibility criteria for recently approved profiles can be met with the SLV system or whether a further profile for the dimming lights will be necessary.</p> <p>Meridian has notified Auckland Transport of the discrepancies and required corrections. Auckland Transport has advised that they will be conducting site visits and will work on corrections over the next 2 months. There has been a dedicated resource allocated.</p>	<p>Ongoing</p> <p>1/7/2022</p>	<p>Identified</p>
Preventative actions taken to ensure no further issues will occur	Completion date	
<p>Meridian will continue to work with Auckland Transport regularly to ensure continued improvements on the database and that corrections are up to date.</p> <p>Once there is an approved profile for the dimming lights and the SLV System Output is used for submission, there will be significant improvement on accuracy</p>	<p>Ongoing</p>	