ELECTRICITY INDUSTRY PARTICIPATION CODE RECONCILIATION PARTICIPANT AUDIT REPORT



For

PAUA TO THE PEOPLE LIMITED

Prepared by: Steve Woods

Date audit commenced: 3 October 2022

Date audit report completed: 14 November 2022

Audit report due date: 15 November 2022

TABLE OF CONTENTS

	·	
Non-	compliances	7
Reco	mmendations	10
Issue	S	11
Admi	inistrative	12
1.1.	Exemptions from Obligations to Comply with Code (Section 11)	12
1.2.	Structure of Organisation	
	·	
Oper	ational Infrastructure	20
•		
2.4.	,	
2.5.	Retailer responsibility for electricity conveyed - participant obligations (Clause 10.4)	
2.6.	Retailer responsibility for electricity conveyed - access to metering installations (Clau	
	•	
	· · · · · · · · · · · · · · · · · · ·	
2.16.	Removal or breakage of seals (Clause 48(1C), 48 (1D), 48 (1E), 48 (1F) of Schedule 10.	7)30
	· · · · · · · · · · · · · · · · · · ·	
	,, , , , , , , , , , , , , , , , , , , ,	
Main	taining registry information	35
3.1.		
	· · · · · · · · · · · · · · · · · · ·	
	Non-Reco Issue Admi 1.1. 1.2. 1.3. 1.4. 1.5. 1.6. 1.7. 1.8. 1.9. 1.10. Oper 2.1. 2.2. 2.3. 2.4. 2.5. 2.6. 2.7. 2.8. 2.9. 2.10. 2.11. 2.12. 2.13. 2.14. 2.15. 2.16. 2.17. 2.18. 3.1. 3.2. 3.3. 3.4. 3.5.	 Structure of Organisation Persons involved in this audit Use of Agents (Clause 15.34) Hardware and Software Breaches or Breach Allegations ICP Data Authorisation Received Scope of Audit Summary of previous audit Operational Infrastructure Relevant information (Clause 10.6, 11.2, 15.2) Provision of information (Clause 15.35) Data transmission (Clause 20 Schedule 15.2) Audit trails (Clause 21 Schedule 15.2) Retailer responsibility for electricity conveyed - participant obligations (Clause 10.7(2),(4),(5) and (6)) Physical location of metering installations (Clause 10.35(1)&(2)) Trader contracts to permit assignment by the Authority (Clause 11.15B) Connection of an ICP (Clause 10.32) Temporary Electrical Connection of an ICP (Clause 10.33(1)) Lit. Electrical Connection of Point of Connection (Clause 10.33A) Arrangements for Ine function services (Clause 11.16) Arrangements for metering equipment provision (Clause 10.36) Connecting ICPs then withdrawing switch (Clause 10.33A(5)) Electrical disconnection of (Ps (Clause 10.33B) Removal or breakage of seals (Clause 48(1C), 48 (1D), 48 (1E), 48 (1F) of Schedule 10. Provision of information on dispute resolution scheme (Clause 11.30A) Provision of information on electricity plan comparison site (Clause 11.30B) Providing registry information (Clause 10.3 Schedule 11.1) Providing registry information (Clause 10.3 Schedule 11.1) Trader responsibility for an ICP (Clause 11.18)

	3.7. 3.8. 3.9. 3.10.	Changes to unmetered load (Clause 9(1)(f) of Schedule 11.1)	42 43
4.	Perfo	orming customer and embedded generator switching4	47
	4.1. 4.2.	Inform registry of switch request for ICPs - standard switch (Clause 2 Schedule 11.3)4 Losing trader response to switch request and event dates - standard switch (Clauses 3 Schedule 11.3)	and 4
	4.3. 4.4. 4.5.	Losing trader must provide final information - standard switch (Clause 5 Schedule 11.3) Retailers must use same reading - standard switch (Clause 6(1) and 6A Schedule 11.3) Non-half hour switch event meter reading - standard switch (Clause 6(2) and (3) Schedule 11.3)	52 dule
	4.6.	Disputes - standard switch (Clause 7 Schedule 11.3)	54
	4.7.	Gaining trader informs registry of switch request - switch move (Clause 9 Schedule 11	•
	4.8.		
	4.9.	Losing trader determines a different date - switch move (Clause 10(2) Schedule 11.3) !	58
		. Losing trader must provide final information - switch move (Clause 11 Schedule 11.3)!	
	4.11.	. Gaining trader changes to switch meter reading - switch move (Clause 12 Schedule 11	
	4.12.	. Gaining trader informs registry of switch request - gaining trader switch (Clause 14 Scl 11.3)	
	4.13.	. Losing trader provision of information - gaining trader switch (Clause 15 Schedule 11.3	3)63
	4.14.	. Gaining trader to advise the registry manager - gaining trader switch (Clause 16 Sched 11.3)	
	4.15.	. Withdrawal of switch requests (Clauses 17 and 18 Schedule 11.3)	
	4.16.	. Metering information (Clause 21 Schedule 11.3)	66
		. Switch protection (Clause 1(a)&(b) of Part 1 and 11.15AA to 11.15AC of Part 11)	
5.	Main	ntenance of unmetered load	68
	5.1.	Maintaining shared unmetered load (Clause 11.14)	68
	5.2.	Unmetered threshold (Clause 10.14 (2)(b))	
	5.3.	Unmetered threshold exceeded (Clause 10.14 (5))	69
	5.4.	Distributed unmetered load (Clause 11 Schedule 15.3, Clause 15.37B)	70
6.	Gath	ering raw meter data	
	6.1.	Electricity conveyed & notification by embedded generators (Clause 10.13, Clause 10. 15.13)	
	6.2.	Responsibility for metering at GIP (Clause 10.26 (6), (7) and (8))	72
	6.3.	Certification of control devices (Clause 33 Schedule 10.7 and clause 2(2) Schedule 15.3	3)72
	6.4.	Reporting of defective metering installations (Clause 10.43(2) and (3))	73
	6.5.	Collection of information by certified reconciliation participant (Clause 2 Schedule 15.	2)73
	6.6.	Derivation of meter readings (Clauses 3(1), 3(2) and 5 Schedule 15.2)	74
	6.7.	NHH meter reading application (Clause 6 Schedule 15.2)	75
	6.8.	Interrogate meters once (Clause 7(1) and (2) Schedule 15.2)	
	6.9.	NHH meters interrogated annually (Clause 8(1) and (2) Schedule 15.2)	76
	6.10.	. NHH meters 90% read rate (Clause 9(1) and (2) Schedule 15.2)	
		. NHH meter interrogation log (Clause 10 Schedule 15.2)	
	6.12.	. HHR data collection (Clause 11(1) Schedule 15.2)	78
	6.13.	. HHR interrogation data requirement (Clause 11(2) Schedule 15.2)	78

	6.14.	HHR interrogation log requirements (Clause 11(3) Schedule 15.2)	79
7.	Stori	ng raw meter data	80
	7.1.	Trading period duration (Clause 13 Schedule 15.2)	80
	7.2.	Archiving and storage of raw meter data (Clause 18 Schedule 15.2)	80
	7.3.	Non metering information collected/archived (Clause 21(5) Schedule 15.2)	
8. infori		ting and managing (including validating, estimating, storing, correcting and archiving	
	8.1.	Correction of NHH meter readings (Clause 19(1) Schedule 15.2)	82
	8.2.	Correction of HHR metering information (Clause 19(2) Schedule 15.2)	
	8.3.	Error and loss compensation arrangements (Clause 19(3) Schedule 15.2)	
	8.4.	Correction of HHR and NHH raw meter data (Clause 19(4) and (5) Schedule 15.2)	
9.	Estin	nating and validating volume information	86
	9.1.	Identification of readings (Clause 3(3) Schedule 15.2)	86
	9.2.	Derivation of volume information (Clause 3(4) Schedule 15.2)	
	9.3.	Meter data used to derive volume information (Clause 3(5) Schedule 15.2)	
	9.4.	Half hour estimates (Clause 15 Schedule 15.2)	88
	9.5.	NHH metering information data validation (Clause 16 Schedule 15.2)	89
	9.6.	Electronic meter readings and estimated readings (Clause 17 Schedule 15.2)	90
10. (claus		sion of metering information to the GRID OWNER in accordance with subpart 4 of F 38(1)(f))	
	10.1	Generators to provide HHR metering information (Clause 13.136)	93
		Unoffered & intermittent generation provision of metering information (Clause 13	
		Loss adjustment of HHR metering information (Clause 13.138)	-
		Notification of the provision of HHR metering information (Clause 13.140)	
11.	Provi	sion of submission information for reconciliation	95
		Buying and selling notifications (Clause 15.3)	
	11.2.	Calculation of ICP days (Clause 15.6)	95
		Electricity supplied information provision to the reconciliation manager (Clause 15 HHR aggregates information provision to the reconciliation manager (Clause 15.8)	•
12.	Subn	nission computation	100
		Daylight saving adjustment (Clause 15.36)	
		Creation of submission information (Clause 15.4)	
		Allocation of submission information (Clause 15.5)	
		Grid owner volumes information (Clause 15.9)	
		Provision of NSP submission information (Clause 15.10)	
		Grid connected generation (Clause 15.11)	
		Accuracy of submission information (Clause 15.12)	
		Permanence of meter readings for reconciliation (Clause 4 Schedule 15.2)	
		Reconciliation participants to prepare information (Clause 2 Schedule 15.3)	
		D.Historical estimates and forward estimates (Clause 3 Schedule 15.3)	
		2.Forward estimate process (Clause 4 and 5 schedule 15.3)	
		3.Compulsory meter reading after profile change (Clause 7 Schedule 15.3)	
12			
13.		nission format and timing	
	12 1	Provision of submission information to the RM (Clause 8 Schedule 15.3)	111

13.2. Reporting resolution (Clause 9 Schedule 15.3)	112
13.3. Historical estimate reporting to RM (Clause 10 Schedule 15.3)	
Conclusion	114
Participant response	115

EXECUTIVE SUMMARY

This Electricity Industry Participation Code Reconciliation Participant audit was performed at the request of **Paua to the People Limited (Paua)**, to support their application for renewal of certification in accordance with clauses 5 and 7 of schedule 15.1. The audit was conducted in accordance with the Guideline for Reconciliation Participant Audits version 7.2.

Paua supplies HHR AMI ICPs with metering category 1, and HHR submission type. No ICPs with unmetered load are supplied, and one ICP with distributed generation is supplied.

Paua's bespoke HHR data management system began to be used for HHR meter data processes from 30 November 2020, following the material change audit. It was fully implemented for importing and exporting registry data, estimation, correction, and submission from 23 March 2021.

Paua's registry management and switching processes are robust and the overall data accuracy was found to be high. Eight of the non-compliances identified relate to the implementation of an upgrade to Paua's HHR data management system which resulted in a number of automated processes being offline for a period of time. Paua has taken a number of learnings from this upgrade to ensure any future system upgrades do not have similar impacts.

Three alleged breaches occurred during the audit period and these related to the availability of key personnel during these time critical timelines. The resourcing issues have been resolved and no recent alleged breaches have occurred since.

Paua continues to supply HHR AMI customers only and relies on AMI reads provided by MEPs. Compliant processes are in place for estimation and correction, and revised submission data is now consistently provided.

This audit identified 15 non-compliances and makes four recommendations. The audit risk rating is 15 indicating that the next audit should be due in 18 months. While this is a slight reduction on compliance since the last audit, the majority of non-compliance stem from two specific events around a system upgrade and temporary resource issues.

The date of the next audit is determined by the Electricity Authority and is dependent on the level of compliance during this audit. The table below provides some guidance on this matter, and I have considered this result in conjunction with Paua's responses and also their progress in resolving 11 of the non compliance identified in this report with the remaining identified non compliances are just awaiting submission revisions to complete the remedial actions. My recommendation for the next audit date is 24 months

The matters raised are shown in the tables below:

AUDIT SUMMARY

NON-COMPLIANCES

Subject	Section	Clause	Non-Compliance	Controls	Audit Risk Rating	Breach Risk Rating	Remedial Action
Provision of information	2.2	Clause 15.35	Three occurrences of failing to deliver submission files on time.	Strong	Low	1	Cleared
Changes to registry information	3.3	10 Schedule 11.1	Three late status updates.	Strong	Low	1	Cleared
ANZSIC codes	3.6	Clause 9 (1(k) of Schedule 11.1	ICP 0000157936TR838 was populated with an incorrect ANZSIC code.	Strong	Low	1	Cleared
Management of "active" status	3.8	Clause 17 Schedule 11.1	ICP 0000010333TR4E4 was populated with an incorrect inactive status.	Strong	Low	1	Cleared
Management of "inactive" status	3.9	Clause 19 Schedule 11.1	Three ICPs had consumption during inactive periods, indicating that their status was incorrect. Estimated under submission of 36 kWh has occurred	Strong	Low	1	Identified
Losing trader response to switch request and event dates - standard switch	4.2	3 and 4 Schedule 11.3	Ten AN timing breaches. Four Transfer ANs applied the incorrect response code.	Strong	Low	1	Cleared
Losing trader must provide final information - standard switch	4.3	5 Schedule 11.3	16 CS breaches due to the late delivery of a CS file. One transfer CS file contained an incorrect switch event read.	Strong	Low	1	Cleared

Subject	Section	Clause	Non-Compliance	Controls	Audit Risk Rating	Breach Risk Rating	Remedial Action
Losing trader provides information - switch move	4.8	10(1) Schedule 11.3	Three AN breaches. Ten T2 breaches.	Strong	Low	1	Cleared
Gaining trader changes to switch meter reading - switch move	4.11	Clause 12 Schedule 11.3	Switch event reading not used for ICP (0000047860TR436).	Strong	Low	1	Cleared
Withdrawal of switch requests	4.15	Clauses 17 and 18 Schedule 11.3	Two AW files were delivered late.	Strong	Low	1	Cleared
Correction of HHR metering information	8.2	Clause 19(2) Schedule 15.2	Some HHR consumption volume not accounted for during a HHR meter change for ICP 0000121079TR333.	Strong	Low	1	Identified
Meter data used to derive volume information	9.3	3(5) Schedule 15.2	The HHR aggregates information is not aligned with HHR submission volumes for September R1 and R3.	Strong	Low	1	Cleared
Half hour estimates	9.4	Clause 15 Schedule 15.2	The estimation performed for ICP 0000126746TR077 did not match the consumption calculated from the supplied midnight reads by 11 kWh.	Strong	Low	1	Cleared

Subject	Section	Clause	Non-Compliance	Controls	Audit Risk Rating	Breach Risk Rating	Remedial Action
Creation of submission information	12.2	15.4	Three ICPs where consumption occurred during an inactive period resulting in under submission of HHR volumes. The estimation performed for ICP 0000126746TR077 did not match the consumption calculated from the supplied midnight reads by 11 kWh. Some HHR consumption volume not accounted for during a HHR meter change for ICP 0000121079TR333. AV-090 Submission file for December 2020 R14 included corrupt data for one trading period.	Strong	Low	1	Identified

Subject	Section	Clause	Non-Compliance	Controls	Audit Risk Rating	Breach Risk Rating	Remedial Action
Accuracy of submission information	12.7	15.12	Three ICPs where consumption occurred during an inactive period resulting in under submission of HHR volumes. The estimation performed for ICP 0000126746TR077 did not match the consumption calculated from the supplied midnight reads by 11 kWh. Some HHR consumption volume not accounted for during a HHR meter change for ICP 0000121079TR333. Submission files delivered late on two occasions.	Strong	Low	Rating 1	Identified
			AV-090 Submission file for December 2020 R14 included corrupt data for one trading period.				
Future Risk Rati	ng						15

Future risk rating	0	1-3	4-15	16-40	41-55	55+
Indicative audit frequency	36 months	24 months	18 months	12 months	6 months	3 months

RECOMMENDATIONS

Subject	Section	Description	Recommendation
Standardise use of inactive reason codes where disconnection is remote by AMI meter	3.9	Management of "inactive" status	For remote disconnections by AMI meter, that Paua standardises the use of a single inactive status reason code (7 – remote by AMI meter) which will assist potential gaining traders in terms of arranging the appropriate reconnection task where these ICPs switch away.

Electronic meter readings and estimated readings	9.6	Maximum allowable interval value	Recommend that Paua considers implementing additional validation encompassing checking interval data against the metering installation capacity.
Creation of submission information	12.2	Rotation of tasks	Paua to implement a task rotation schedule with its support resource to ensure they are familiar with each time dependant process, and this will also ensure both the primary and back up personnel are aware of upcoming submission deadlines.
Permanence of meter readings for reconciliation	12.8	Identify outstanding gaps in interval data and escalate	Paua to implement a process where all outstanding gaps in interval data are identified and escalated to the relevant MEP in a timely manner to ensure all available data has been provided to Paua before it is determined that the data gap is unrecoverable, and the interim estimation becomes permanent.

ISSUES

Subject	Section	Description	Issue
		Nil	

1. ADMINISTRATIVE

1.1. Exemptions from Obligations to Comply with Code (Section 11)

Code reference

Section 11 of Electricity Industry Act 2010.

Code related audit information

Section 11 of the Electricity Industry Act provides for the Electricity Authority to exempt any participant from compliance with all or any of the clauses.

Audit observation

Current code exemptions were reviewed on the Electricity Authority website.

Audit commentary

There are no exemptions in place that are relevant to the scope of this audit.

1.2. Structure of Organisation

The structure of the organisation was provided.

1.3. Persons involved in this audit

Auditors:

Name	Company	Role
Steve Woods	Veritek Limited	Lead Auditor
Bernie Cross	Veritek Limited	Supporting Auditor

Paua personnel assisting in this audit were:

Name	Title
Mark Hughes	Managing Director

1.4. Use of Agents (Clause 15.34)

Code reference

Clause 15.34

Code related audit information

A reconciliation participant who uses an agent

- remains responsible for the contractor's fulfilment of the participant's Code obligations
- cannot assert that it is not responsible or liable for the obligation due to something the agent has or has not done.

Audit observation

Any agents used by Paua were identified and their agent reports assessed as a part of this audit.

Audit commentary


Paua receives HHR data from AMS, Intellihub and Metrix as MEPs. Paua does not use estimates created by the MEPs, and instead creates their own using their bespoke HHR data management system.

1.5. Hardware and Software

Paua uses a bespoke HHR data management system, developed by Paua to manage customer, ICP, meter, and submission data. This system imports and exports registry information and generates submission files for the reconciliation manager. Status and trader updates are processed manually on the registry.

This bespoke HHR data management system began to be used for HHR meter data processes from 30 November 2020, following the material change audit. This system was fully implemented for importing and exporting registry data, estimation, correction, and submission from 23 March 2021.

System and participant interactions are shown below:



Paua utilises the following software:

Task	Software	Notes
Security	Norton	Remote server has full security suite protection.
SFTP	winSCP	Automated uploads and downloads of data to and from remote servers.
Disaster Recovery	OneDrive	Physical and one drive back-ups are performed.

Task	Software	Notes
CRM/Billing	the HHR data management system application and SQL Server database	The database is backed up weekly. Backups will be completed nightly when activity increases. Access to HHR data management system is restricted using Windows authentication. Paua confirmed that the disaster recovery and system restore processes have been tested.

1.6. Breaches or Breach Allegations

Three alleged breaches have occurred since the last audit.

Ref	Breach Description	Clause	Outcome
2104GIVE1	GIVE (Paua to the People Limited) failed to submit data to the Reconciliation Manager by 16:00 on 4 March 2021. GIVE failed to provide submissions for AV-140 (HHRAGGR), AV-060 (ICPDAYS), AV-090 (HHRVOLS) and AV-120 (BILLED) by the deadline at 16:00 on BD4. After being contacted GIVE submitted all required files by 16:19 on 4 March 2021, 19 minutes after the deadline.	Part 15 clause 15.4 (1)	closed
2105GIVE1	Paua to the People Limited (GIVE) failed to submit information to the reconciliation manager by 1600 hours on the 13th business day of the reconciliation period. GIVE failed to submit their AV-090 (HHR volumes) for R1 and R3 by 16:00 on BD13. On BD13 at 15:16 the Reconciliation Manager sent an email to GIVE as no washup files had been received. The Reconciliation Manager then called GIVE at 15:35 to chase the files. GIVE told the Reconciliation Manager they had forgotten. They confirmed they would submit. Unfortunately, 2 of their files didn't make the deadline and were uploaded after the gate was closed.	Part 15 clause 15.4 (2)	closed
2108GIVE1	GIVE submitted wrong volumes for NSP CPK0111-CKHK. In their AV-090 (HHR submission) file for NSP CPK0111-CKHK 3/12/2020 TP1 they submitted 59,019 kWh. This was well over the rest of their submissions for that NSP (all between 4 and 50 kWh per trading period).	Part 15 Schedule 1 5.2 clause 15.2 (1) (a)	closed

1.7. ICP Data

Paua's active ICPs are summarised by meter category in the table below:

Metering Category	Number of ICPs (Sept 2022)	Number of ICPs (Mar 2021)	Number of ICPs (Sep 2020)	Number of ICPs (Apr 2020)	Number of ICPs (Oct 2018)	Number of ICPs (Jan 2018)
1	264	444	519	577	1,205	920
2	-	-	-	-	-	-
3	-	-	-	-	-	-
4	-	-	-	-	-	-
5	-	-	-	-	-	-
9	-	-	-	-	-	-

Paua's ICPs are summarised by status in the table below:

Status	Number of ICPs (Sept 2022)	Number of ICPs (Mar 2021)	Number of ICPs (Sep 2020)	Number of ICPs (Apr 2020)	Number of ICPs (Oct 2018)	Number of ICPs (Jan 2018)
Active (2,0)	264	444	517	576	1,205	920
Inactive – new connection in progress (1,12)	-	-	-	-	-	-
Inactive – electrically disconnected vacant property (1,4)	-	1	1	-	2	1
Inactive – electrically disconnected remotely by AMI meter (1,7)	-	1	1	1	6	4
Inactive – electrically disconnected at pole fuse (1,8)	-	-	-	-	-	1
Inactive – electrically disconnected due to meter disconnected (1,9)	-	-	-	-	-	-
Inactive – electrically disconnected at meter box fuse (1,10)	-	-	-	-	-	-
Inactive – electrically disconnected at meter box switch (1,11)	-	-	-	-	-	1
Inactive – electrically disconnected ready for decommissioning (1,6)	-	-	-	-	-	-
Inactive – reconciled elsewhere (1,5)	-	-	-	-	-	-
Decommissioned (3)	-	-	-	-	-	-

1.8. Authorisation Received

An authorisation email was provided.


1.9. Scope of Audit

This Electricity Industry Participation Code Reconciliation Participant audit was performed at the request of Paua, to support their application for renewal of certification in accordance with clauses 5 and 7 of schedule 15.1.

The audit was conducted in accordance with the Guideline for Reconciliation Participant Audits V7.2.

The audit was carried out on site on 25 October 2022. Registry list, event detail and audit compliance reports for 1 March 2021 to 30 September 2022 and a registry list snapshot for 8 October 2022 were reviewed.

The scope of the audit is shown in the diagram below, with the Paua audit boundary shown for clarity.



The table below shows the tasks under clause 15.38 of part 15 for which Paua requires certification. AMS, Intellihub, and Metrix provide AMI data as MEPs. Paua does not use estimates created by the MEPs, and instead creates their own using its bespoke HHR data management system.

Tasks Requiring Certification Under Clause 15.38(1) of Part 15	Agents Involved in Performance of Tasks	MEPs Providing AMI data
(a) - Maintaining registry information and performing customer and embedded generator switching		
(b) – Gathering and storing raw meter data		AMS – HHR (AMI) MTRX - HHR (AMI) IHUB - HHR (AMI)

Tasks Requiring Certification Under Clause 15.38(1) of Part 15	Agents Involved in Performance of Tasks	MEPs Providing AMI data
(c)(iii) - Creation and management of volume information		AMS – HHR (AMI) MTRX - HHR (AMI) IHUB - HHR (AMI)
(d) – Calculation of ICP days		
(da) - delivery of electricity supplied information under clause 15.7		
(db) - delivery of information from retailer and direct purchaser half hourly metered ICPs under clause 15.8		
(e) – Provision of submission information for reconciliation		

1.10. Summary of previous audit

Paua provided a copy of their previous audit conducted in April 2021 by Tara Gannon of Veritek Limited. The summary tables below show the status of the non-compliances and recommendations raised in the previous audit. Further comment is made in the relevant sections of this report.

Table of Non-compliance

Subject	Section	Clause	Non-compliance	Status
Changes to registry information	3.3	10 Schedule 11.1	Two late status updates.	Still existing
Inform registry of switch request for ICPs - standard switch	4.1	2 Schedule 11.3	The NT files for ICPs 0000045037TR2B9 (event date 3 September 2020) and 0001406533UNA1D (26 November 2020) were issued three and four business days after preconditions were met.	Cleared
Losing trader response to switch request and event dates - standard switch	4.2	3 and 4 Schedule 11.3	Eight AN breaches.	Still existing
Losing trader must provide final information - standard switch	4.3	5 Schedule 11.3	Three CS breaches. One transfer CS file contained an incorrect last actual read date.	Still existing

Subject	Section	Clause	Non-compliance	Status
Losing trader provides information - switch move	4.8	10(1) Schedule 11.3	Three AN breaches. Ten T2 breaches.	Still existing
Losing trader must provide final information - switch move	4.10	11 Schedule 11.3	Seven switch move CS files contained incorrect last actual read dates.	Still existing
Meter data used to derive volume information	9.3	3(5) Schedule 15.2	The HHR aggregates information is truncated to two decimal places at trading period level before being summed by ICP to produce the submission information.	Cleared
ICP days	11.2	15.6	ICP days for 0000170598TR21D were double counted in error from 12 February 2021 because the HHR data management system counted one set of ICP days for each flow direction. The issue was detected and resolved prior to the audit, and I confirmed that the current ICP days values in the HHR data management system are correct.	Cleared
HHR aggregates information provision to the reconciliation manager	11.4	15.8	The HHR aggregates file does not contain electricity supplied information.	Still existing
Creation of submission information	12.2	15.4	Under submission of 10 kWh for ICP 0000145867TRED0 for consumption during an inactive period	Still existing
Accuracy of submission information	12.7	15.12	Under submission of 10 kWh for ICP 0000145867TRED0 for consumption during an inactive period.	Still existing

Table of Recommendations

Subject	Section	Clause	Recommendation	Status
Electrical Connection of Point of Connection	2.11	Reconnection of uncertified meter installations	Identify uncertified meters which are to be reconnected and arrange for the MEP to re-certify.	Cleared
Collection of information by certified reconciliation participant	6.5	Clock synchronisation corrections	Consider whether a correction to spread the consumption between the period of clock adjustment and any previous missing trading periods is required when reviewing clock synchronisation events affecting more than one trading period.	Cleared

2. OPERATIONAL INFRASTRUCTURE

2.1. Relevant information (Clause 10.6, 11.2, 15.2)

Code reference

Clause 10.6, 11.2, 15.2

Code related audit information

A participant must take all practicable steps to ensure that information that the participant is required to provide is:

- a) complete and accurate
- b) not misleading or deceptive
- c) not likely to mislead or deceive.

If the participant becomes aware that in providing information under this Part, the participant has not complied with that obligation, the participant must, as soon as practicable, provide such further information as is necessary to ensure that the participant does comply.

Audit observation

The processes to find and correct incorrect information was examined. The registry validation processes were examined in relation to the achievement of this requirement.

The registry list and ACO20 reports were examined to identify any registry discrepancies, and to confirm that all information was correct and not misleading.

Audit commentary

Most trader-maintained information is recorded only on the registry, including status. All status and trader updates are processed manually using the registry interface. The HHR data management system contains fields for the MEP and ANZSIC code.

Changes to trader and status information are infrequent.

- Trader information is expected to change rarely, if ever. There have been no updates to trader
 information during the audit period. All ICPs in the HHR data management system will have
 HHR profile and submission type, no unmetered load has been or is expected to be supplied,
 and Paua only accepts ICPs with AMS, Intellihub or Metrix as the MEP. Only one ICP with
 distributed generation is supplied.
- Status changes are processed manually on the registry once Paua has confirmed the correct status and event date. Processes are in place to identify and estimate missing data for periods with active status, and to raise field services checks for ICPs which have not received actual meter data for 28 days or more.

A daily ICP list with history (including all data from January 2015 onwards) is downloaded from the registry and imported into the HHR data management system. This is used to determine reconciliation report aggregation factors, any changes to the ICP attributes, and whether the ICP is active and expected to be included in reconciliation reports and receive metering data. Changes to attributes are reported to the operator for investigation as alerts in the action hub, including changes to:

- distributor unmetered load details: if unmetered load is found, Paua would relinquish
 responsibility for shared unmetered load if allowed under clause 11.14, or would arrange for the
 ICP to switch out;
- · distributed generation, and
- dedicated NSP.

Notification and acknowledgement files are not reviewed, discrepancies will be identified through action hub validation.

Prior to the implementation of the HHR data management system, Paua downloaded an ICP List monthly and Foxworks created a report of any exceptions. This compared ICP status, network, POC, loss factor, MEP, multiplier, distributed generation, and indicators of unmetered load to the data recorded in Foxworks. Any discrepancies were investigated and corrected. Paua also completed a weekly status check. Checks for unmetered load changes were not completed prior to the implementation of the HHR data management system, but review of the registry list confirmed that no unmetered load has ever been supplied.

The audit compliance report was reviewed and found:

Issue	Sept 2022 Qty	Mar 2021 Qty	Sep 2020 Qty	Oct 2018 Qty	Jan 2018 Qty	Comments
Blank ANZSIC codes	-	-	-	-	-	Compliant.
ANZSIC "T99" series	-	-	-	-	-	Compliant.
UML load = zero	-	-	-	-	-	Compliant, no unmetered load was identified.
Incorrect UML load	-	-	-	-	-	Compliant, no unmetered load was identified.
Shared unmetered load incorrect	-	-	-	-	-	Compliant, no unmetered load was identified.
ICPs with Distributor unmetered load populated but retail unmetered load is blank and UML flag = N	-	-	-	-	-	Compliant, no unmetered load was identified.
No MEP recorded or nominated and UML= "N"	-	-	-	-	-	Compliant, all ICPs have an MEP.
Active Category 9 and UML "N"	-	-	-	-	-	Compliant, all ICPs have metering category 1.
Incorrect profile	-	-	-	-	-	Compliant, all ICPs have HHR profile.
Incorrect submission type	-	-	-	-	-	Compliant, all ICPs have HHR submission type.
Incorrect status or status date	-	-	-	1	1	Compliant.

Audit outcome

Compliant

2.2. Provision of information (Clause 15.35)

Code reference

Clause 15.35

Code related audit information

If an obligation exists to provide information in accordance with Part 15, a participant must deliver that information to the required person within the timeframe specified in the Code, or, in the absence of any such timeframe, within any timeframe notified by the Authority. Such information must be delivered in the format determined from time to time by the Authority.

Audit observation

Processes to provide information were reviewed and observed throughout the audit.

Audit commentary

This area is discussed in a number of sections in this report and compliance is confirmed.

The HHR data management system contains a reconciliation schedule which includes the due dates for each revision, and I walked through the revision submission generation process. There have been three alleged breaches for late provision of submission information during the audit period. The underlying cause of the late delivery of submission files was the availability of key personnel during these time critical timelines. The resourcing issues have been resolved and no recent alleged breaches have occurred since. Non compliance is recorded for the three failures to provide submission data on time.

Audit outcome

Non-compliant

Non-compliance	Description					
Audit Ref: 2.2	Three occurrences of failing to deliver submission files on time.					
With: Clause 15.35	Potential impact: Low					
	Actual impact: Low					
	Audit history: None					
From: 01-Mar-21	Controls: Strong					
To: 30-Sep-22	Breach risk rating: 1					
Audit risk rating	Rationale for audit risk rating					
Low	The controls are strong as the is a schedule inbuilt within the system to alert users when submission files are due however key personnel availability resulted in delayed file delivery.					
Actions taken to resolve the issue		Completion date	Remedial action status			
All reports are submitted to match the required submission schedule		Cleared	Cleared			
Preventative actions tal	ken to ensure no further issues will occur	Completion date				

We have introduced reminders to email us on days that reports are due. We have also added visible reminders on our Action and Reconciliation hubs.	Implemented	
We now have automated the entire process so that AV reports can be produced within minutes of being happy with the data. All reports are checked prior to dispatch		

2.3. Data transmission (Clause 20 Schedule 15.2)

Code reference

Clause 20 Schedule 15.2

Code related audit information

Transmissions and transfers of data related to metering information between reconciliation participants or their agents, for the purposes of the Code, must be carried out electronically using systems that ensure the security and integrity of the data transmitted and received.

Audit observation

HHR AMI data is provided by AMS, Intellihub and Metrix via SFTP.

To confirm the process, I traced six monthly ICP volumes for HHR ICPs from the source data to the HHR data management system and the HHR aggregates submissions. The sample included all MEPs.

Audit commentary

HHR AMI data is provided by AMS, Intellihub and Metrix via SFTP, and automatically imported into the HHR data management system. Missing data is estimated on import and replaced with actual data if it becomes available at a later date.

I traced six monthly ICP volumes for HHR ICPs from the source data to the HHR data management system and the HHR aggregates submissions. The volumes were recorded in the HHR data management system and the submissions matched the raw data provided.

For all ICPs except two, the readings are based on actual meter data, field services paperwork, are provided by another trader via the switching process, or estimated. Paua are using customer supplied readings for two ICPs with ongoing AMI communication issues by way of a monthly photo provided by the customer which is then used for estimation of interval data purposes. Both ICPs are awaiting a modem upgrade to 4G which is expected to resolve the communication issue.

Audit outcome

Compliant

2.4. Audit trails (Clause 21 Schedule 15.2)

Code reference

Clause 21 Schedule 15.2

Code related audit information

Each reconciliation participant must ensure that a complete audit trail exists for all data gathering, validation, and processing functions of the reconciliation participant.

The audit trail must include details of information:

- provided to and received from the registry manager,
- provided to and received from the reconciliation manager,
- provided and received from other reconciliation participants and their agents.

The audit trail must cover all archived data in accordance with clause 18.

The logs of communications and processing activities must form part of the audit trail, including if automated processes are in operation.

Logs must be printed and filed as hard copy or maintained as data files in a secure form, along with other archived information.

The logs must include (at a minimum) the following:

- an activity identifier (clause 21(4)(a))
- the date and time of the activity (clause 21(4)(b))
- the operator identifier for the person who performed the activity (clause 21(4)(c)).

Audit observation

Audit trails were discussed and reviewed.

Audit commentary

Audit trails were reviewed and the logs include the activity identifier, date, time, and an operator identifier.

Paua has recently upgraded its HHR data management systems front end and as part of this effort a full back load of HHR interval data from the original source interval data files was conducted. The audit trail clearly identifies the reload of data that has occurred.

Audit outcome

Compliant

2.5. Retailer responsibility for electricity conveyed - participant obligations (Clause 10.4)

Code reference

Clause 10.4

Code related audit information

If a participant must obtain a consumer's consent, approval, or authorisation, the participant must ensure it:

- extends to the full term of the arrangement,
- covers any participants who may need to rely on that consent.

Audit observation

I reviewed Paua's current terms and conditions.

Audit commentary

Paua's Terms and Conditions include consent to access for authorised parties for the duration of the contract.

Audit outcome

Compliant

2.6. Retailer responsibility for electricity conveyed - access to metering installations (Clause 10.7(2),(4),(5) and (6))

Code reference

Clause 10.7(2),(4),(5) and (6)

Code related audit information

The responsible reconciliation participant must, if requested, arrange access for the metering installation to the following parties:

- the Authority
- an ATH
- an auditor
- an MEP
- a gaining metering equipment provider.

The trader must use its best endeavours to provide access:

- in accordance with any agreements in place
- in a manner and timeframe which is appropriate in the circumstances.

If the trader has a consumer, the trader must obtain authorisation from the customer for access to the metering installation, otherwise it must arrange access to the metering installation.

The reconciliation participant must provide any necessary facilities, codes, keys or other means to enable the party to obtain access to the metering installation by the most practicable means.

Audit observation

I reviewed Paua's current terms and conditions.

Audit commentary

Paua's Terms and Conditions include consent to access for authorised parties for the duration of the contract. Paua confirmed that they have been able to arrange access for other parties when requested.

Audit outcome

Compliant

2.7. Physical location of metering installations (Clause 10.35(1)&(2))

Code reference

Clause 10.35(1)&(2)

Code related audit information

A reconciliation participant responsible for ensuring there is a category 1 metering installation or category 2 metering installation must ensure that the metering installation is located as physically close to a point of connection as practical in the circumstances.

A reconciliation participant responsible for ensuring there is a category 3 or higher metering installation must:

- a) if practical in the circumstances, ensure that the metering installation is located at a point of connection; or
- b) if it is not practical in the circumstances to locate the metering installation at the point of connection, calculate the quantity of electricity conveyed through the point of connection using a loss compensation process approved by the certifying ATH.

Audit observation

The physical meter location point is not specifically mentioned in the terms and conditions, but the existing practices in the electricity industry achieve compliance.

Review of a registry list with history confirmed that Paua do not supply any ICPs with metering category 2 or above.

Audit commentary

Paua only supplies ICPs with metering category 1 and does not deal with any installations with loss compensation.

Audit outcome

Compliant

2.8. Trader contracts to permit assignment by the Authority (Clause 11.15B)

Code reference

Clause 11.15B

Code related audit information

A trader must at all times ensure that the terms of each contract between a customer and a trader permit:

- the Authority to assign the rights and obligations of the trader under the contract to another trader if the trader commits an event of default under paragraph (a) or (b) or (f) or (h) of clause 14.41 (clause 11.15B(1)(a)); and
- the terms of the assigned contract to be amended on such an assignment to—
- the standard terms that the recipient trader would normally have offered to the customer immediately before the event of default occurred (clause 11.15B(1)(b)(i)); or
- such other terms that are more advantageous to the customer than the standard terms, as the recipient trader and the Authority agree (clause 11.15B(1)(b)(ii); and
- the terms of the assigned contract to be amended on such an assignment to include a minimum term in respect of which the customer must pay an amount for cancelling the contract before the expiry of the minimum term (clause 11.15B(1)(c)); and
- the trader to provide information about the customer to the Authority and for the Authority to provide the information to another trader if required under Schedule 11.5 (clause 11.15B(1)(d)); and
- the trader to assign the rights and obligations of the trader to another trader (clause 11.15B(1)(e)).

The terms specified in subclause (1) must be expressed to be for the benefit of the Authority for the purposes of the Contracts (Privacy) Act 1982, and not be able to be amended without the consent of the Authority (clause 11.15B(2)).

Audit observation

I reviewed Paua's current terms and conditions.

Audit commentary

Paua's terms and conditions contain the appropriate clauses to achieve compliance with this requirement.

Audit outcome

Compliant

2.9. Connection of an ICP (Clause 10.32)

Code reference

Clause 10.32

Code related audit information

A reconciliation participant must only request the connection of a point of connection if they:

- accept responsibility for their obligations in Parts 10, 11 and 15 for the point of connection; and
- have an arrangement with an MEP to provide 1 or more metering installations for the point of connection.

Audit observation

New connections were discussed. The registry list, event detail report and audit compliance report for the audit period were examined to determine whether any new connections were completed during the audit period.

Audit commentary

Paua does not intend to handle new connections, and ICPs must be connected before they will be accepted by Paua. Review of the registry reports confirmed that Paua has not completed any new connections during the audit period.

Audit outcome

Compliant

2.10. Temporary Electrical Connection of an ICP (Clause 10.33(1))

Code reference

Clause 10.33(1)

Code related audit information

A reconciliation participant may temporarily electrically connect a point of connection, or authorise a MEP to temporarily electrically connect a point of connection, only if:

- for a point of connection to the grid the grid owner has approved the connection,
- for an NSP that is not a point of connection to the grid the relevant distributor has approved the connection.
- for a point of connection that is an ICP, but is not as NSP:
- the reconciliation participant is recorded in the registry as the trader responsible for the ICP,
- if the ICP has metered load, 1 or more certified metering installations are in place,
- if the ICP has not previously been electrically connected, the relevant distributor has given written approval of the temporary electrical connection.

Audit observation

New connections were discussed. The registry list, event detail report and audit compliance report for the audit period were examined to determine whether any new connections were completed during the audit period.

Audit commentary

No new connections were completed during the audit period, and no temporary connections were identified.

Audit outcome

Compliant

2.11. Electrical Connection of Point of Connection (Clause 10.33A)

Code reference

Clause 10.33A(1)

Code related audit information

A reconciliation participant may electrically connect or authorise the electrical connection of a point of connection only if:

- for a point of connection to the grid the grid owner has approved the connection,
- for an NSP that is not a point of connection to the grid the relevant distributor has approved the connection.
- for a point of connection that is an ICP, but is not as NSP:
 - the trader is recorded in the registry as the trader responsible for the ICP or has an arrangement with the customer and initiates a switch within 2 business days of electrical connection,
 - if the ICP has metered load, 1 or more certified metering installations are in place,
 - o if the ICP has not previously been electrically connected, the relevant distributor has given written approval of the electrical connection.

Audit observation

New connection, reconnection and meter bridging processes were discussed. The registry list, event detail report and audit compliance report for the audit period were examined to determine compliance.

Audit commentary

New connections

No new connections were completed during the audit period.

Reconnections

Five ICPs were reconnected on switch in. The audit compliance report confirmed that all the reconnected ICPs had certified meters installed, and Paua was listed as the responsible retailer at the time of reconnection. All reconnections are performed by the AMI MEP.

Paua has implemented a process to identify if reconnection of an uncertified meter has occurred and to then engage with the MEP to ensure that they are already aware of the certification status of their metering installation and have arranged for it to be re-certified.

Bridged meters

Paua does not normally allow meters to be bridged, and no bridged meters were identified during the audit period.

Audit outcome

Compliant

2.12. Arrangements for line function services (Clause 11.16)

Code reference

Clause 11.16

Code related audit information

Before providing the registry manager with any information in accordance with clause 11.7(2) or clause 11.18(4), a trader must ensure that it, or its customer, has made any necessary arrangements for the provision of line function services in relation to the relevant ICP.

Before providing the registry manager with any information in accordance with clause 11.7(2) or clause 11.18(4), a trader must have entered into an arrangement with an MEP for each metering installation at the ICP.

Audit observation

The process to ensure an arrangement is in place before trading commences on a network was examined, along with the application process. The registry list was examined to confirm the networks Paua trades on.

Audit commentary

Paua only trades on the Wellington Electricity network and has a Use of System Agreement with Wellington Electricity. Before an application is accepted, ICPs are checked on the registry to confirm the network is Wellington Electricity.

Audit outcome

Compliant

2.13. Arrangements for metering equipment provision (Clause 10.36)

Code reference

Clause 10.36

Code related audit information

A reconciliation participant must ensure it has an arrangement with the relevant MEP prior to accepting responsibility for an installation.

Audit observation

The process to ensure an arrangement is in place with the metering equipment provider before an ICP can be created or switched in was checked. The registry list was examined to confirm the MEPs for Paua's ICPs.

Audit commentary

All current Paua ICPs have AMS (258 ICPs), Intellihub (one ICP), or Metrix (five ICPs) as their MEP. Paua demonstrated that an arrangement is currently in place with each MEP. Before an application is accepted, ICPs are checked on the registry to confirm the MEP is AMS, Intellihub or Metrix.

Audit outcome

Compliant

2.14. Connecting ICPs then withdrawing switch (Clause 10.33A(5))

Code reference

Clause 10.33B

Code related audit information

If a trader connects an ICP it is in the process of switching and the switch does not proceed or is withdrawn the trader must:

- restore the disconnection, including removing any bypass and disconnecting using the same method the losing trader used,
- reimburse the losing trader for any direct costs incurred.

Audit observation

The process for reconnecting ICPs during switch in was discussed.

The event detail report was reviewed to identify reconnections for switch ins where the switch was withdrawn, and the ICP was no longer supplied by the trader. If the ICP is not currently supplied by Paua, it is less likely that the switch was successfully completed at a later date.

Audit commentary

If an ICP was reconnected as part of the switching process and the switch was later withdrawn, Paua would restore the disconnection and reimburse the losing trader for any direct costs incurred if requested.

Review of the event detail report identified five ICPs reconnected as part of the switching process; all the switches were completed and not withdrawn.

Audit outcome

Compliant

2.15. Electrical disconnection of ICPs (Clause 10.33B)

Code reference

Clause 10.33B

Code related audit information

Unless the trader is recorded in the registry or is meeting its obligation under 10.33A(5) it must not disconnect or electrically disconnect the ICP or authorise the metering equipment provider to disconnect or electrically disconnect the ICP.

Audit observation

The disconnection process was examined.

Traders are only able to update the ICP status for event dates where they are responsible for the ICP on the registry. The event detail reports were reviewed to identify all ICPs which were disconnected during the audit period where an NT was received from another trader during the audit period. I checked a sample of these ICPs where the disconnection event date was after the NT receipt date and/or NT event date to determine compliance.

Audit commentary

Paua's policy is not to disconnect any ICP in the process of switching out.

Eight ICPs were disconnected during the audit period, and five of those had NT files issued by other traders. In all cases the NT event date and NT receipt date were after Paua had completed the disconnection.

Audit outcome

Compliant

2.16. Removal or breakage of seals (Clause 48(1C), 48 (1D), 48 (1E), 48 (1F) of Schedule 10.7)

Code reference

Clause 48(1C), 48 (1D), 48 (1E), 48 (1F) of Schedule 10.7

Code related audit information

<u>A trader can remove or break a seal without authorisation from the MEP to:</u>

- reset a load control switch, bridge or unbridge a load control switch if the load control switch does not control a tome block meter channel,
- electrically connect load or generation, of the load or generation has been disconnected at the meter,
- electrically disconnect load or generation, if the trader has exhausted all other appropriate methods of electrical disconnection,
- bridge the meter.

A trader that removes or breaks a seal in this way must:

- ensure personal are qualified to remove the seal and perform the permitted work and they replace the seal in accordance with the Code,
- replace the seal with its own seal,
- have a process for tracing the new seal to the personnel,
- update the registry (if the profile code has changed)
- notify the metering equipment provider.

Audit observation

Policies and processes for removal and breakage of seals were reviewed. I checked ICPs where work had been conducted which could have resulted in seals being removed or broken, to determine compliance.

Audit commentary

All activities which could result in seals being removed or broken are completed by the MEP or their subcontractors. The MEPs are required to ensure that only qualified personnel perform work and manage and trace seals.

Paua receives work completion paperwork from the MEPs and uses this information to confirm the correct ICP attributes including status and update the registry. The MEPs do not usually provide details of seals in their job completion paperwork.

I checked ICPs where work had been conducted which could have resulted in seals being removed or broken:

- all disconnections and reconnections were conducted remotely, and no seals were broken in the process, and
- no bridged meters were identified.

Audit outcome

Compliant

2.17. Meter bridging (Clause 10.33C and 2A of Schedule 15.2

Code reference

Clause 10.33C and 2A of Schedule 15.2

Code related audit information

A trader, or a distributor or MEP which has been authorised by the trader, may only electrically connect an ICP in a way that bypasses a meter that is in place ("bridging") if, despite best endeavours:

- the MEP is unable to remotely electrically connect the ICP,
- the MEP cannot repair a fault with the meter due to safety concerns,
- the consumer will likely be without electricity for a period which would cause significant disadvantage to the consumer.

If the trader bridges a meter, the trader must:

- determine the quantity of electricity conveyed through the ICP for the period of time the meter was bridged,
- submit that estimated quantity of electricity to the reconciliation manager,
- within one business day of being advised that the meter is bridged, notify the MEP that they are required to reinstate the meter so that all electricity flows through a certified metering installation.

The trader must determine meter readings as follows:

- by substituting data from an installed check meter or data storage device
- if a check meter or data storage device is not installed, by using half hour data from another
 period where the trader considers the pattern of consumption is materially similar to the period
 during which the meter was bridged,
- if half hour data is not available, a non-half hour estimated reading that the trader considers is the best estimate during the bridging period must be used.

Audit observation

Processes for bridged meters were discussed, and events that could have resulted in meter bridging or caused by meter bridging were reviewed.

Audit commentary

Paua only supplies HHR meters, which are disconnected and reconnected remotely. Paua does not normally allow meters to be bridged.

No bridged meters were identified during the audit period. All disconnections and reconnections were conducted remotely, and all periods of zero consumption identified were genuine and did not occur due to faults or meter bridging.

Audit outcome

Compliant

2.18. Use of ICP identifiers on invoices (Clause 11.30)

Code reference

Clause 11.30

Code related audit information

Each trader must ensure the relevant ICP identifier is printed on every invoice or document relating to the sale of electricity.

Audit observation

The process to ensure that the ICP identifier is printed on every invoice or document relating to the sale of electricity was discussed, and the invoice template was reviewed.

Audit commentary

Paua's billing run information is used to populate an invoice template, and the invoice details are stored against each ICP and customer so that invoices can be reproduced if needed, and the information remains available.

I viewed the invoice template and confirmed that the ICP field is displayed.

Audit outcome

Compliant

2.19. Provision of information on dispute resolution scheme (Clause 11.30A)

Code reference

Clause 11.30A

Code related audit information

A retailer must provide clear and prominent information about Utilities Disputes:

- on their website
- when responding to gueries from consumers
- in directed outbound communications to consumers about electricity services and bills.

If there are a series of related communications between the retailer and consumer, the retailer needs to provide this information in at least one communication in that series.

Audit observation

The process to ensure that information on Utilities Disputes is provided to customers was discussed. Invoices, emails, and Paua's website were reviewed to determine whether clear and prominent information on Utilities Disputes is provided.

Audit commentary

Clear and prominent information on Utilities Disputes is provided:

- on Paua's website's contact page, there is information about Utilities Disputes including a link to their telephone number and website,
- in Paua's current terms and conditions,
- on each Paua invoice, which customers receive weekly, and
- as part of the email footer for outbound emails.

Outbound communications to customers are normally via email.

Audit outcome

Compliant

2.20. Provision of information on electricity plan comparison site (Clause 11.30B)

Code reference

Clause 11.30B

Code related audit information

A retailer that trades at an ICP recorded on the registry must provide clear and prominent information about Powerswitch:

- on their website
- in outbound communications to residential consumers about price and service changes

- to residential consumers on an annual basis
- in directed outbound communications about the consumer's bill.

If there are a series of related communications between the retailer and consumer, the retailer needs to provide this information in at least one communication in that series.

Audit observation

The process to ensure that information on Powerswitch is provided to customers was discussed. Invoices and Paua's website were reviewed to determine whether clear and prominent information on Powerswitch is provided.

Audit commentary

Clear and prominent information on Powerswitch is provided:

- on Paua's website's homepage there is a button which links to Powerswitch,
- in Paua's current terms and conditions, and
- on each Paua invoice, which customers receive weekly.

Paua meets the annual requirement to provide information on Powerswitch through including this information on its weekly invoices.

Any communications to customers regarding price and service changes are via email. and this communication included information on Powerswitch.

Audit outcome

Compliant

3. MAINTAINING REGISTRY INFORMATION

3.1. Obtaining ICP identifiers (Clause 11.3)

Code reference

Clause 11.3

Code related audit information

The following participants must, before assuming responsibility for certain points of connection on a local network or embedded network, obtain an ICP identifier for the point of connection:

- a) a trader who has agreed to purchase electricity from an embedded generator or sell electricity to a consumer,
- b) an embedded generator who sells electricity directly to the clearing manager
- c) a direct purchaser connected to a local network or an embedded network,
- d) an embedded network owner in relation to a point of connection on an embedded network that is settled by differencing,
- e) a network owner in relation to a shared unmetered load point of connection to the network owner's network
- f) a network owner in relation to a point of connection between the network owner's network and an embedded network.

ICP identifiers must be obtained for points of connection at which any of the following occur:

- a consumer purchases electricity from a trader 11.3(3)(a)
- a trader purchases electricity from an embedded generator 11.3(3)(b)
- a direct purchaser purchases electricity from the clearing manager 11.3(3)(c)
- an embedded generator sells electricity directly to the clearing manager 11.3(3)(d)
- a network is settled by differencing 11.3(3)(e)
- there is a distributor status ICP on the parent network point of connection of an embedded network or at the point of connection of shared unmetered load 11.3(3)(f).

Audit observation

The new connection process was discussed. The registry list, event detail report and audit compliance report for the audit period were examined to determine whether any new connections were completed during the audit period.

Audit commentary

Paua does not intend to handle new connections, and ICPs must be connected before they will be accepted by Paua. Review of the registry reports confirmed that Paua has not completed any new connections during the audit period.

Audit outcome

Compliant

3.2. Providing registry information (Clause 11.7(2))

Code reference

Clause 11.7(2)

Code related audit information

Each trader must provide information to the registry manager about each ICP at which it trades electricity in accordance with Schedule 11.1.

Audit observation

The new connection, disconnection, reconnection, MEP nomination, and switching processes were examined. This clause links directly to **sections 3.3** below, where findings on the timeliness of updates are recorded.

The audit compliance report for the audit period was analysed in relation to updating of the registry.

Audit commentary

Paua's processes are designed to ensure that trader information is populated as required by this clause.

Audit outcome

Compliant

3.3. Changes to registry information (Clause 10 Schedule 11.1)

Code reference

Clause 10 Schedule 11.1

Code related audit information

If information provided by a trader to the registry manager about an ICP changes, the trader must provide written notice to the registry manager of the change no later than five business days after the change.

Audit observation

The processes to manage status changes are discussed in detail in **sections 3.8** and **3.9** below. The processes to manage MEP nominations and trader updates were discussed. All late updates were reviewed to determine why they were delayed.

Audit commentary

Status updates

Status is maintained in the registry and not recorded in the HHR data management system. All changes to status are processed manually using the registry user interface once confirmation of the correct status and event date is received. When a disconnection or reconnection is requested, a reminder is set in the HHR data management system action hub to process the disconnection or reconnection.

The audit compliance report was examined to confirm whether the registry is notified within five business days when information referred to in clause 9 of schedule 11.1 changes.

Status	Review period end	ICPs notified greater than 5 days	Percentage on time	Average Business Days between Status Event and Status Input Dates
Active	2017	-	100.0%	8.1
	Jan 2018	3	72.7%	5.4
	Oct 2018	3	75.0%	4
	Apr 2020	6	55.6%	38.7
	Mar 2021	1	66.67%	3.67
	Sept 2022	2	60%	32
Inactive	Jan 2018	2	90%	Not able to calculate due to
	Oct 2018	6	57.1%	table format change from earlier audit.
	Apr 2020	4	75.0%%	4.31
	Mar 2021	1	85.71	86.43
	Sept 2022	1	85.71	2.43

The late status updates were checked:

- ICP 0000144850TR542was updated to "active" status 71 business days late after the ICP was switched and reconnected,
- ICP 0000189886TR71F was updated to "active" status 85 business days late after being reconnected, and
- ICP 0000010355TRA9B was updated to "inactive" status 12 days late.

All three late updates were due to human error. Two were during the period the action hub was offline due to the implementation of an upgrade to the front end of the HHR data management system therefore the user was not alerted to the need to undertake the status update. One late update was to correct a previous incorrect date for the status. These late status updates are recorded as non-compliance below.

Trader updates and MEP nominations

Trader updates including MEP nominations are processed manually using the registry user interface once the correct values and event date have been confirmed.

No MEP nominations, or trader updates other than NT updates occurred during the period. This was confirmed by checking the audit compliance reports and the event detail report for the audit period.

The ACO20 report did not record any late trader ANZSIC code updates for switched in or newly connected ICPs.

Audit outcome

Non-compliance	Description		
Audit Ref: 3.3	Three late status updates.		
With: Clause 10 Schedule	Potential impact: Low		
11.1	Actual impact: Low		
	Audit history: Multiple times		
From: 01-Mar-21	Controls: Strong		
To: 30-Sep-22	Breach risk rating: 1		
Audit risk rating	Rationale	for audit risk rati	ng
Low	The controls are adequate to ensure that the registry is updated on time most of the time. One late status update was caused by a backdated switch, and the other was a correction. The risk is low as a small number of updates were affected.		
Actions tak	en to resolve the issue	Completion date	Remedial action status
We identified the ICP and I	resolved them as soon as they were	Cleared	Cleared
Preventative actions tal	ken to ensure no further issues will occur	Completion date	
We recently implemented identification of consumption from ICP which the registry reports as disconnected. Alerts are prominently displayed on our Action and ICP Management Hubs for the operator to identify and fix. Our disconnection & reconnection process now has reminders built in to add to our to do list where we are unable to change the status because the ICP is in the switch process.		Implemented	

3.4. Trader responsibility for an ICP (Clause 11.18)

Code reference

Clause 11.18

Code related audit information

A trader becomes responsible for an ICP when the trader is recorded in the registry as being responsible for the ICP.

A trader ceases to be responsible for an ICP if:

- another trader is recorded in the registry as accepting responsibility for the ICP (clause 11.18(2)(a)); or
- the ICP is decommissioned in accordance with clause 20 of Schedule 11.1 (clause 11.18(2)(b)).
- if an ICP is to be decommissioned, the trader who is responsible for the ICP must (clause 11.18(3)):
 - o arrange for a final interrogation to take place prior to or upon meter removal (clause 11.18(3)(a)); and

o advise the MEP responsible for the metering installation of the decommissioning (clause 11.18(3)(b)).

A trader who is responsible for an ICP (excluding UML) must ensure that an MEP is recorded in the registry for that ICP (clause 11.18(4)).

A trader must not trade at an ICP (excluding UML) unless an MEP is recorded in the registry for that ICP (clause 11.18(5)).

Audit observation

The new connection, MEP nomination and decommissioning processes were reviewed, and the registry list and audit compliance reports were examined to confirm process compliance.

Audit commentary

Retailers Responsibility to Nominate and Record MEP in the Registry

Review of the registry list and audit compliance reports confirmed all active ICPs have a valid MEP and at least one meter channel recorded in the registry, and no MEP nominations were made.

Paua ensures that ICPs have AMS, Metrix or Intellihub as an MEP before they switch in, and MEP changes are not expected. If MEP nominations are required in the future, they will be manually processed on the registry.

ICP Decommissioning

Review of the event detail report confirmed that no ICPs were decommissioned during the audit period. Paua is aware of their responsibility to notify the MEP where an ICP is decommissioned, and to obtain a final reading. Paua expects that final interrogations will occur for decommissioned ICPs because data will be provided daily up to the point the meter is de-energised as part of the permanent disconnection prior to decommissioning.

Audit outcome

Compliant

3.5. Provision of information to the registry manager (Clause 9 Schedule 11.1)

Code reference

Clause 9 Schedule 11.1

Code related audit information

Each trader must provide the following information to the registry manager for each ICP for which it is recorded in the registry as having responsibility:

- a) the participant identifier of the trader, as approved by the Authority (clause 9(1)(a))
- b) the profile code for each profile at that ICP, as approved by the Authority (clause 9(1)(b))
- c) the metering equipment provider for each category 1 metering or higher (clause 9(1)(c))
- d) the type of submission information the trader will provide to the RM for the ICP (clause 9(1)(ea)
- e) if a settlement type of UNM is assigned to that ICP, either:
 - the code ENG if the load is profiled through an engineering profile in accordance with profile class 2.1 (clause 9(1)(f)(i)); or
 - in all other cases, the daily average kWh of unmetered load at the ICP (clause 9(1)(f)(ii)).
 - the type and capacity of any unmetered load at each ICP (clause 9(1)(g))
 - the status of the ICP, as defined in clauses 12 to 20 (clause 9(1)(j))

- except if the ICP exists for the purposes of reconciling an embedded network or the ICP has distributor status, the trader must provide the relevant business classification code applicable to the customer (clause 9(1)(k)).

The trader must provide information specified in (a) to (j) above within 5 business days of trading (clause 9(2)).

The trader must provide information specified in 9(1)(k) no later than 20 business days of trading (clause 9(3)).

Audit observation

New connections were discussed. The registry list, event detail report and audit compliance report for the audit period were examined to determine whether any new connections were completed during the audit period.

Audit commentary

Paua does not intend to handle new connections, and ICPs must be connected before they will be accepted by Paua. Review of the registry reports confirmed that Paua has not completed any new connections during the audit period.

Any changes to status or trader information are processed manually using the registry user interface.

No late updates or discrepancies relating to new connections were identified on the registry list, event detail report or audit compliance report, and the ACO20 report did not record any late ANZSIC code updates for switched in or newly connected ICPs.

Audit outcome

Compliant

3.6. ANZSIC codes (Clause 9 (1(k) of Schedule 11.1)

Code reference

Clause 9 (1(k) of Schedule 11.1

Code related audit information

Traders are responsible to populate the relevant ANZSIC code for all ICPs for which they are responsible.

Audit observation

The process to capture and manage ANZISC codes was examined. The registry list and AC020 reports were reviewed. ANZSIC codes were checked for a sample of ICPs to determine compliance.

Audit commentary

ANZSIC codes are set based on information provided on the customer application, and appropriate processes are in place to ensure that ANZSIC codes are confirmed with the customer during the onboarding process and are recorded correctly.

No active ICPs have blank or T99 (unknown) series ANZSIC codes, and no ICPs have metering category two or higher.

ANZSIC codes for a diverse sample of 20 ICPs were checked, including two ICPs with a non-residential code. For the sample of 20 ICPs, only one ICP (0000157936TR838) was identified where the ANZSIC code was incorrect. This has now been updated by Paua.

Audit outcome

Non-compliance		Description				
Audit Ref: 3.6	ICP 0000157936TR838 was populated with an incorrect ANZSIC code.					
With: Clause 9 (1(k) of	Potential impact: Low	Potential impact: Low				
Schedule 11.1	Actual impact: Low	Actual impact: Low				
	Audit history: None					
From: 01-Mar-21	Controls: Strong					
To: 30-Sep-22	Breach risk rating: 1					
Audit risk rating	Rationale	Rationale for audit risk rating				
Low	=	The controls are strong to ensure that the ANZSIC code is reviewed as part of the sign-up process. The risk is low as only one ICP was affected.				
Actions ta	ken to resolve the issue	Completion	Remedial action status			
		date				
The ANZSIC code has been changed		October 2022	Cleared			
We have added a step to our onboarding process to check the ANZSIC code.		Implemented				

3.7. Changes to unmetered load (Clause 9(1)(f) of Schedule 11.1)

Code reference

Clause 9(1)(f) of Schedule 11.1

Code related audit information

If a settlement type of UNM is assigned to that ICP, the trader must populate:

- the code ENG if the load is profiled through an engineering profile in accordance with profile class 2.1 (clause 9(1)(f)(i)); or
- the daily average kWh of unmetered load at the ICP in all other cases (clause 9(1)(f)(ii)).

Audit observation

The processes to manage unmetered load were examined. The registry list audit and audit compliance reports were examined to identify ICPs where unmetered load was recorded by the distributor and/or Paua.

Audit commentary

Paua only accepts applications from customers who do not have unmetered load connected.

Review of the registry list and audit compliance reports confirmed that no unmetered load is recorded by the distributor or trader for any Paua ICP. All active ICPs are metered with an MEP recorded and at least one meter channel.

Additions or changes to unmetered load details will be identified as part of the registry validation process. A daily ICP list with history (including all data from January 2015 onwards) is downloaded from the registry and imported into the HHR data management system. Changes to attributes are reported to the operator for investigation in the action hub, including changes to distributor unmetered load

details. If unmetered load is found, Paua would relinquish responsibility for shared unmetered load if allowed under clause 11.14 or would arrange for the ICP to switch out.

Audit outcome

Compliant

3.8. Management of "active" status (Clause 17 Schedule 11.1)

Code reference

Clause 17 Schedule 11.1

Code related audit information

The ICP status of "active" is be managed by the relevant trader and indicates that:

- the associated electrical installations are electrically connected (clause 17(1)(a))
- the trader must provide information related to the ICP in accordance with Part 15, to the reconciliation manager for the purpose of compiling reconciliation information (clause 17(1)(b)).

Before an ICP is given the "active" status, the trader must ensure that:

- the ICP has only one customer, embedded generator, or direct purchaser (clause 17(2)(a))
- the electricity consumed is quantified by a metering installation or a method of calculation approved by the Authority (clause 17(2)(b)).

Audit observation

As discussed in **sections 2.9** and **3.5** Paua does not complete new connections. Review of the event detail report and ACO20 report confirmed this.

The reconnection process was examined using the ACO20 and event detail reports. The timeliness of data for reconnections is assessed in **section 3.3**, and a sample of seven updates were checked for accuracy.

Audit commentary

Status is maintained in the registry and not recorded in the HHR data management system. All changes to status are processed manually using the registry user interface once confirmation of the correct status and event date is received. When a reconnection is requested, a reminder is set in the HHR data management system action hub to process the reconnection.

Seven ICPs had status changes to "active" on the event detail report. All were reconnections on switch in and had fully certified metering installations in place. I reviewed the status codes and reconnection dates and identified that for one ICP (0000010333TR4E4) the disconnection (reason code 11 - disconnected at meter box switch) was performed by the customer by turning off all load downstream of the meter and this does not meet the criteria of electrically disconnecting an ICP as electricity is still able to flow when the customer turned load back on. Paua were actively monitoring the AMI data on a daily basis to ensure no electricity consumption was being recorded however if the AMI meter experienced a communications issue, then the connection status would not be able to be effectively monitored. Non compliance is recorded relating to this ICP in relation to the incorrect status.

Two late registry updates to "active" status and one late registry updates to "inactive" status were identified and these are recorded as a non-compliance in **section 3.3.**

No new connections have been created, and the ACO20 did not record any discrepancies relating to new connections.

The HHR data management system will not allow more than one party per ICP, nor will it allow an ICP to be set up without both a meter and MEP.

Audit outcome

Non-compliant

Non-compliance	Description		
Audit Ref: 3.8	ICP 0000010333TR4E4 was populated with an incorrect inactive status.		
With: 17 Schedule 11.1	Potential impact: Low		
	Actual impact: Low		
	Audit history: None		
From: 01-Mar-21	Controls: Strong		
To: 30-Sep-22	Breach risk rating: 1		
Audit risk rating	Rationale for audit risk rating		
Low	The controls are strong as Paua only complete disconnections remotely by AMI meter.		
	The risk is low as only one ICP was in	volved.	
Actions tak	en to resolve the issue	Completion date	Remedial action status
We have changed our processes to only use the disconnected by AMI Meter code.		Cleared	Cleared
We have changed our processes to only use the disconnected by AMI Meter code.		Implemented	

3.9. Management of "inactive" status (Clause 19 Schedule 11.1)

Code reference

Clause 19 Schedule 11.1

Code related audit information

The ICP status of "inactive" must be managed by the relevant trader and indicates that:

- electricity cannot flow at that ICP (clause 19(a)); or
- submission information related to the ICP is not required by the reconciliation manager for the purpose of compiling reconciliation information (clause 19(b)).

Audit observation

The disconnection process was examined using the ACO20 and event detail reports. The timeliness of data for disconnections is assessed in **section 3.3**, and a sample of eight updates were checked for accuracy.

Paua does not complete new connections. Review of the registry list confirmed that no ICPs are at "new", "ready", or "inactive new connection in progress" status.

Audit commentary

Status is maintained in the registry and not recorded in the HHR data management system. All changes to status are processed manually using the registry user interface once confirmation of the correct status and event date is received. When a disconnection is requested, a reminder is set in the HHR data management systems action hub to process the disconnection.

The physical method of disconnections that are requested by Paua is by way of remote by AMI meter in all cases however Paua applies either vacant disconnection or disconnection by AMI meter reason codes in the registry. The application of either reason code by Paua for the disconnection of a vacant ICP appears arbitrary and I recommend that Paua standardises the use of a single inactive status reason code (7 – remote by AMI meter) which will assist potential gaining traders in terms of arranging the appropriate reconnection task where these ICPs switch away post disconnection.

Description	Recommendation	Audited party comment	Remedial action
Standardise use of inactive reason codes where disconnection is remote by AMI meter	For remote disconnections by AMI meter, that Paua standardises the use of a single inactive status reason code (7 – remote by AMI meter) which will assist potential gaining traders in terms of arranging the appropriate reconnection task where these ICPs switch away.	Already implemented	Cleared

Vacant and disconnected ICPs will continue to receive readings, if provided by the MEP, but ICPs will only be included in submission data if their status is "active" for the period with consumption.

Eight ICPs had status changes to "inactive" on the event detail report. I reviewed the reason codes and disconnection dates for the sample and found that they had been applied appropriately. One late registry update is recorded as a non-compliance in **section 3.3**.

Paua has an alert set up within the action hub to identify any ICP with a status of 001 (inactive) in the registry with HHR volumes so that the status can be corrected. However, during the period that the action hub was offline due to the implementation of an upgrade to the front end of the HHR data management system these exceptions were not being generated to alert the user to investigate and correct the registry status. One late registry update to "inactive" status was identified and this is recorded as a non-compliance in **section 3.3**

Four ICPs with inactive registry status were reviewed to confirm that no consumption was recorded during this inactive period:

- one ICP did not have any consumption recorded during the inactive period,
- one ICP (0000135165TRDE5 23.285 kWh) switched in with an inactive status then switched away 21 days later without an update to the registry status; this ICP was not set up within the HHR data management system so there was no opportunity for an exception to be generated and investigated (the registry status was corrected during the audit), and
- two ICPs (0000172686TRB68 11 kWh, 1001152620CKF66 1.6 kWh) had an incorrect inactive date applied within the registry resulting in some volume not being included in submission (the registry inactive status dates were corrected during the audit).

Non compliance is recorded for these four ICPs and the unreported inactive consumption is also recorded as non-compliance in **section 12.2** and **12.7**.

Audit outcome

Non-compliance	D	escription	
Audit Ref: 3.9 With: Clause 19	Three ICPs had consumption during inactive periods, indicating that their status was incorrect. Estimated under submission of 36 kWh has occurred.		
Schedule 11.1	Potential impact: Low		
	Actual impact: Low		
	Audit history: Once		
From: 01-Mar-21	Controls: Strong		
To: 30-Sep-22	Breach risk rating: 1		
Audit risk rating	Rationale	for audit risk rati	ng
Low	The controls are rated as strong as there are system checks in place to capture this exception, however the system was offline for a period of time for a system upgrade.		
	The impact is low, because the impact and 36 kWh.	t on settlement a	nd participants is four ICPs
Actions ta	ken to resolve the issue	Completion date	Remedial action status
The ICPs have been inclu	ded in future submissions.	Completed	Identified
Preventative actions ta	ken to ensure no further issues will occur	Completion date	
We have now implemented identification of consumption of ICP which the registry reports as disconnected. Alerts are prominently displayed on our Home and ICP Management Hubs for the operator to identify and fix. Our disconnection & reconnection process now has reminders built in to add to our to do list.		Implemented	

3.10. ICPs at new or ready status for 24 months (Clause 15 Schedule 11.1)

Code reference

Clause 15 Schedule 11.1

Code related audit information

If an ICP has had the status of "New" or "Ready" for 24 calendar months or more, the distributor must ask the trader whether it should continue to have that status and must decommission the ICP if the trader advises the ICP should not continue to have that status.

Audit observation

Whilst this is a distributor's code obligation, I investigated whether any queries had been received from distributors in relation to ICPs at the "new" or "ready" status for more than 24 months and what process is in place to manage and respond to such requests.

I analysed a registry list of ICPs with "new" or "ready" status and Paua as the proposed trader, and reviewed processes to monitor new connections.

Audit commentary

Review of the registry list confirmed that no ICPs have had "new" or "ready" status. Paua has not completed any new connections and does not intend to.

Paua has amended its monitoring process from an email-based escalation for querying the status of "new" or "ready" ICPs, to the new HHR data management system action hub alert for ICPs with the proposed trader "GIVE".

The registry list validation will identify any ICPs with "active" or "inactive" status which are not recorded in Paua's database. These will be displayed in the action hub as "unknown ICPs" for investigation.

Audit outcome

4. PERFORMING CUSTOMER AND EMBEDDED GENERATOR SWITCHING

4.1. Inform registry of switch request for ICPs - standard switch (Clause 2 Schedule 11.3)

Code reference

Clause 2 Schedule 11.3

Code related audit information

The standard switch process applies where a trader and a customer or embedded generator enters into an arrangement in which the trader commences trading electricity with the customer or embedded generator at a non-half hour or unmetered ICP at which another trader supplies electricity, or the trader assumes responsibility for such an ICP.

If the uninvited direct sale agreement applies to an arrangement described above, the gaining trader must identify the period within which the customer or embedded generator may cancel the arrangement in accordance with section 36M of the Fair Trading Act 1986. The arrangement is deemed to come into effect on the day after the expiry of that period.

A gaining trader must advise the registry manager of a switch no later than two business days after the arrangement comes into effect and include in its advice to the registry manager that the switch type is TR and one or more profile codes associated with that ICP.

Audit observation

The switch gain process was examined to determine when Paua deem all conditions to be met. A sample of five transfer switch NTs were checked to confirm that these were notified to the registry within two business days, and that the correct switch type was selected.

Audit commentary

Paua's processes are compliant with the requirements of Section 36M of the Fair Trading Act 1986. NT files will be sent as soon as all pre-conditions are met, and the withdrawal process is used if the customer changes their mind.

The information required to create the NT is manually entered into the HHR data management system on receipt of a customer application. NT files are generated by the HHR data management system and uploaded to the registry each evening.

Switch type is selected based on information provided by the customer on application. The customer is asked if they have recently moved into the property and their move in date as part of the application process. If they have not recently moved in, a transfer switch is requested. Paua only supplies ICPs with a metering installation category of 1.

Only five transfer switch NTs were generated during the audit period, and all had the correct switch type selected. All were sent within two business days of pre-conditions being cleared.

Audit outcome

4.2. Losing trader response to switch request and event dates - standard switch (Clauses 3 and 4 Schedule 11.3)

Code reference

Clauses 3 and 4 Schedule 11.3

Code related audit information

Within three business days after receiving notice of a switch from the registry manager, the losing trader must establish a proposed event date. The event date must be no more than 10 business days after the date of receipt of such notification, and in any 12-month period, at least 50% of the event dates must be no more than five business days after the date of notification. The losing trader must then:

- provide acknowledgement of the switch request by (clause 3(a) of Schedule 11.3):
- providing the proposed event date to the registry manager and a valid switch response code (clause 3(a)(i) and (ii) of Schedule 11.3); or
- providing a request for withdrawal of the switch in accordance with clause 17 (clause 3(c) of Schedule 11.3).

When establishing an event date for clause 4, the losing trader may disregard every event date established by the losing trader for an ICP for which when the losing trader received notice from the registry manager under clause 22(a) the losing trader had been responsible for less than 2 months.

Audit observation

The AN process was examined, and the event detail report was reviewed to:

- identify AN files issued by Paua during the audit period,
- assess compliance with the requirement to meet the setting of event dates requirement, and
- a diverse sample ANs were checked to determine whether the codes had been correctly applied.

The switch breach history report was examined for the audit period.

Audit commentary

AN timeliness

When an NT is received from the registry, the HHR data management system automatically creates an AN unless the proposed transfer date is more than nine business days after NT receipt. If the proposed transfer date is more than nine business days after NT receipt, a withdrawal notice will be issued with date failure as the reason code.

The timeliness of AN files is monitored:

- a notification is generated in the HHR data management system action hub if the AN process fails to run,
- the switch breach history report is imported into the HHR data management system daily, and updates file due dates, and
- the switch breach history report is also reviewed manually every two to three days, to check that all files have been issued as required.

The HHR data management system process was fully automated in March 2021 however this automated process was suspended for a time during the implementation of an upgrade to the front end of the HHR data management system. During this affected period there were no automated alerts being generated by the action hub informing the user that an AN was required and AN files were being created manually using the registry user interface.

The switch breach history report recorded ten AN breaches where the AN arrival date was more than three business days after the NT arrival date. The late files all occurred during the period the automated

AN process was offline due to the implementation of an upgrade to the front end of the HHR data management system and the action alert hub was also not providing exceptions to enable timely manual processing of the AN files directly into the registry. The automated process is now back online.

AN content

The HHR data management system generates AN event dates and response codes according to system rules:

- if the proposed event date is within Paua's acceptable range, the switch event date is set to match the gaining trader's proposed event date, unless it is blank or backdated, in which case it is set to the contract end date + one day or if there is no contract end date, tomorrow, and
- response codes are selected according to a hierarchy, which should ensure that correct response codes apply.

The event detail report was reviewed for all 160 transfer ANs to assess compliance with the setting of event dates requirements:

- three had a proposed event date greater than five business days of the NT receipt date, and
- all had proposed event dates within ten business days of the NT receipt date.

A diverse sample of 13 AN files were checked, and for 16 records the correct response codes were applied. Four ANs applied an incorrect response code of OC (Occupied) instead of AD (Advanced Meter) for a transfer switch.

Audit outcome

Description
Ten AN timing breaches.
Four Transfer ANs applied the incorrect response code.
Potential impact: Low
Actual impact: Low
Audit history: Multiple times
Controls: Strong
Breach risk rating: 1
Rationale for audit risk rating
Controls are assessed as strong because the process is automated, and all the late files occurred during the period the switching automation within the HHR data management system was offline to enable a system upgrade to be implemented. The impact is low because most of the late files were only a day or two late and the longest delay was no more than 10 business days late.

Actions taken to resolve the issue	Completion date	Remedial action status
The automated switching system is now up, and we do not expect to operate without it going forward.	Implemented	Cleared
Preventative actions taken to ensure no further issues will occur	Completion date	
With the upgrade to our system completed we should now be compliant. Future upgrades will not have to take this part of the system down.	Implemented	

4.3. Losing trader must provide final information - standard switch (Clause 5 Schedule 11.3)

Code reference

Clause 5 Schedule 11.3

Code related audit information

If the losing trader provides information to the registry manager in accordance with clause 3(a) of Schedule 11.3 with the required information, no later than five business days after the event date, the losing trader must complete the switch by:

- providing event date to the registry manager (clause 5(a)); and
- provide to the gaining trader a switch event meter reading as at the event date, for each meter
 or data storage device that is recorded in the registry with accumulator of C and a settlement
 indicator of Y (clause 5(b)); and
- if a switch event meter reading is not a validated reading, provide the date of the last meter reading (clause 5(c)).

Audit observation

The CS process was examined, and the event detail report was reviewed to identify CS files issued by Paua during the audit period. The accuracy of the content of CS files was confirmed by checking a sample of records. The content checked included:

- · correct identification of meter readings and correct date of last meter reading,
- accuracy of meter readings, and
- accuracy of average daily consumption.

I checked the event detail report for CS files with average daily kWh that was negative, zero, or over 50 kWh.

The process to manage the sending of the CS file within five business days of the event date was examined, and the switch breach history report for the audit period was reviewed to identify late CS files.

Audit commentary

CS content

All ICPs have HHR AMI meters and are expected to switch in and out on validated readings. The HHR data management system automatically creates a CS file as soon as a midnight reading is received, or estimated, for the day before the switch event date.

- The read quality indicator is used to determine whether reads should be classified as estimate or
 actual, and determine the last actual read date during the period of supply. The HHR data
 management system creates an alert where there is no HHR data available to create the CS file.
- The registry functional specification requires average daily kWh to be based on the average daily consumption for the last read to read period. Paua receives daily readings, and the average daily kWh is based on the average daily consumption between the last two readings received prior to switch out, truncated to zero decimal places. Paua's average daily kWh process was considering estimates where actual readings were not available. During the audit, Paua updated the HHR data management system logic during to consider only actual readings and create an alert where less than two actual readings have been received, so that the average daily kWh could be updated manually. Review of the event detail report confirmed that all CS files during the audit period switched out on actual readings, and all CS files checked had compliant average daily kWh.
- The key held indicator is determined from information obtained from the customer on application and stored in the HHR data management system. Paua have not held any customer keys to date, because all meters are read remotely.

Review of the event detail report did not identify any transfer switches with average daily kWh which was negative, zero or over 200 kWh.

I checked the content of a sample of 11 transfer CS files and found the data was recorded correctly for 10 files. For ICP 0000008223TR2AC the switch event meter reading was incorrect compared to the value recorded in the HHR Data management system. The gaining trader did not dispute this estimated switch event read as the difference was less than 200 kWh and the gaining trader was not settling the ICP as HHR.

CS timeliness

The timeliness of CS files is monitored:

- the switch breach history report is imported into the HHR data management system daily, and updates file due dates, and
- the switch breach history report is also reviewed manually every two to three days, to check that all files have been issued as required.

The switch breach history report recorded 16 CS breaches where the CS arrival date was more than five business days after the CS actual transfer date, and no NW was provided.

The late files all occurred during the period the automated CS process was offline due to the implementation of an upgrade to the front end of the HHR data management system and the action alert hub was also not providing notifications to enable timely manual processing of the CS files directly into the registry. The automated process is now back online.

Audit outcome

Non-compliance	C	escription		
Audit Ref: 4.3	16 CS breaches due to the late delivery of a CS file.			
With: Clause 5 Schedule	One transfer CS file contained an incorrect switch event read.			
11.3	Potential impact: Low			
	Actual impact: Low			
	Audit history: Multiple times			
From: 01-Mar-21	Controls: Strong			
To: 30-Sep-22	Breach risk rating: 1			
Audit risk rating	Rationale	for audit risk rati	ng	
Low	Controls are assessed as strong because the process is automated, and all the late files occurred during the period the switching automation within the HHR data management system was offline to enable a system upgrade to be implemented. The impact is low because most of the late files were only a day or two late and the longest delay was no more than 10 business days late. The incorrect switch event reading was less than 200 kWh different, and the gaining trader was not settling the ICP as HHR.			
Actions tak	en to resolve the issue	Completion date	Remedial action status	
The automated switching s expect to operate without	ystem is now up, and we do not it going forward.	Implemented	Cleared	
Preventative actions taken to ensure no further issues will occur		Completion date		
With the upgrade to our system completed we should now be compliant. Future upgrades will not have to take this part of the system down.		Implemented		

4.4. Retailers must use same reading - standard switch (Clause 6(1) and 6A Schedule 11.3)

Code reference

Clause 6(1) and 6A Schedule 11.3

Code related audit information

The losing trader and the gaining trader must both use the same switch event meter reading as determined by the following procedure:

- if the switch event meter reading provided by the losing trader differs by less than 200 kWh from a value established by the gaining trader, the gaining trader must use the losing trader's validated meter reading or permanent estimate (clause 6(a)); or
- the gaining trader may dispute the switch meter reading if the validated meter reading or permanent estimate provided by the losing trader differs by 200 kWh or more. (clause 6(b)).

If the gaining trader disputes a switch meter reading because the switch event meter reading provided by the losing trader differs by 200 kWh or more, the gaining trader must, within 4 calendar months of the registry manager giving the gaining trader written notice of having received information about the

switch completion, provide to the losing trader a changed switch event meter reading supported by 2 validated meter readings.

- the losing trader can choose not to accept the reading, however, must advise the gaining trader no later than five business days after receiving the switch event meter reading from the gaining trader (clause 6A(a)); or
- if the losing trader notifies its acceptance or does not provide any response, the losing trader must use the switch event meter reading supplied by the gaining trader (clause 6A(b)).

Audit observation

The process for the management of read change requests was examined, and the event detail report was analysed to identify all read change requests and acknowledgements during the audit period.

I also checked for CS files with estimated readings provided by other traders where no RR was issued, to determine whether the correct readings were recorded in the HHR data management system.

The switch breach history report for the audit period was reviewed.

Audit commentary

All ICPs switched in will have HHR AMI meters and are expected to switch in and out on validated readings. The HHR data management system compares the losing trader's closing read with the actual midnight read as soon as it is received by calculating the difference between the midnight reading on Paua's first day of supply and the sum of the intervals for the first day of supply. Where the CS read differs from the calculated opening reading the HHR data management system will automatically send an RR file, because the CS read appears to be incorrect. These read change requests normally meet the requirements of 6(2) and (3) Schedule 11.3 and are required to be accepted by the losing retailer. The HHR data management system creates an alert where there is no HHR data available to determine whether an RR is required.

Any ACs accepting Paua's proposed change are automatically processed by the HHR data management system, and ACs rejecting the proposed change are directed to an operator who will either reissue the RR or manually change the opening read.

RRs issued by other traders are directed to an operator, who will review the request and accept or reject it. The HHR data management system will generate the AC file which contains the operator response the evening after it is added.

The switch breach history report is also reviewed manually every two to three days, to check that all files have been issued as required.

Application of CS readings

Review of the event detail report did not identify any transfer CS files issued to Paua where an estimated reading had been provided and no RR file had been issued.

RR

No RR files were issued by Paua for transfer switches, and the switch breach history report did not record any late RR files.

AC

No AC files were issued by Paua for transfer switches, and the switch breach history report did not record any late AC files.

Audit outcome

4.5. Non-half hour switch event meter reading - standard switch (Clause 6(2) and (3) Schedule 11.3)

Code reference

Clause 6(2) and (3) Schedule 11.3

Code related audit information

If the losing trader trades electricity from a non-half hour meter, with a switch event meter reading that is not from an AMI certified meter flagged Y in the registry: and

- the gaining trader will trade electricity from a meter with a half hour submission type in the registry (clause 6(2)(b);
- the gaining trader within five business days after receiving final information from the registry manager, may provide the losing trader with a switch event meter reading from that meter. The losing trader must use that switch event meter reading.

Audit observation

The process for the management of read requests was examined. The event detail report was analysed to identify read change requests issued and received under Clause 6(2) and (3) Schedule 11.3 and determine compliance.

Audit commentary

Paua is a HHR only trader and will not receive any read change requests where clause 6(2) and (3) of schedule 11.3 applies.

Paua did not issue any read change requests where clause 6(2) and (3) of schedule 11.3 applied, because no RR files were issued for transfer switches.

Audit outcome

Compliant

4.6. Disputes - standard switch (Clause 7 Schedule 11.3)

Code reference

Clause 7 Schedule 11.3

Code related audit information

A losing trader or gaining trader may give written notice to the other that it disputes a switch event meter reading provided under clauses 1 to 6. Such a dispute must be resolved in accordance with clause 15.29 (with all necessary amendments).

Audit observation

I confirmed with Paua whether any disputes have needed to be resolved in accordance with this clause.

Audit commentary

Paua confirmed that no disputes have needed to be resolved in accordance with this clause.

Audit outcome

Compliant

4.7. Gaining trader informs registry of switch request - switch move (Clause 9 Schedule 11.3)

Code reference

Clause 9 Schedule 11.3

Code related audit information

The switch move process applies where a gaining trader has an arrangement with a customer or embedded generator to trade electricity at an ICP using non-half-hour metering or an unmetered ICP, or to assume responsibility for such an ICP, and no other trader has an agreement to trade electricity at that ICP, this is referred to as a switch move and the following provisions apply:

If the "uninvited direct sale agreement" applies, the gaining trader must identify the period within which the customer or embedded generator may cancel the arrangement in accordance with section 36M of the Fair Trading Act 1986. The arrangement is deemed to come into effect on the day after the expiry of that period.

In the event of a switch move, the gaining trader must advise the registry manager of a switch and the proposed event date no later than two business days after the arrangement comes into effect.

In its advice to the registry manager the gaining trader must include:

- a proposed event date (clause 9(2)(a)); and
- that the switch type is "MI" (clause 9(2)(b); and
- one or more profile codes of a profile at the ICP (clause 9(2)(c)).

Audit observation

The switch gain process was examined to determine when Paua deem all conditions to be met. A typical sample of NTs were checked to confirm that these were notified to the registry within two business days, and that the correct switch type was selected.

Audit commentary

Paua's processes are compliant with the requirements of Section 36M of the Fair Trading Act 1986. NT files will be sent as soon as all pre-conditions are met, and the withdrawal process is used if the customer changes their mind.

The information required to create the NT is manually entered into the HHR data management system on receipt of a customer application. NT files are generated by the HHR data management system and uploaded to the registry each evening.

Switch type is selected based on information provided by the customer on application. The customer is asked if they have recently moved into the property and their move in date as part of the application process. Paua only supplies ICPs with a metering installation category of 1.

The five NT files checked were sent within two business days of pre-conditions being cleared, and the correct switch type was selected.

Audit outcome

Compliant

4.8. Losing trader provides information - switch move (Clause 10(1) Schedule 11.3)

Code reference

Clause 10(1) Schedule 11.3

Code related audit information

10(1) Within five business days after receiving notice of a switch move request from the registry manager—

- 10(1)(a) If the losing trader accepts the event date proposed by the gaining trader, the losing trader must complete the switch by providing to the registry manager:
 - o confirmation of the switch event date; and
 - o a valid switch response code; and
 - o final information as required under clause 11; or
- 10(1)(b) If the losing trader does not accept the event date proposed by the gaining trader, the losing trader must acknowledge the switch request to the registry manager and determine a different event date that
 - o is not earlier than the gaining trader's proposed event date, and
 - o is no later than 10 business days after the date the losing trader receives notice: or
- 10(1)(c) request that the switch be withdrawn in accordance with clause 17.

Audit observation

The AN and CS processes were examined, and the event detail report was reviewed to:

- identify AN files issued by Paua during the audit period,
- assess compliance with the requirement to meet the setting of event dates requirement, and
- a diverse sample ANs were checked to determine whether the codes had been correctly applied.

The switch breach history report was examined for the audit period.

Audit commentary

AN timeliness

When an NT is received from the registry, the HHR data management system automatically creates an AN unless the proposed transfer date is more than nine business days after NT receipt. If the proposed transfer date is more than nine business days after NT receipt, a withdrawal notice will be issued with date failure as the reason code.

The timeliness of AN files is monitored:

- a notification is generated in the HHR data management system action hub if the AN process fails to run,
- the switch breach history report is imported into the HHR data management system daily, and updates file due dates, and
- the switch breach history report is also reviewed manually every two to three days, to check that all files have been issued as required.

The HHR data management system process was fully automated in March 2021 however this automated process was suspended for a time during the implementation of an upgrade to the front end of the HHR data management system. During this affected period there were no automated alerts being generated by the action hub informing the user that an AN was required and AN files were being created manually using the registry user interface.

The switch breach history report recorded three AN breaches where the AN arrival date is more than three business days after the NT arrival date.

The late files all occurred during the period the automated AN process was offline due to the implementation of an upgrade to the front end of the HHR data management system and the action alert hub was also not providing exceptions to enable timely manual processing of the AN files directly into the registry. The automated process is now back online.

CS timeliness

The HHR data management system will automatically create a CS file as soon as a midnight reading is received, or estimated, for the day before the switch event date.

The timeliness of CS files is monitored:

- the switch breach history report is imported into the HHR data management system daily, and updates file due dates, and
- the switch breach history report is also reviewed manually every two to three days, to check that all files have been issued as required.

The switch breach history report recorded ten T2 breaches for switch moves because the CS arrival date was more than five business days after receipt of the NT, where no NW or AN notice was provided, or a notice was provided, and the NT proposed transfer date matched the AN expected transfer date.

The late files all occurred during the period the automated CS process was offline due to the implementation of an upgrade to the front end of the HHR data management system and the action alert hub was also not providing alerts to enable timely manual processing of the CS files directly into the registry. The automated process is now back online.

AN content

The HHR data management system generates AN event dates and response codes according to system rules:

- if the proposed event date is within Paua's acceptable range, the switch event date is set to match the gaining trader's proposed event date, unless it is blank or backdated, in which case it is set to the contract end date + one day or if there is no contract end date, tomorrow, and
- response codes are selected according to a hierarchy, which should ensure that correct response codes apply.

The event detail report was reviewed for all 80 switch move ANs to assess compliance with the setting of event dates requirements:

- all ANs had proposed event dates within ten business days of the NT receipt date, and
- no ANs has a proposed event date before the gaining trader's requested date, in all cases the AN date matched the requested date.

A diverse sample of seven AN files were checked, and in all cases correct response codes were applied.

Audit outcome

Non-compliance	C	escription	
Audit Ref: 4.8	Three AN breaches.		
With: Clause 10(1)	Ten T2 breaches.		
Schedule 11.3	Potential impact: Low		
	Actual impact: Low		
	Audit history: Multiple times		
From: 01-Mar-21	Controls: Strong		
To: 30-Sep-22	Breach risk rating: 1		
Audit risk rating	Rationale for audit risk rating		
Low	Controls are assessed as strong because the process is automated, and all the late files occurred during the period the switching automation within the HHR data management system was offline to enable a system upgrade to be implemented.		
	The impact is low because most of the late files were only a day or two late and the longest delay was no more than six business days late.		
Actions tak	en to resolve the issue	Completion date	Remedial action status
The automated switching system is now up, and we do not expect to operate without it going forward.		Implemented	Cleared
With the upgrade to our system completed we should now be compliant. Future upgrades will not have to take this part of the system down.		Implemented	

4.9. Losing trader determines a different date - switch move (Clause 10(2) Schedule 11.3)

Code reference

Clause 10(2) Schedule 11.3

Code related audit information

If the losing trader determines a different date, then within 10 business days of receiving notice the losing trader must also complete the switch by providing to the registry manager as described in subclause (1)(a):

- the event date proposed by the losing trader; and
- a valid switch response code; and
- final information as required under clause 1.

Audit observation

The event detail report was reviewed to identify AN files issued by Paua during the audit period, and assess compliance with the requirement to meet the setting of event dates requirement.

Audit commentary

Analysis found all switch move ANs had a valid switch response code, and switches were completed as required by this clause. Paua accepted the proposed event dates for all ICPs.

Audit outcome

Compliant

4.10. Losing trader must provide final information - switch move (Clause 11 Schedule 11.3)

Code reference

Clause 11 Schedule 11.3

Code related audit information

The losing trader must provide final information to the registry manager for the purposes of clause 10(1)(a)(ii), including—

- the event date (clause 11(a)); and
- a switch event meter reading as at the event date for each meter or data storage device that is recorded in the registry with an accumulator type of C and a settlement indicator of Y (clause 11(b)); and
- if the switch event meter reading is not a validated meter reading, the date of the last meter reading of the meter or storage device (clause (11(c)).

Audit observation

The CS process was examined, and the event detail report was reviewed to identify CS files issued by Paua during the audit period. The accuracy of the content of CS files was confirmed by checking a sample of records. The content checked included:

- correct identification of meter readings and correct date of last meter reading,
- accuracy of meter readings, and
- accuracy of average daily consumption.

CS files with average daily kWh that was negative, zero, or over 200 kWh were identified. A sample of these CS files were checked to determine whether the average daily consumption was correct.

Audit commentary

All ICPs have HHR AMI meters and are expected to switch in and out on validated readings. The HHR data management system automatically creates a CS file as soon as a midnight reading is received, or estimated, for the day before the switch event date.

- The read quality indicator is used to determine whether reads should be classified as estimate or
 actual, and determine the last actual read date during the period of supply. The HHR data
 management system creates an alert where there is no HHR data available to create the CS file.
- The registry functional specification requires average daily kWh to be based on the average daily consumption for the last read to read period. Paua receives daily readings, and the average daily kWh is based on the average daily consumption between the last two readings received prior to switch out, truncated to zero decimal places. Paua's average daily kWh process was considering estimates where actual readings were not available. During the audit, Paua updated the HHR data management system logic during to consider only actual readings and create an alert where less than two actual readings have been received, so that the average daily kWh could be updated manually. Review of the event detail report confirmed that all CS files during the audit period switched out on actual readings, and all CS files checked had compliant average daily kWh.

 The key held indicator is determined from information obtained from the customer on application and stored in the HHR data management system. Paua have not held any customer keys to date, because all meters are read remotely.

Review of the event detail report did not identify any switch moves with average daily kWh which was negative or over 200 kWh. 11 switch move CS files had zero estimated daily kWh. A sample of nine were checked for eight files and found the data was recorded correctly.

Audit outcome

Compliant

4.11. Gaining trader changes to switch meter reading - switch move (Clause 12 Schedule 11.3)

Code reference

Clause 12 Schedule 11.3

Code related audit information

The gaining trader may use the switch event meter reading supplied by the losing trader or may, at its own cost, obtain its own switch event meter reading. If the gaining trader elects to use this new switch event meter reading, the gaining trader must advise the losing trader of the switch event meter reading and the actual event date to which it refers as follows:

- if the switch meter reading established by the gaining trader differs by less than 200 kWh from that provided by the losing trader, both traders must use the switch event meter reading provided by the gaining trader (clause 12(2)(a)); or
- if the switch event meter reading provided by the losing trader differs by 200 kWh or more from a value established by the gaining trader, the gaining trader may dispute the switch meter reading. In this case, the gaining trader, within 4 calendar months of the date the registry manager gives the gaining trader written notice of having received information about the switch completion, must provide to the losing trader a changed validated meter reading or a permanent estimate supported by 2 validated meter readings and the losing trader must either (clause 12(2)(b) and clause 12(3)):
- advise the gaining trader if it does not accept the switch event meter reading and the losing trader and the gaining trader must resolve the dispute in accordance with the dispute procedure in clause 15.29 (with all necessary amendments) (clause 12(3)(a)); or
- if the losing trader notifies its acceptance or does not provide any response, the losing trader must use the switch event meter reading supplied by the gaining trader (clause 12(3)(b)).

12(2A) If the losing trader trades electricity from a non-half hour meter, with a switch event meter reading that is not from an AMI certified meter flagged Y in the registry,

- the gaining trader will trade electricity from a meter with a half hour submission type in the registry (clause 12(2A)(b));
- the gaining trader no later than five business days after receiving final information from the registry manager, may provide the losing trader with a switch event meter reading from that meter. The losing trader must use that switch event meter reading (clause 12(2B)).

Audit observation

The process for the management of read change requests was examined.

The event detail report was analysed to identify all read change requests and acknowledgements during the audit period. A sample of RR and AC files issued for switch moves were checked to confirm that the content was correct, and that Paua's systems reflected the outcome of the RR process.

I also checked for CS files with estimated readings provided by other traders where no RR was issued, to determine whether the correct readings were recorded in Paua's systems.

The switch breach history report for the audit period was reviewed.

Audit commentary

All ICPs switched in will have HHR AMI meters and are expected to switch in and out on validated readings. The HHR data management system compares the losing trader's closing read with the actual midnight read as soon as it is received by calculating the difference between the midnight reading on Paua's first day of supply and the sum of the intervals for the first day of supply. Where the CS read differs from the calculated opening reading the HHR data management system will automatically send an RR file, because the CS read appears to be incorrect. These read change requests normally meet the requirements of 6(2) and (3) Schedule 11.3 and are required to be accepted by the losing retailer. The HHR data management system creates an alert where there is no HHR data available to determine whether an RR is required.

However, for the period of time during the implementation of an upgrade to the front end of the HHR data management system the automated process to compare the switch read with the first received midnight read during the period of supply less the sum of the intervals for this first day of supply did not occur. This meant that RR files were not sent to the losing trader where the switch read estimate did not align with the HHR consumption information received by Paua. The automated process is now back online.

Any ACs accepting Paua's proposed change are automatically processed by the HHR data management system, and ACs rejecting the proposed change are directed to an operator who will either reissue the RR or manually change the opening read.

RRs issued by other traders are directed to an operator, who will review the request and accept or reject it. The HHR data management system will generate the AC file which contains the operator response the evening after it is added.

The switch breach history report is also reviewed manually every two to three days, to check that all files have been issued as required.

Application of CS readings

Review of the event detail report identified five switch move CS files issued to Paua where an estimated reading had been provided and no RR file had been issued. For one ICP (0000047860TR436) the switch read estimate did not align with the HHR consumption volumes submitted by Paua and no adjustments were made to ensure that no consumption was lost in the switching process. Non-compliance is recorded.

RR

No RR were issued for a switch move during the audit period.

AC

One AC was issued for a switch move. The other trader's RR was validly accepted, and the reads and volumes recorded in the HHR data management system reflected the outcome of the RR process. The switch breach history report did not record any late AC files.

Audit outcome

Non-compliance	Description		
Audit Ref: 4.11	Switch event reading not used for ICP (0000047860TR436).		
With: 12 Schedule 11.3	Potential impact: Low		
	Actual impact: Low		
	Audit history: None		
From: 01-Mar-21	Controls: Strong		
To: 30-Sep-22	Breach risk rating: 1		
Audit risk rating	Rationale for audit risk rating		
Low	Controls are assessed as strong because the process is automated, and the failure to issue RR files occurred during the period the switching automation within the HHR data management system was offline to enable a system upgrade to be implemented. The impact is low as the volumes are small.		
Actions take	en to resolve the issue	Completion date	Remedial action status
The opening read for 0000047860TR436 has been adjusted to match the supplied estimate.		Cleared	Cleared
Preventative actions tak	en to ensure no further issues will occur	Completion date	
With the upgrade to our system completed we should now be compliant. Future upgrades will not have to take this part of the system down.		Implemented	

4.12. Gaining trader informs registry of switch request - gaining trader switch (Clause 14 Schedule 11.3)

Code reference

Clause 14 Schedule 11.3

Code related audit information

The gaining trader switch process applies when a trader has an arrangement with a customer or embedded generator to trade electricity at an ICP at which the losing trader trades electricity with the customer or embedded generator, and one of the following applies at the ICP:

- the gaining trader will trade electricity through a half hour metering installation that is a category 3 or higher metering installation; or
- the gaining trader will trade electricity through a non-AMI half hour metering installation and the losing trader trades electricity through a non-AMI non half hour metering installation; or
- the gaining trader will trade electricity through a non-AMI non half hour metering installation and the losing trader trades electricity through anon-AMI half hour metering installation.

If the uninvited direct sale agreement applies to an arrangement described above, the gaining trader must identify the period within which the customer or embedded generator may cancel the arrangement

in accordance with section 36M of the Fair Trading Act 1986. The arrangement is deemed to come into effect on the day after the expiry of that period.

A gaining trader must advise the registry manager of the switch and expected event date no later than three business days after the arrangement comes into effect.

14(2) The gaining trader must include in its advice to the registry manager:

- a) a proposed event date; and
- b) that the switch type is HH.

14(3) The proposed event date must be a date that is after the date on which the gaining trader advises the registry manager, unless clause 14(4) applies.

14(4) The proposed event date is a date before the date on which the gaining trader advised the registry manager, if:

14(4)(a) – the proposed event date is in the same month as the date on which the gaining trader advised the registry manager; or

14(4)(b) – the proposed event date is no more than 90 days before the date on which the gaining trader advises the registry manager, and this date is agreed between the losing and gaining traders.

Audit observation

The event detail report was examined to identify any HH switches, and switches for ICPs with metering category 3 or higher.

Audit commentary

All ICPs supplied by Paua have metering category 1, and no HH switches were identified.

Audit outcome

Compliant

4.13. Losing trader provision of information - gaining trader switch (Clause 15 Schedule 11.3)

Code reference

Clause 15 Schedule 11.3

Code related audit information

Within three business days after the losing trader is informed about the switch by the registry manager, the losing trader must:

15(a) - provide to the registry manager a valid switch response code as approved by the Authority; or

15(b) - provide a request for withdrawal of the switch in accordance with clause 17.

Audit observation

The event detail report was examined to identify any HH switches, and switches for ICPs with metering category 3 or higher.

Audit commentary

All ICPs supplied by Paua have metering category 1, and no HH switches were identified.

Audit outcome

Compliant

4.14. Gaining trader to advise the registry manager - gaining trader switch (Clause 16 Schedule 11.3)

Code reference

Clause 16 Schedule 11.3

Code related audit information

The gaining trader must complete the switch no later than three business days, after receiving the valid switch response code, by advising the registry manager of the event date.

If the ICP is being electrically disconnected, or if metering equipment is being removed, the gaining trader must either-

16(a)- give the losing trader or MEP for the ICP an opportunity to interrogate the metering installation immediately before the ICP is electrically disconnected or the metering equipment is removed; or

16(b)- carry out an interrogation and, no later than five business days after the metering installation is electrically disconnected or removed, advise the losing trader of the results and metering component numbers for each data channel in the metering installation.

Audit observation

The event detail report was examined to identify any HH switches, and switches for ICPs with metering category 3 or higher.

Audit commentary

All ICPs supplied by Paua have metering category 1, and no HH switches were identified.

Audit outcome

Compliant

4.15. Withdrawal of switch requests (Clauses 17 and 18 Schedule 11.3)

Code reference

Clauses 17 and 18 Schedule 11.3

Code related audit information

A losing trader or gaining trader may request that a switch request be withdrawn at any time until the expiry of two calendar months after the event date of the switch.

If a trader requests the withdrawal of a switch, the following provisions apply:

- for each ICP, the trader withdrawing the switch request must provide the registry manager with (clause 18(c)):
 - the participant identifier of the trader making the withdrawal request (clause 18(c)(i));
 and
 - o the withdrawal advisory code published by the Authority (clause 18(c)(ii))
- within five business days after receiving notice from the registry manager of a switch, the trader receiving the withdrawal must advise the registry manager that the switch withdrawal request is accepted or rejected. A switch withdrawal request must not become effective until accepted by the trader who received the withdrawal (clause 18(d)).
- on receipt of a rejection notice from the registry manager, in accordance with clause 18(d), a trader may re-submit the switch withdrawal request for an ICP in accordance with clause 18(c).

- All switch withdrawal requests must be resolved within 10 business days after the date of the initial switch withdrawal request (clause 18(e)).
- if the trader requests that a switch request be withdrawn, and the resolution of that switch withdrawal request results in the switch proceeding, within two business days after receiving notice from the registry manager in accordance with clause 22(b), the losing trader must comply with clauses 3,5,10 and 11 (whichever is appropriate) and the gaining trader must comply with clause 16 (clause 18(f)).

Audit observation

The event detail report was reviewed to identify all NW and AW files issued by Paua, and review them for accuracy. The switch breach history report was checked for any late switch withdrawal requests or acknowledgements.

Audit commentary

The HHR data management system automatically generates NWs for date failure where:

- a transfer switch proposed transfer date is more than nine business days after NT receipt, or
- a switch move proposed transfer date is more than four business days after NT receipt.

Otherwise, the HHR data management system creates a NW file once the operator has selected an NW code from the drop-down list, which includes the required codes. Paua's documentation confirmed that NWs are required to be created within two months of the switch being completed and their NW code application policy should ensure that the correct codes are applied. When the NW is raised, the HHR data management system creates an AW ticket which remains open until the AW is received for monitoring purposes.

NWs issued by other traders will be directed to an operator, who will review the request and accept or reject it. The HHR data management system will generate the AW file which contains the operator response the evening after it is added. The switch breach history report is also reviewed manually every two to three days, to check that all files have been issued as required.

NW

Four NW files were issued by Paua, and the switch breach history report did not record any late NW files.

ΑW

Three AW files were issued by Paua, and the switch breach history identified two late AW files. The reason for the late AW files was due to the manual checks for outstanding NW requests not being performed regularly during the time the automated process was offline due an upgrade of the HHR data management system front end. All of the AW files accepted the other trader's NW.

Audit outcome

Non-compliance	0	escription	
Audit Ref: 4.15 With: Clause17 and 18	Two AW files were delivered late. Potential impact: Low		
Schedule 11.3	Actual impact: Low		
From: 01-Mar-21 To: 30-Sep-22	Audit history: None Controls: Strong		
Audit risk rating	Breach risk rating: 1 Rationale	for audit risk rati	ng
Low	Controls are assessed as strong because the process is automated, and the failure to issue AW files on time occurred during the period the switching automation within the HHR data management system was offline to enable a system upgrade to be implemented. The impact is low because the delay in providing the AW files was no more than six business days.		
Actions take	en to resolve the issue	Completion date	Remedial action status
The automated switching s expect to operate without	ystem is now up, and we do not it going forward.	Implemented	Cleared
Preventative actions tak	en to ensure no further issues will occur	Completion date	
With the upgrade to our system completed we should now be compliant. Future upgrades will not have to take this system down.		Implemented	

4.16. Metering information (Clause 21 Schedule 11.3)

Code reference

Clause 21 Schedule 11.3

Code related audit information

For an interrogation or validated meter reading or permanent estimate carried out in accordance with Schedule 11.3:

21(a)- the trader who carries out the interrogation, switch event meter reading must ensure that the interrogation is as accurate as possible, or that the switch event meter reading is fair and reasonable.

21(b) and (c) - the cost of every interrogation or switch event meter reading carried out in accordance with clauses 5(b) or 11(b) or (c) must be met by the losing trader. The costs in every other case must be met by the gaining trader.

Audit observation

The meter reading process in relation to meter reads for switching purposes was examined.

Audit commentary

All meter readings used in the switching process are validated meter readings or permanent estimates. All CS files generated during the audit period had actual readings.

Paua's policy regarding the management of meter reading expenses is compliant.

Audit outcome

Compliant

4.17. Switch protection (Clause 1(a)&(b) of Part 1 and 11.15AA to 11.15AC of Part 11)

Code reference

Clause 11.15AA to 11.15AC

Code related audit information

A losing retailer (including any party acting on behalf of the retailer) must not initiate contact to save or win back any customer who is switching away or has switched away for 180 days from the date of the switch.

The losing retailer may contact the customer for certain administrative reasons and may make a counteroffer only if the customer initiated contacted with the losing retailer and invited the losing retailer to make a counteroffer.

The losing retailer must not use the customer contact details to enable any other retailer (other than the gaining retailer) to contact the customer.

Audit observation

Win-back processes were discussed. The event detail report was analysed to identify all withdrawn switches with a CX code applied within 180 days of switch completion post 31 March 2020.

Audit commentary

Paua emails the customers for ICPs requested by another retailer only to confirm that the switch request is valid, and if they have any comments on why they decided to switch. No win-back activity is initiated with lost customers.

No NWs were issued during the audit period.

Audit outcome

5. MAINTENANCE OF UNMETERED LOAD

5.1. Maintaining shared unmetered load (Clause 11.14)

Code reference

Clause 11.14

Code related audit information

The trader must adhere to the process for maintaining shared unmetered load as outlined in clause 11.14:

- 11.14(2) The distributor must give written notice to the traders responsible for the ICPs across which the unmetered load is shared, of the ICP identifiers of the ICPs.
- 11.14(3) A trader who receives such a notification from a distributor must give written notice to the distributor if it wishes to add or omit any ICP from the ICPs across which unmetered load is to be shared.
- 11.14(4) A distributor who receives such a notification of changes from the trader under (3) must give written notice to the registry manager and each trader responsible for any of the ICPs across which the unmetered load is shared.
- 11.14(5) If a distributor becomes aware of any change to the capacity of a shared unmetered load ICP or if a shared unmetered load ICP is decommissioned, it must give written notice to all traders affected by that change as soon as practicable after that change or decommissioning.
- 11.14(6) Each trader who receives such a notification must, as soon as practicable after receiving the notification, adjust the unmetered load information for each ICP in the list for which it is responsible to ensure that the entire shared unmetered load is shared equally across each ICP.
- 11.14(7) A trader must take responsibility for shared unmetered load assigned to an ICP for which the trader becomes responsible as a result of a switch in accordance with Part 11.
- 11.14(8) A trader must not relinquish responsibility for shared unmetered load assigned to an ICP if there would then be no ICPs left across which that load could be shared.
- 11.14(9) A trader can change the status of an ICP across which the unmetered load is shared to inactive status, as referred to in clause 19 of Schedule 11.1. In that case, the trader is not required to give written notice to the distributor of the change. The amount of electricity attributable to that ICP becomes UFE.

Audit observation

The processes to identify and monitor shared unmetered load were discussed. The registry list and ACO20 report were reviewed to identify any ICPs with shared unmetered load and assess compliance.

Audit commentary

Paua only accepts applications from customers who do not have unmetered load connected.

Review of the registry list and audit compliance reports confirmed that no unmetered load is recorded by the distributor or trader for any Paua ICP. All active ICPs are metered with an MEP recorded and at least one meter channel.

Additions or changes to unmetered load details will be identified as part of the registry validation process. A daily ICP list with history (including all data from January 2015 onwards) is downloaded from the registry and imported into the HHR data management system. Changes to attributes are reported to the operator for investigation in the action hub, including changes to distributor unmetered load

details. If unmetered load is found, Paua would relinquish responsibility for shared unmetered load if allowed under clause 11.14 or would arrange for the ICP to switch out.

Audit outcome

Compliant

5.2. Unmetered threshold (Clause 10.14 (2)(b))

Code reference

Clause 10.14 (2)(b)

Code related audit information

The reconciliation participant must ensure that unmetered load does not exceed 3,000 kWh per annum, or 6,000 kWh per annum if the load is predictable and of a type approved and published by the Authority.

Audit observation

The registry list and AC020 report were reviewed to identify any ICPs with unmetered load over 3,000 kWh per annum.

Audit commentary

Paua has not supplied any ICPs with unmetered load.

Audit outcome

Compliant

5.3. Unmetered threshold exceeded (Clause 10.14 (5))

Code reference

Clause 10.14 (5)

Code related audit information

If the unmetered load limit is exceeded the retailer must:

- within 20 business days, commence corrective measure to ensure it complies with Part 10,
- within 20 business days of commencing the corrective measure, complete the corrective measures,
- no later than 10 business days after it becomes aware of the limit having been exceeded, advise each participant who is or would be expected to be affected of:
 - o the date the limit was calculated or estimated to have been exceeded,
 - the details of the corrective measures that the trader proposes to take or is taking to reduce the unmetered load.

Audit observation

The registry list and AC020 report were reviewed to identify any ICPs with unmetered load over 6,000 kWh per annum.

Audit commentary

Paua has not supplied any ICPs with unmetered load.

Audit outcome

5.4. Distributed unmetered load (Clause 11 Schedule 15.3, Clause 15.37B)

Code reference

Clause 11 Schedule 15.3, Clause 15.37B

Code related audit information

An up-to-date database must be maintained for each type of distributed unmetered load for which the retailer is responsible. The information in the database must be maintained in a manner that the resulting submission information meets the accuracy requirements of clause 15.2.

A separate audit is required for distributed unmetered load data bases.

The database must satisfy the requirements of Schedule 15.5 with regard to the methodology for deriving submission information.

Audit observation

The registry list was reviewed to identify any ICPs with distributed unmetered load.

Audit commentary

Paua has not supplied any ICPs with unmetered load.

Audit outcome

6. GATHERING RAW METER DATA

6.1. Electricity conveyed & notification by embedded generators (Clause 10.13, Clause 10.24 and 15.13)

Code reference

Clause 10.13, Clause 10.24 and Clause 15.13

Code related audit information

A participant must use the quantity of electricity measured by a metering installation as the raw meter data for the quantity of electricity conveyed through the point of connection.

This does not apply if data is estimated or gifted in the case of embedded generation under clause 15.13.

A trader must, for each electrically connected ICP that is not also an NSP, and for which it is recorded in the registry as being responsible, ensure that:

- there is one or more metering installations,
- all electricity conveyed is quantified in accordance with the Code,
- it does not use subtraction to determine submission information for the purposes of Part 15.

An embedded generator must give notification to the reconciliation manager for an embedded generating station, if the intention is that the embedded generator will not be receiving payment from the clearing manager or any other person through the point of connection to which the notification relates.

Audit observation

Processes for metering, submission, and distributed generation were reviewed. The registry list and ACO20 report were examined to determine compliance.

Audit commentary

Metering installations installed

All active ICPs have an MEP, and at least one meter channel. No submission information is determined using subtraction, and no new connections were completed during the audit period.

Distributed Generation

Paua declines applications to supply customers with distributed generation unless they are for an existing Paua customer.

ICP 0000170598TR21D had distributed generation added by the distributor and EG metering added by the MEP on 12 February 2021. I checked submission information for February 2022 and confirmed that X and I flow submission was correctly recorded.

Bridged meters

Paua does not normally allow meters to be bridged, and no bridged meters were identified during the audit period.

Audit outcome

6.2. Responsibility for metering at GIP (Clause 10.26 (6), (7) and (8))

Code reference

Clause 10.26 (6), (7) and (8)

Code related audit information

For each proposed metering installation or change to a metering installation that is a connection to the grid, the participant, must:

- provide to the grid owner a copy of the metering installation design (before ordering the equipment)
- provide at least three months for the grid owner to review and comment on the design,
- respond within three business days of receipt to any request from the grid owner for additional details or changes to the design,
- ensure any reasonable changes from the grid owner are carried out.

The participant responsible for the metering installation must:

- advise the reconciliation manager of the certification expiry date not later than 10 business days after certification of the metering installation,
- become the MEP or contract with a person to be the MEP,
- advise the reconciliation manager of the MEP identifier no later than 20 days after entering into a contract or assuming responsibility to be the MEP.

Audit observation

The NSP table was reviewed to confirm whether Paua is responsible for any GIPs.

Audit commentary

Review of the NSP table confirmed that Paua is not responsible for any GIPs.

Audit outcome

Not applicable

6.3. Certification of control devices (Clause 33 Schedule 10.7 and clause 2(2) Schedule 15.3)

Code reference

Clause 33 Schedule 10.7 and clause 2(2) Schedule 15.3

Code related audit information

The reconciliation participant must advise the metering equipment provider if a control device is used to control load or switch meter registers.

The reconciliation participant must ensure the control device is certified prior to using it for reconciliation purposes.

Audit observation

The ACO20 report and registry list were reviewed to confirm the profiles used.

Audit commentary

Examination of the reports found that Paua has only used the HHR profile, and control devices are not used for reconciliation purposes.

Audit outcome

6.4. Reporting of defective metering installations (Clause 10.43(2) and (3))

Code reference

Clause 10.43(2) and (3)

Code related audit information

If a participant becomes aware of an event or circumstance that leads it to believe a metering installation could be inaccurate, defective, or not fit for purpose they must:

- advise the MEP,
- include in the advice all relevant details.

Audit observation

Processes for defective metering were examined. All meter defects identified were checked.

Audit commentary

Defective meters are typically identified through the meter reading validation process, or from information provided by the MEP or customer. Reporting is in place to identify meters which have not communicated for more than 28 days, so that the operator can raise a communications fault. During the audit Paua adjusted the query to report ICPs which have not been read for 21 days and added the report to the data management hub.

Upon identifying a possible defective meter, Paua raises a field services job to investigate.

I reviewed nine HHR aggregates submissions and checked all ICPs with zero consumption to determine whether it was genuine or related to a meter fault or accuracy issue. In all cases the zero consumption was genuine.

Audit outcome

Compliant

6.5. Collection of information by certified reconciliation participant (Clause 2 Schedule 15.2)

Code reference

Clause 2 Schedule 15.2

Code related audit information

Only a certified reconciliation participant may collect raw meter data, unless only the MEP can interrogate the meter, or the MEP has an arrangement which prevents the reconciliation participant from electronically interrogating the meter:

- 2(2) The reconciliation participant must collect raw meter data used to determine volume information from the services interface or the metering installation or from the MEP.
- 2(3) The reconciliation participant must ensure the interrogation cycle is such that is does not exceed the maximum interrogation cycle in the registry.
- 2(4) The reconciliation participant must interrogate the meter at least once every maximum interrogation cycle.

2(5) - When electronically interrogating the meter the participant must:

- a) ensure the system is to within +/- 5 seconds of NZST or NZDST,
- b) compare the meter time to the system time,
- c) determine the time error of the metering installation,
- d) if the error is less than the maximum permitted error, correct the meter's clock,
- e) if the time error is greater than the maximum permitted error then:
 - i) correct the metering installation's clock,
 - ii) compare the metering installation's time with the system time,
 - iii) correct any affected raw meter data.
- f) download the event log.

2(6) – The interrogation systems must record:

- the time
- the date
- the extent of any change made to the meter clock.

Audit observation

HHR AMI data is provided by AMS, Intellihub and Metrix as MEPs. Interrogation requirements and clock synchronisation were reviewed as part of their MEP audits.

Audit commentary

Fulfilment of the interrogation systems requirements was examined as part of the MEP's audits and found to be compliant.

Meter event reports and clock synchronisation events provided by the MEP are imported into the HHR data management system. Paua works through the events in the data management hub every two to three days, checking data before and after the event occurred using a graph to determine whether action is required.

Paua had not received notification of any clock synchronisation events outside the maximum permissible errors during the audit period. I reviewed one example of a clock synchronisation event within maximum permissible errors and there was no impact on the HHR data.

Audit outcome

Compliant

6.6. Derivation of meter readings (Clauses 3(1), 3(2) and 5 Schedule 15.2)

Code reference

Clauses 3(1), 3(2) and 5 Schedule 15.2

Code related audit information

All meter readings must in accordance with the participants certified processes and procedures and using its certified facilities be sourced directly from raw meter data and, if appropriate, be derived and calculated from financial records.

All validated meter readings must be derived from meter readings.

A meter reading provided by a consumer may be used as a validated meter reading only if another set of validated meter readings not provided by the consumer are used during the validation process.

During the manual interrogation of each NHH metering installation the reconciliation participant must:

a) obtain the meter register,

- b) ensure seals are present and intact,
- c) check for phase failure (if supported by the meter),
- d) check for signs of tampering and damage,
- e) check for electrically unsafe situations,

if the relevant parts of the metering installation are visible and it is safe to do so.

Audit observation

The data collection process was examined. Paua will only accept digital photo reads where an AMI meter has comms issues preventing data delivery. Paua uses these customer provided reads to estimate interval data. Paua records these readings as estimates and the interval data based on these reads and the customers historic consumption pattern as estimated data.

Audit commentary

HHR AMI data is provided by AMS, Metrix and Intellihub as MEPs. Validated readings are derived from actual meter readings.

Metrix and Intellihub provide estimates where data is missing. Paua does not use these estimates and creates their own as described in **section 9.4**.

Audit outcome

Compliant

6.7. NHH meter reading application (Clause 6 Schedule 15.2)

Code reference

Clause 6 Schedule 15.2

Code related audit information

For NHH switch event meter reads, for the gaining trader the reading applies from 0000 hours on the day of the relevant event date and for the losing trader at 2400 hours at the end of the day before the relevant event date.

In all other cases, All NHH readings apply from 0000hrs on the day after the last meter interrogation up to and including 2400hrs on the day of the meter interrogation.

Audit observation

Review of the registry list with history confirmed that all ICPs supplied by Paua have HHR metering and submission type.

Audit commentary

All ICPs have submission type HHR. Review of switch reads in **sections 4.3** and **4.10** confirmed that they are applied from the correct time.

Audit outcome

6.8. Interrogate meters once (Clause 7(1) and (2) Schedule 15.2)

Code reference

Clause 7(1) and (2) Schedule 15.2

Code related audit information

Each reconciliation participant must ensure that a validated meter reading is obtained in respect of every meter register for every non half hour metered ICP for which the participant is responsible, at least once during the period of supply to the ICP by the reconciliation participant and used to create volume information.

This may be a validated meter reading at the time the ICP is switched to, or from, the reconciliation participant.

If exceptional circumstances prevent a reconciliation participant from obtaining the validated meter reading, the reconciliation participant is not required to comply with clause 7(1).

Audit observation

Review of the registry list with history confirmed that all ICPs supplied by Paua have HHR metering and submission type.

Audit commentary

All ICPs have submission type HHR, and this clause does not apply.

Audit outcome

Not applicable

6.9. NHH meters interrogated annually (Clause 8(1) and (2) Schedule 15.2)

Code reference

Clause 8(1) and (2) Schedule 15.2

Code related audit information

At least once every 12 months, each reconciliation participant must obtain a validated meter reading for every meter register for non-half hour metered ICPs, at which the reconciliation participant trades continuously for each 12-month period.

If exceptional circumstances prevent a reconciliation participant from obtaining the validated meter reading, the reconciliation participant is not required to comply with clause 8(1).

Audit observation

Review of the registry list with history confirmed that all ICPs supplied by Paua have HHR metering and submission type.

Audit commentary

All ICPs have submission type HHR, and this clause does not apply.

Audit outcome

Not applicable

6.10. NHH meters 90% read rate (Clause 9(1) and (2) Schedule 15.2)

Code reference

Clause 9(1) and (2) Schedule 15.2

Code related audit information

In relation to each NSP, each reconciliation participant must ensure that for each NHH ICP at which the reconciliation participant trades continuously for each four months, for which consumption information is required to be reported into the reconciliation process. A validated meter reading is obtained at least once every 4 months for 90% of the non-half hour metered ICPs.

A report is to be sent to the Authority providing the percentage, in relation to each NSP, for which consumption information has been collected no later than 20 business days after the end of each month.

If exceptional circumstances prevent a reconciliation participant from obtaining the validated meter reading, the reconciliation participant is not required to comply with clause 9(1).

Audit observation

Review of the registry list with history confirmed that all ICPs supplied by Paua have HHR metering and submission type.

Audit commentary

All ICPs have submission type HHR, and this clause does not apply.

Audit outcome

Not applicable

6.11. NHH meter interrogation log (Clause 10 Schedule 15.2)

Code reference

Clause 10 Schedule 15.2

Code related audit information

The following information must be logged as the result of each interrogation of the NHH metering:

10(a) - the means to establish the identity of the individual meter reader,

10(b) - the ICP identifier of the ICP, and the meter and register identification,

10(c) - the method being used for the interrogation and the device ID of equipment being used for interrogation of the meter,

10(d) - the date and time of the meter interrogation.

Audit observation

Review of the registry list with history confirmed that all ICPs supplied by Paua have HHR metering and submission type.

Audit commentary

All ICPs have submission type HHR, and this clause does not apply.

Audit outcome

Not applicable

6.12. HHR data collection (Clause 11(1) Schedule 15.2)

Code reference

Clause 11(1) Schedule 15.2

Code related audit information

Raw meter data from all electronically interrogated metering installations must be obtained via the services access interface.

This may be carried out by a portable device or remotely.

Audit observation

HHR AMI data is provided by AMS, Intellihub, and Metrix as MEPs, and compliance was assessed as part of their MEP audits.

Audit commentary

AMS, Intellihub, and Metrix are responsible for HHR data collection, and compliance is recorded in their audit reports.

Audit outcome

Compliant

6.13. HHR interrogation data requirement (Clause 11(2) Schedule 15.2)

Code reference

Clause 11(2) Schedule 15.2

Code related audit information

The following information is collected during each interrogation:

11(2)(a) - the unique identifier of the data storage device

11(2)(b) - the time from the data storage device at the commencement of the download unless the time is within specification and the interrogation log automatically records the time of interrogation,

11(2)(c) - the metering information, which represents the quantity of electricity conveyed at the point of connection, including the date and time stamp or index marker for each half hour period. This may be limited to the metering information accumulated since the last interrogation,

11(2)(d) - the event log, which may be limited to the events information accumulated since the last interrogation,

11(2)(e) - an interrogation log generated by the interrogation software to record details of all interrogations.

The interrogation log must be examined by the reconciliation participant responsible for collecting the data and appropriate action must be taken if problems are apparent or an automated software function flags exceptions.

Audit observation

HHR AMI data is provided by AMS, Intellihub, and Metrix as MEPs.

Audit commentary

MEPs are responsible for meeting the meter interrogation data requirements, and this is reviewed as part of their audits.

Audit outcome

Compliant

6.14. HHR interrogation log requirements (Clause 11(3) Schedule 15.2)

Code reference

Clause 11(3) Schedule 15.2

Code related audit information

The interrogation log forms part of the interrogation audit trail and, as a minimum, must contain the following information:

11(3)(a)- the date of interrogation

11(3)(b)- the time of commencement of interrogation

11(3)(c)- the operator identification (if available)

11(3)(d)- the unique identifier of the meter or data storage device

11(3)(e)- the clock errors outside the range specified in Table 1 of clause 2

11(3)(f)- the method of interrogation

11(3)(g)- the identifier of the reading device used for interrogation (if applicable).

Audit observation

HHR AMI data is provided by AMS, Intellihub, and Metrix as MEPs.

Audit commentary

MEPs are responsible for meeting the meter interrogation data requirements, and this is reviewed as part of their audits.

Audit outcome

7. STORING RAW METER DATA

7.1. Trading period duration (Clause 13 Schedule 15.2)

Code reference

Clause 13 Schedule 15.2

Code related audit information

The trading period duration, normally 30 minutes, must be within $\pm 0.1\%$ (± 2 seconds).

Audit observation

Trading period duration was reviewed as part of AMS, Intellihub and Metrix MEP audits.

Audit commentary

MEPs are responsible for trading period duration, and compliance is recorded in their audit reports. Clock synchronisation is discussed further in **section 6.5.**

Audit outcome

Compliant

7.2. Archiving and storage of raw meter data (Clause 18 Schedule 15.2)

Code reference

Clause 18 Schedule 15.2

Code related audit information

A reconciliation participant who is responsible for interrogating a metering installation must archive all raw meter data and any changes to the raw meter data for at least 48 months, in accordance with clause 8(6) of Schedule 10.6.

Procedures must be in place to ensure that raw meter data cannot be accessed by unauthorised personnel.

Meter readings cannot be modified without an audit trail being created.

Audit observation

Raw meter data is retained by AMS, Intellihub and Metrix as MEPs, and compliance is assessed as part of their MEP audits.

Processes to archive and store raw meter data were reviewed.

Audit commentary

Compliance with this clause is recorded in the MEP's audit reports.

Paua retains meter reading data for over 48 months. I viewed the earliest meter readings recorded in Paua's system, which matched the switch in date for their earliest customer on 23 January 2015.

As discussed in **section 2.4**, Paua has recently upgraded its HHR data management systems front end and as part of this effort a full back load of HHR interval data from the original source interval data files was conducted. This backload resulted in previous data estimations and corrections to be overwritten and resulting audit trails to be lost. Non-compliance is recorded in **section 2.4** for this single event resulting in the loss of historic audit trails and journals.

Access to modify readings is restricted through log on privileges, and audit trails are discussed in **section 2.4**.

Audit outcome

Compliant

7.3. Non metering information collected/archived (Clause 21(5) Schedule 15.2)

Code reference

Clause 21(5) Schedule 15.2

Code related audit information

All relevant non-metering information, such as external control equipment operation logs, used in the determination of profile data must be collected, and archived in accordance with clause 18.

Audit observation

Processes to record non-metering information were discussed.

Audit commentary

No non-metering information is collected by Paua.

Audit outcome

8. CREATING AND MANAGING (INCLUDING VALIDATING, ESTIMATING, STORING, CORRECTING AND ARCHIVING) VOLUME INFORMATION

8.1. Correction of NHH meter readings (Clause 19(1) Schedule 15.2)

Code reference

Clause 19(1) Schedule 15.2

Code related audit information

If a reconciliation participant detects errors while validating non-half hour meter readings, the reconciliation participant must:

19(1)(a) - confirm the original meter reading by carrying out another meter reading

19(1)(b) – replace the original meter reading the second meter reading (even if the second meter reading is at a different date)

19(1A) if a reconciliation participant detects errors while validating non half hour meter readings, but the reconciliation participant cannot confirm the original meter reading or replace it with a meter reading from another interrogation, the reconciliation participant must:

- substitute the original meter reading with an estimated reading that is marked as an estimate; and
- subsequently replace the estimated reading in accordance with clause 4(2).

Audit observation

Review of the registry list with history confirmed that all ICPs supplied by Paua have HHR metering and submission type.

Audit commentary

All ICPs have submission type HHR, and this clause does not apply.

Audit outcome

Not applicable

8.2. Correction of HHR metering information (Clause 19(2) Schedule 15.2)

Code reference

Clause 19(2) Schedule 15.2

Code related audit information

If a reconciliation participant detects errors while validating half hour meter readings, the reconciliation participant must correct the meter readings as follows:

19(2)(a) - if the relevant metering installation has a check meter or data storage device, substitute the original meter reading with data from the check meter or data storage device; or

19(2)(b) - if the relevant metering installation does not have a check meter or data storage device, substitute the original meter reading with data from another period provided:

- i. The total of all substituted intervals matches the total consumption recorded on a meter, if available; and
- ii. The reconciliation participant considers the pattern of consumption to be materially similar to the period in error.

Audit observation

Processes for correction of HHR meter readings were reviewed.

Audit commentary

HHR estimates and corrections are processed in the HHR data management system. Following the previous audit, Paua began calculating estimates and corrections manually to improve compliance until the HHR data management system process was implemented. They used method created for the HHR data management system. The previous Foxworks estimation process used a flat interval pattern and did not ensure that the sum of trading periods was consistent with the difference in midnight readings.

If an agreed switch reading differs from the actual data received from the MEP, the midnight reading is entered with the lowest read quality value (10) to ensure that it is retained and not overwritten with actual data, and the trading period values will be estimated to ensure that they are consistent with the difference between the agreed switch reading and next actual reading.

If errors are found when validating HHR readings, such as a stopped or faulty meter, consumption can be estimated. The estimated data would be entered with the lowest read quality value (10) to ensure that it is retained and not overwritten with actual data.

The process for estimation of missing data in the HHR data management system is set out below:

- the HHR data management system imports the meter reading and interval data and assigns a read quality flag; the flag indicates whether midnight readings and some or all interval data is present, and if a reading has been modified to match an agreed switch reading,
- the HHR data management system compares the HHR data imported to the daily registry list to identify ICPs where HHR data is expected and identify missing trading period data,
- where midnight readings and/or interval data is missing, the HHR data management system's daily estimation process creates estimated midnight readings and/or interval data,
- the HHR data management system's deduplication process identifies meters with multiple readings/volumes for the ICP meter trading period combination and removes the values with the highest data quality flag (i.e., the poorest quality data), and
- the HHR data management system checks that the midnight reading = the next day's midnight reading — the next day's trading period volumes; if there is a difference, the HHR data management system will alert an operator for manual estimation using the HHR data management system's data estimation rules.

The estimation methodology ensures that estimates are based on midnight reads if they are available and consumption is profiled between trading periods based on a similar period with actual data. If no history is available, Paua will request consumption history from the previous trader and use it to calculate an estimate.

If actual data is received following estimation, it will be imported, and retained through the deduplication process.

One correction (0000121079TR333 – 16 September 2022) around AMI meter changes was reviewed to ensure all volume was accounted for. The HHR data management system installs and removes meters as at midnight to ensure there is no overlap of meters. Meters are removed using the last midnight reading provided by the AMI MEP and the new meter is installed from the next day using a start reading provided by the AMI MEP.

If there is any interval data available for the removed meter on the day of the meter change, then this volume is manually assigned to the new meter and this interval data is then scaled to ensure the total interval data aligns with the consumption between the install read and the first day's midnight read. Any consumption from the removed meter between the last interval downloaded and the time of the meter change is not accounted for within Paua's estimation/correction process.

Audit outcome

Non-compliant

Non-compliance	С	Description	
Audit Ref: 8.2 With: Clause 19(2) Schedule 15.2	Some HHR consumption volume not accounted for during a HHR meter change for ICP 0000121079TR333. Potential impact: Low Actual impact: Low Audit history: None		
From: 01-Mar-21	Controls: Strong		
To: 30-Sep-22	Breach risk rating: 1		
Audit risk rating	Rationale for audit risk rating		
Low	The controls are strong because the estimation process is robust for most scenarios. The impact is low because the volume affected is small.		
Actions tak	Actions taken to resolve the issue Completion Remedial action state		
Adjusted volume included	in future volumes	Oct 2022	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
The SUM Check we conduct and each is individually acc	et daily will pick up meter changes eessed	Implemented	

8.3. Error and loss compensation arrangements (Clause 19(3) Schedule 15.2)

Code reference

Clause 19(3) Schedule 15.2

Code related audit information

A reconciliation participant may use error compensation and loss compensation as part of the process of determining accurate data. Whichever methodology is used, the reconciliation participant must document the compensation process and comply with audit trail requirements set out in the Code.

Audit observation

Review of a registry list with history confirmed that Paua do not supply any ICPs with metering category 2 or above.

Audit commentary

Paua has only supplied ICPs with metering category 1 and has not completed any new connections. No ICPs have required loss compensation.

Audit outcome

Compliant

8.4. Correction of HHR and NHH raw meter data (Clause 19(4) and (5) Schedule 15.2)

Code reference

Clause 19(4) and (5) Schedule 15.2

Code related audit information

In correcting a meter reading in accordance with clause 19, the raw meter data must not be overwritten. If the raw meter data and the meter readings are the same, an automatic secure backup of the affected data must be made and archived by the processing or data correction application.

If data is corrected or altered, a journal must be generated. The journal must contain the following:

19(5)(a)- the date of the correction or alteration

19(5)(b)- the time of the correction or alteration

19(5)(c)- the operator identifier for the person within the reconciliation participant who made the correction or alteration,

19(5)(d)- the half-hour metering data or the non-half hour metering data corrected or altered, and the total difference in volume of such corrected or altered data,

19(5)(e)- the technique used to arrive at the corrected data,

19(5)(f)- the reason for the correction or alteration.

Audit observation

Corrections are discussed in **sections 2.1** and **8.2**, which confirmed that raw meter data is not overwritten as part of the correction process. Audit trails are discussed in **section 2.4**. Raw meter data retention for MEPs and agents was reviewed as part of their own audits.

Audit commentary

Raw meter data is collected by the MEP, and data retention was reviewed as part of their MEP audits.

Corrections are discussed in **section 8.2**, which confirmed that raw meter data is not overwritten as part of the correction process. The HHR data management system creates a compliant correction journal when data is corrected. The raw meter data is retained as part of the correction journal.

As discussed in **section 2.4**, Paua has recently upgraded its HHR data management systems front end and as part of this effort a full back load of HHR interval data from the original source interval data files was conducted. This backload resulted in previous data estimations and corrections to be overwritten and resulting audit trails to be lost. Non-compliance is recorded in **section 2.4** for this single event resulting in the loss of historic audit trails and journals.

Audit outcome

9. ESTIMATING AND VALIDATING VOLUME INFORMATION

9.1. Identification of readings (Clause 3(3) Schedule 15.2)

Code reference

Clause 3(3) Schedule 15.2

Code related audit information

All estimated readings and permanent estimates must be clearly identified as an estimate at source and in any exchange of metering data or volume information between participants.

Audit observation

The event detail report was reviewed to identify all CS and RR files provided to other participants during the audit period. The accuracy of readings provided in a sample of CS and RR files was checked in sections 4.3, 4.4, 4.10 and 4.11.

Correct identification of estimated reads, and review of the estimation process was completed in **sections 8.2** and **9.4**.

Audit commentary

Readings are appropriately labelled with a data quality flag which indicates whether they are actual, estimated, or agreed switch readings where actual readings have been replaced with agreed switch readings. Estimates are identifiable at trading period level.

Review of CS and RR content confirmed that switch reads were correctly labelled. Readings are clearly identified in Paua's systems.

Audit outcome

Compliant

9.2. Derivation of volume information (Clause 3(4) Schedule 15.2)

Code reference

Clause 3(4) Schedule 15.2

Code related audit information

Volume information must be directly derived, in accordance with Schedule 15.2, from:

3(4)(a) - validated meter readings

3(4)(b) - estimated readings

3(4)(c) - permanent estimates.

Audit observation

Processes for derivation of volumes were discussed and observed.

Audit commentary

All readings are based on actual meter data, field services paperwork, or are provided by another trader via the switching process or estimated. In the future, if readings are not able to be obtained Paua will use customer supplied readings via digital photos from non-communicating AMI metered ICPs to estimate interval data. Paua records these readings as estimates.

Audit outcome

9.3. Meter data used to derive volume information (Clause 3(5) Schedule 15.2)

Code reference

Clause 3(5) Schedule 15.2

Code related audit information

All meter data that is used to derive volume information must not be rounded or truncated from the stored data from the metering installation.

Audit observation

A sample of submission data was reviewed in **sections 11** and **12**, to confirm that volume was based on readings as required. HHR AMI data is provided by AMS, Intellihub, and Metrix as MEPs. Compliance was assessed as part of their MEP audits.

Audit commentary

AMS, Intellihub, and Metrix are responsible for HHR data collection, and this was reviewed as part of their audits. The MEP retains raw, unrounded data.

Meter reading data is recorded in Paua's system to three decimal places. The rounding methodology is now aligned between HHRVOLS and HHRAGGS files ensuring the data between these two files is consistent.

HHRVOLS and HHRAGGS files for the consumption periods April 2021, June 2021, September 2021, November 2021, February 2022 and March 2022 were reviewed to ensure alignment. For most consumption periods and revisions, the difference between the HHRVOLS & HHRAGGS was less than 10 kWh (0.004%). The difference between these file types for September 2021 revisions R1 and R3 was 1,530 kWh where HHRVOLS exceeded HHRAGGS and Paua was not able to identify the cause of this difference.

Audit outcome

Non-compliant

Non-compliance	Description
Audit Ref: 9.3 With: Clause 3(5) Schedule 15.2 From: 01-Mar-21	The HHR aggregates information is not aligned with HHR submission volumes for September R1 and R3. Potential impact: Low Actual impact: Low Audit history: None Controls: Strong
To: 30-Sep-22	Breach risk rating: 1
Audit risk rating	Rationale for audit risk rating
Low	The controls are strong as the process to generate these files simultaneously ensures data alignment. The impact is low, because the aggregates are not used to calculate reconciliation results and the differences between the volumes and aggregates are less than 1%.

Actions taken to resolve the issue	Completion date	Remedial action status
Cycle 14 Reports matched	Cleared	Cleared
Preventative actions taken to ensure no further issues will occur	Completion date	
FOXworks presents the operator with a checksum to enable the volumes of the two reports to match.		

9.4. Half hour estimates (Clause 15 Schedule 15.2)

Code reference

Clause 15 Schedule 15.2

Code related audit information

If a reconciliation participant is unable to interrogate an electronically interrogated metering installation before the deadline for providing submission information, the submission to the reconciliation manager must be the reconciliation participant's best estimate of the quantity of electricity that was purchased or sold in each trading period during any applicable consumption period for that metering installation.

The reconciliation participant must use reasonable endeavours to ensure that estimated submission information is within the percentage specified by the Authority.

Audit observation

The HHR estimate process was examined, and a sample of three estimates were reviewed.

Metrix and Intellihub provide estimates where data is missing. Paua does not use these estimates and creates their own as described below.

Audit commentary

HHR estimations are processed in the HHR data management system.

The process for estimation of missing data in the HHR data management system is set out below:

- the HHR data management system imports the meter reading and interval data and assigns a read
 quality flag; the flag indicates whether midnight readings and some or all interval data is present,
 and if a reading has been modified to match an agreed switch reading,
- the HHR data management system compares the HHR data imported to the daily registry list to identify ICPs where HHR data is expected and identify missing trading period data,
- where midnight readings and/or interval data is missing, the HHR data management system's daily estimation process creates estimated midnight readings and/or interval data,
- the HHR data management system's deduplication process identifies meters with multiple readings/volumes for the ICP meter trading period combination and removes the values with the highest data quality flag (i.e., the poorest quality data), and
- the HHR data management system checks that the midnight reading = the next day's midnight reading — the next day's trading period volumes; if there is a difference, the HHR data management system will alert an operator for manual estimation using the HHR data management system's data estimation rules.

If no history is available, Paua will request consumption history from the previous trader and use it to calculate an estimate.

If actual data is received following estimation, it will be imported and retained through the deduplication process.

Four examples of estimates were identified during the audit period and three were accurately processed according to the methodology above and reasonable endeavours requirements were met. For ICP 0000126746TR077 the estimated interval data for 11 April 2022 did not align with the calculated consumption between the supplied midnight reads by 11 kWh and the cause was identified as human error when manually processing this estimation.

Audit outcome

Non-compliant

Non-compliance	0	Description		
Audit Ref: 9.4 With: Clause 15 Schedule 15.2	The estimation performed for ICP 0000126746TR077 did not match the consumption calculated from the supplied midnight reads by 11 kWh. Potential impact: Low			
	Actual impact: Low			
	Audit history: None			
From: 01-Mar-21	Controls: Strong			
To: 30-Sep-22	Breach risk rating: 1			
Audit risk rating	Rationale for audit risk rating			
Low	The controls are strong because the estimation process is robust for most scenarios.			
	The impact is low because the volume	e affected is 11 kV		
Actions take	en to resolve the issue	Completion date	Remedial action status	
Volume included in future volumes Oct 2			Cleared	
Preventative actions taken to ensure no further issues will Completion date				
The SUM Check we conduct and each is individually acc	et daily will pick up meter changes Bessed	Implemented		

9.5. NHH metering information data validation (Clause 16 Schedule 15.2)

Code reference

Clause 16 Schedule 15.2

Code related audit information

Each validity check of non-half hour meter readings and estimated readings must include the following:

16(2)(a) - confirmation that the meter reading or estimated reading relates to the correct ICP, meter, and register,

16(2)(b) - checks for invalid dates and times,

16(2)(c) - confirmation that the meter reading or estimated reading lies within an acceptable range compared with the expected pattern, previous pattern, or trend,

16(2)(d) - confirmation that there is no obvious corruption of the data, including unexpected 0 values.

Audit observation

Review of the registry list with history confirmed that all ICPs supplied by Paua have HHR metering and submission type.

Audit commentary

All ICPs have submission type HHR, and this clause does not apply.

Audit outcome

Not applicable

9.6. Electronic meter readings and estimated readings (Clause 17 Schedule 15.2)

Code reference

Clause 17 Schedule 15.2

Code related audit information

Each validity check of electronically interrogated meter readings and estimate readings must be at a frequency that will allow a further interrogation of the data storage device before the data is overwritten within the data storage device and before this data can be used for any purpose under the Code.

Each validity check of a meter reading obtained by electronic interrogation, or an estimated reading must include:

17(4)(a) - checks for missing data,

17(4)(b) - checks for invalid dates and times,

17(4)(c) - checks of unexpected zero values,

17(4)(d) - comparison with expected or previous flow patterns,

17(4)(e) - comparisons of meter readings with data on any data storage device registers that are available,

17(4)(f) - a review of meter and data storage device event log for any event that could have affected the integrity of metering data must be investigated,

17(4)(g) – a review of the relevant metering data where there is an event that could have affected the integrity of the metering data.

If there is an event that could affect the integrity of the metering data (including events reported by MEPs but excluding where the MEP is responsible for investigating and remediating the event) the reconciliation must investigate and remediate any events.

If the event may affect the integrity or operation of the metering installation the reconciliation participant must notify the metering equipment provider.

Audit observation

I reviewed the HHR data validation process, including meter event logs, and volume validation processes.

Validation of electronic readings was also reviewed as part of the MEP audits.

Audit commentary

Electronic meter reading information is provided by the MEP, and data validation was reviewed as part of their MEP audits. Meters are interrogated regularly, and there is little risk that data can be overwritten. Data is held for a longer period at the meter and can be re-interrogated later if required.

HHR data validation is conducted using the HHR data management system's data management hub usually every two to three days, including:

• Meter event reporting

Meter event reports and clock synchronisation events provided by the MEP are imported into the HHR data management system. Paua works through the events, checking data before and after the event occurred using a graph to determine whether action is required. I reviewed four examples of HHR meter events and two examples of clock synchronisation events which did not impact on meter accuracy.

ICPs with zero kWh for the weekly billing cycle

Any ICPs with overall zero consumption for the weekly billing cycle are checked to determine whether the zero consumption is genuine.

Missing data

Any ICPs with data missing for an active trading period are checked. No exceptions usually occur because the HHR data management system estimates data for any missing trading periods on import.

Re-estimates required

Any ICPs with a difference between the midnight reading and the next day's midnight reading — the next day's trading period volumes are identified and re-estimated. Where the interval data was previously estimated, the HHR data management system recalculates estimated intervals and spread the difference pro-rata based on the previous estimated values.

A query is run to identify any ICPs which have not been read for more than 28 days, so that a communications fault can be sent to the MEP. During the audit Paua adjusted the query to report ICPs which have not been read for 21 days and added the report to the data management hub.

Paua checks that consumption is in line with expected patterns at an ICP level, as part of their weekly billing validations. An ICP list of weekly billed data is reviewed by sorting and checking values for reasonableness. During the audit, Paua expanded and automated the billing validation process to identify ICPs outside expected tolerances based on their consumption history, with graphs presenting the consumption information.

Paua does not validate whether an interval may exceed the maximum allowable kWh value for the metering installation capacity. This check is performed by a number of participants and their agents around C&I HHR data and is a useful tool to identify potential impacts of clock synchronisation time corrections where volumes may have been pushed into other periods, invalid interval data from faulty AMI meters or where estimations for a data gap results in unexpected consumption values. I recommend that Paua considers implementing additional validation encompassing checking interval data against the metering installation capacity.

Description	Recommendation	Audited party comment	Remedial action
Maximum allowable interval value check	Recommend that Paua considers implementing additional validation encompassing checking interval data against the metering installation capacity.	We will look at implementing this in a future revision of our system	Investigating

Audit outcome

10. PROVISION OF METERING INFORMATION TO THE GRID OWNER IN ACCORDANCE WITH SUBPART 4 OF PART 13 (CLAUSE 15.38(1)(F))

10.1. Generators to provide HHR metering information (Clause 13.136)

Code reference

Clause 13.136

Code related audit information

The generator (and/or embedded generator) must provide to the grid owner connected to the local network in which the embedded generator is located, half hour metering information in accordance with clause 13.138 in relation to generating plant that is subject to a dispatch instruction:

- that injects electricity directly into a local network; or
- if the meter configuration is such that the electricity flows into a local network without first passing through a grid injection point or grid exit point metering installation.

Audit observation

The NSP table on the registry was reviewed.

Audit commentary

Paua is not responsible for any NSPs. No information is provided to the pricing manager in accordance with this clause.

Audit outcome

Not applicable

10.2. Unoffered & intermittent generation provision of metering information (Clause 13.137)

Code reference

Clause 13.137

Code related audit information

Each generator must provide the relevant grid owner half-hour metering information for:

- any unoffered generation from a generating station with a point of connection to the grid 13.137(1)(a)
- any electricity supplied from an intermittent generating station with a point of connection to the grid. 13.137(1)(b)

The generator must provide the relevant grid owner with the half-hour metering information required under this clause in accordance with the requirements of Part 15 for the collection of that generator's volume information. (clause 13.137(2))

If such half-hour metering information is not available, the generator must provide the pricing manager and the relevant grid owner a reasonable estimate of such data. (clause 13.137(3))

Audit observation

The NSP table on the registry was reviewed.

Audit commentary

Paua is not responsible for any NSPs. No information is provided to the pricing manager in accordance with this clause.

Audit outcome

Not applicable

10.3. Loss adjustment of HHR metering information (Clause 13.138)

Code reference

Clause 13.138

Code related audit information

The generator must provide the information required by clauses 13.136 and 13.137,

with the requirements of Part 15 for the collection of the generator's volume information.

13.138(1)(a)- adjusted for losses (if any) relative to the grid injection point or, for embedded generators the grid exit point, at which it offered the electricity,

13.138(1)(b)- in the manner and form that the pricing manager stipulates,

13.138(1)(c)- by 0500 hours on a trading day for each trading period of the previous trading day. The generator must provide the half-hour metering information required under this clause in accordance

Audit observation

The NSP table on the registry was reviewed.

Audit commentary

Paua is not responsible for any NSPs. No information is provided to the pricing manager in accordance with this clause.

Audit outcome

Not applicable

10.4. Notification of the provision of HHR metering information (Clause 13.140)

Code reference

Clause 13.140

Code related audit information

If the generator provides half-hourly metering information to a grid owner under clauses 13.136 to 13.138, or 13.138A, it must also, by 0500 hours of that day, advise the relevant grid owner.

Audit observation

The NSP table on the registry was reviewed.

Audit commentary

Paua is not responsible for any NSPs. No information is provided to the pricing manager in accordance with this clause.

Audit outcome

Not applicable

11. PROVISION OF SUBMISSION INFORMATION FOR RECONCILIATION

11.1. Buying and selling notifications (Clause 15.3)

Code reference

Clause 15.3

Code related audit information

Unless an embedded generator has given a notification in respect of the point of connection under clause 15.3, a trader must give notice to the reconciliation manager if it is to commence or cease trading electricity at a point of connection using a profile with a profile code other than HHR, RPS, UML, EG1, or PV1 at least five business days before commencing or ceasing trader.

The notification must comply with any procedures or requirements specified by the reconciliation manager.

Audit observation

Review of the registry list with history confirmed that all ICPs supplied by Paua have HHR metering and submission type.

Audit commentary

Paua only uses the HHR profile; buying and selling notifications are not required.

Audit outcome

Compliant

11.2. Calculation of ICP days (Clause 15.6)

Code reference

Clause 15.6

Code related audit information

Each retailer and direct purchaser (excluding direct consumers) must deliver a report to the reconciliation manager detailing the number of ICP days for each NSP for each submission file of submission information in respect of:

15.6(1)(a) - submission information for the immediately preceding consumption period, by 1600 hours on the 4th business day of each reconciliation period

15.6(1)(b) - revised submission information provided in accordance with clause 15.4(2), by 1600 hours on the 13th business day of each reconciliation period.

The ICP days information must be calculated using the data contained in the retailer or direct purchaser's reconciliation system when it aggregates volume information for ICPs into submission information.

Audit observation

The process for the calculation of ICP days was examined by checking the ICP days submitted for February 2022 and July 2022 against the active ICP days recorded on the registry list for all NSPs.

I reviewed variances for 29 months of GR100 reports.

Audit commentary

AV110 files are generated from the HHR data management system based on aggregation factors and active ICP days from a current date ranged registry list. This is consistent with the logic for generating the AV090 and AV140 volumes and aggregates submissions which also use a date ranged registry list to

determine the correct aggregation factors and include all trading periods where the ICP has active status.

The review of the AV110 report for February 2022 and July 2022 found that the ICP days are calculated based on the registry list aggregation factors and active ICP days at the time that the report is generated.

The GR090 ICP Missing files and GR100 ICP days comparison files are imported into the HHR data management system on publication of reconciliation results, and any exceptions are checked.

The following table shows the ICP days difference between Paua's database and the RM return file (GR100) for all available revisions for 29 months. Negative percentage figures indicate that the Paua's ICP days are higher than those contained on the registry, and positive percentage figures indicate that the Paua's ICP days are lower than those contained on the Registry. The differences appear small and reasonable and were between -130 and +94 days.

Month	Ri	R1	R3	R7	R14
Mar-20	-0.18%	-0.18%	-0.31%	-0.31%	0.00%
Apr-20	-0.45%	-0.43%	-0.43%	-0.43%	0.00%
May-20	-0.53%	-0.50%	0.00%	0.00%	0.00%
Jun-20	-0.04%	-0.04%	0.00%	0.00%	0.00%
Jul-20	0.00%	-0.13%	-0.13%	-0.13%	0.00%
Aug-20	0.00%	0.00%	0.00%	0.00%	0.00%
Sep-20	0.01%	0.01%	0.01%	0.00%	0.00%
Oct-20	0.23%	0.23%	0.23%	0.00%	0.00%
Nov-20	-	0.15%	0.03%	0.00%	0.00%
Dec-20	-0.03%	-0.03%	0.00%	0.00%	0.00%
Jan-21	0.87%	0.87%	0.00%	0.00%	0.00%
Feb-21	0.05%	-0.13%	0.00%	0.00%	0.00%
Mar-21	-0.22%	0.00%	0.00%	0.00%	0.00%
Apr-21	-0.37%	0.00%	0.00%	0.00%	0.00%
May-21	0.00%	0.00%	0.00%	0.00%	0.00%
Jun-21	-0.07%	0.00%	0.00%	0.00%	0.00%

Month	Ri	R1	R3	R7	R14
Jul-21	0.00%	0.00%	0.00%	-0.08%	0.40%
Aug-21	0.00%	0.00%	0.00%	0.00%	-
Sep-21	0.00%	0.00%	0.00%	0.00%	-
Oct-21	0.16%	0.00%	0.00%	0.00%	-
Nov-21	-0.14%	-0.14%	-0.14%	0.00%	-
Dec-21	0.00%	0.00%	0.00%	0.00%	-
Jan-22	0.00%	0.00%	0.00%	0.00%	-
Feb-22	-0.05%	-0.05%	-0.05%	0.29%	-
Mar-22	0.41%	0.09%	0.00%	1	1
Apr-22	0.00%	0.00%	0.00%	ı	-
May-22	0.00%	0.00%	0.00%	-	-
Jun-22	-	-	0.40%	-	-
Aug-22	0.16%	0.19%	-	-	-

I checked five NSP level differences between the retailer and registry days and found that they related to the full reload of interval data as part of the implementation of a new front end to the HHR data management system which resulted in some previous data estimates to be lost resulting in small ICP days omissions for a small subset of ICPs.

Audit outcome

Compliant

11.3. Electricity supplied information provision to the reconciliation manager (Clause 15.7)

Code reference

Clause 15.7

Code related audit information

A retailer must deliver to the reconciliation manager its total monthly quantity of electricity supplied for each NSP, aggregated by invoice month, for which it has provided submission information to the reconciliation manager, including revised submission information for that period as non- loss adjusted values in respect of:

15.7(a) - submission information for the immediately preceding consumption period, by 1600 hours on the 4th business day of each reconciliation period

15.7(b) - revised submission information provided in accordance with clause 15.4(2), by 1600 hours on the 13th business day of each reconciliation period.

Audit observation


The process for the calculation of as billed volumes was examined. GR130 reports for December 2018 to May 2022 were reviewed to confirm whether the relationship between billed and submitted data appears reasonable.

Audit commentary

AV120 files are generated from the HHR data management system based on invoiced volumes and invoices are selected for inclusion in the AV120 report based on their invoice date.

I compared billed submission information against the HHR aggregates submissions for the periods April 2021, June 2021, September 2021, November 2021, November 2021, February 2022 and March 2022 for reasonableness. The data appeared reasonable and consistent.

The difference between the billed and submitted data has increased during the audit period and was 3.0% for the year ended May 2022 (billed higher than submitted) and 2.2% for the two years ended May 2022 (billed lower than submitted). The differences are primarily causes by timing, because Paua customers are billed weekly and the number of billing cycles per month varies.



Audit outcome

11.4. HHR aggregates information provision to the reconciliation manager (Clause 15.8)

Code reference

Clause 15.8

Code related audit information

A retailer or direct purchaser (excluding direct consumers) must deliver to the reconciliation manager its total monthly quantity of electricity supplied for each half hourly metered ICP for which it has provided submission information to the reconciliation manager, including:

15.8(a) - submission information for the immediately preceding consumption period, by 1600 hours on the 4th business day of each reconciliation period

15.8(b) - revised submission information provided in accordance with clause 15.4(2), by 1600 hours on the 13th business day of each reconciliation period.

Audit observation

I confirmed that the process for the calculation and aggregation of HHR data is correct, by matching HHR aggregates information with the HHR volumes data for eight submissions. I traced three ICPs across seven monthly volumes for HHR ICPs from the source data to the HHR data management system and the HHR aggregates submissions. The sample included all MEPs.

The GR090 ICP missing files were examined for March 2020 to May 2022. An extreme case sample of the ten ICPs with the most frequent ICP missing differences were reviewed.

Audit commentary

AV090 and AV140 files are generated from the HHR data management system based on actual and estimated data for each trading period. Aggregation factors are determined from a current date ranged registry list. Volumes are included in the submissions for all trading periods where the ICP has active status on the registry.

I checked that the process for the calculation and aggregation of HHR data is correct, by:

- matching HHR aggregates information with the HHR volumes data for eight submissions, and
- tracing three ICPs across seven monthly volumes for HHR ICPs from the source data to the HHR
 data management system and the HHR aggregates submissions; the volumes recorded in the
 HHR data management system and the submissions matched the raw data provided.

The GR090 ICP missing files are imported into the HHR data management system on publication of reconciliation results, and any exceptions are checked. I examined GR090 files all revisions for March 2020 to May 2022. An extreme case sample of the ten ICPs missing from the most revisions were examined:

- five ICPs were temporarily missing because of backdated switches/switch withdrawals,
- two ICPs were late status updates to inactive status on the registry,
- two ICPs were missing from some submission periods prior to this audit because of an
 incorrect status, or incorrect NSP; both errors were corrected after the previous audit, and the
 ICPs have been correctly included in revisions since the corrections, and
- one ICP was reported against a different NSP due to late processing of a registry network event to update the NSP assignment.

I followed up GR090 exceptions identified in the previous audit and found that they had all been cleared prior to the audit, or revision 14 had passed and they were unable to be cleared.

Audit outcome

12. SUBMISSION COMPUTATION

12.1. Daylight saving adjustment (Clause 15.36)

Code reference

Clause 15.36

Code related audit information

The reconciliation participant must provide submission information to the reconciliation manager that is adjusted for NZDT using one of the techniques set out in clause 15.36(3) specified by the Authority.

Audit observation

Data processes for AMS, Metrix and Intellihub were reviewed as part of their MEP audits. Submissions for periods with daylight savings changes were reviewed.

Audit commentary

Daylight savings processes for the MEPs were reviewed as part of their audit and found to be compliant.

The "trading period run on" technique is used for daylight saving adjustment. This was confirmed by checking submission data for the beginning and end of daylight savings. The correct number of trading periods were recorded.

Audit outcome

Compliant

12.2. Creation of submission information (Clause 15.4)

Code reference

Clause 15.4

Code related audit information

By 1600 hours on the 4th business day of each reconciliation period, the reconciliation participant must deliver submission information to the reconciliation manager for all NSPs for which the reconciliation participant is recorded in the registry as having traded electricity during the consumption period immediately before that reconciliation period (in accordance with Schedule 15.3).

By 1600 hours on the 13th business day of each reconciliation period, the reconciliation participant must deliver submission information to the reconciliation manager for all points of connection for which the reconciliation participant is recorded in the registry as having traded electricity during any consumption period being reconciled in accordance with clauses 15.27 and 15.28, and in respect of which it has obtained revised submission information (in accordance with Schedule 15.3).

Audit observation

Processes to ensure that submissions are accurate were reviewed.

HHR submissions were checked in section 11.4, and correction processes were checked in section 8.2.

Alleged breaches during the audit period were reviewed to determine whether any reconciliation submissions were late.

Audit commentary

AV090 and AV140 files are generated from the HHR data management system based on actual and estimated data for each trading period. Aggregation factors are determined from a current date ranged registry list. Volumes are included in the submissions for all trading periods where the ICP has active status on the registry. Volumes are reviewed prior to submission as discussed in **section 9.6**.

The accuracy of the HHR aggregates and HHR volumes files is discussed in **section 11.4**. Vacant and disconnected ICPs will continue to receive readings, if provided by the MEP, but ICPs will only be included in submission data if their status is active for the period with consumption. Prior to the audit there was no process in place to identify consumption during inactive periods.

As described in **section 3.9**, inactive consumption for three ICPs was not included in submission due to a combination of incorrect statuses and status event dates.

The estimation process was reviewed in **section 9.4** and for ICP 0000126746TR077 the estimated interval data for 11 April 2022 did not align with the calculated consumption between the supplied midnight reads.

The correction process was reviewed in **section 8.2** and some HHR consumption volume was not accounted for during a HHR meter change for ICP 0000121079TR333.

There were two alleged breaches for late provision of submission information during the audit period. The cause of the late submission files was due to availability of key personnel to perform the submission tasks. Paua has a casual back up resource available to operate time dependant tasks where required using process documentation available for each task. However, the back-up resource is not actively involved in day-to-day operations, so their familiarity of some time critical tasks is limited. The result is some tasks are left until the key personnel become available. I recommend that Paua implements a task rotation schedule with its support resource to ensure they are familiar with each time dependant process and this will also ensure both the primary and back up personnel are aware of upcoming submission deadlines.

Description	Recommendation	Audited party comment	Remedial action
Rotation of tasks.	Paua to implement a task rotation schedule with its support resource to ensure they are familiar with each time dependant process, and this will also ensure both the primary and back up personnel are aware of upcoming submission deadlines.	The late submissions were because of a miscalculation of the 13th business Day. Numerous reminders are in place to now ensure the days are not mixed up	Identified

There was one alleged breach raised in relation to the accuracy of a single trading period within the R14 Dec 2020 AV-090 submission file. Paua's investigation as to the cause of this identified some corrupt internal data was the cause and a revised final revision file was produced and submitted. Non compliance is recorded here and in **section 12.7**

Audit outcome

Non-compliant

Non-compliance	С	Description		
Audit Ref: 12.2 With: Clause 15.4	Three ICPs where consumption occur under submission of HHR volumes.	red during an inad	ctive period resulting in	
With Clause 15.4	The estimation performed for ICP 0000126746TR077 did not match the consumption calculated from the supplied midnight reads by 11 kWh.			
	Some HHR consumption volume not a ICP 0000121079TR333.	ing a HHR meter change for		
	Submission files delivered late on two	occasions.		
	AV-090 Submission file for December trading period.	2020 R14 include	ed corrupt data for one	
	Potential impact: Low			
	Actual impact: Low			
	Audit history: Multiple times			
From: 01-Mar-21	Controls: Strong			
To: 30-Sep-22	Breach risk rating: 1			
Audit risk rating	Rationale	for audit risk rati	ng	
Low	Controls are assessed as strong as:			
	 there is an automated process to alert users where inactive consum occurs and the exceptions occurred during the period the action hul within the HHR data management system was offline to enable a sy- upgrade to be implemented, 			
	 the estimation process has a midnight reads where these 			
	 late delivery of submission fi 	les was due to ke	y personnel availability.	
	The impact is low because the volume	e affected is small	l.	
Actions take	en to resolve the issue	Completion date	Remedial action status	
Correct HHR volume for the	e corrupted period was reloaded	Cleared	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
Our system has several checks and balances to ensure that the reports are accurate including comparisons against days expected, last month's submission, previous submissions, and that the AV140 and AV090 sum matches.		Implemented		

12.3. Allocation of submission information (Clause 15.5)

Code reference

Clause 15.5

Code related audit information

In preparing and submitting submission information, the reconciliation participant must allocate volume information for each ICP to the NSP indicated by the data held in the registry for the relevant consumption period at the time the reconciliation participant assembles the submission information. Volume information must be derived in accordance with Schedule 15.2.

However, if, in relation to a point of connection at which the reconciliation participant trades electricity, a notification given by an embedded generator under clause 15.13 for an embedded generating station is in force, the reconciliation participant is not required to comply with the above in relation to electricity generated by the embedded generating station.

Audit observation

Processes to ensure that information used to aggregate the reconciliation reports is consistent with the registry were reviewed in **section 2.1**. The processes to ensure that submissions are accurate were discussed and observed.

Audit commentary

Submissions (including revisions) are currently generated using the HHR data management system. Submission data is validated:

- ICP level volumes are validated as described in section 9.6,
- the HHR data management system's metering data is compared to a registry list imported from the registry to ensure that all active ICP days are included, and actual or estimated data is available for each active trading period, and
- current submission totals are compared to previous submissions for the same month and previous month for reasonableness, and exceptions are investigated.

Submission and billing information are not compared prior to submission. Because billing is weekly and the number of billing runs varies from month to month, Paua found that this check was not worthwhile.

Aggregation factors are taken directly from date ranged registry list information, to ensure that they are correctly applied.

Audit outcome

Compliant

12.4. Grid owner volumes information (Clause 15.9)

Code reference

Clause 15.9

Code related audit information

The participant (if a grid owner) must deliver to the reconciliation manager for each point of connection for all of its GXPs, the following:

- submission information for the immediately preceding consumption period, by 1600 hours on the 4th business day of each reconciliation period (clause 15.9(a))
- revised submission information provided in accordance with clause 15.4(2), by 1600 hours on the 13th business day of each reconciliation period (clause 15.9(b)).

Audit observation

Review of the NSP table confirmed that Paua is not a grid owner.

Audit commentary

Review of the NSP table confirmed that Paua is not a grid owner, and is not required to submit grid owner volume information.

Audit outcome

Not applicable

12.5. Provision of NSP submission information (Clause 15.10)

Code reference

Clause 15.10

Code related audit information

The participant (if a local or embedded network owner) must provide to the reconciliation manager for each NSP for which the participant has given a notification under clause 25(1) Schedule 11.1 (which relates to the creation, decommissioning, and transfer of NSPs) the following:

- submission information for the immediately preceding consumption period, by 1600 hours on the 4th business day of each reconciliation period (clause 15.10(a))
- revised submission information provided in accordance with clause 15.4(2), by 1600 hours on the 13th business day of each reconciliation period (clause 15.10(b)).

Audit observation

A registry list was reviewed to confirm Paua does not own any local or embedded networks.

Audit commentary

Paua is not required to provide NSP submission information.

Audit outcome

Not applicable

12.6. Grid connected generation (Clause 15.11)

Code reference

Clause 15.11

Code related audit information

The participant (if a grid connected generator) must deliver to the reconciliation manager for each of its points of connection, the following:

- submission information for the immediately preceding consumption period, by 1600 hours on the 4th business day of each reconciliation period (clause 15.11(a))
- revised submission information provided in accordance with clause 15.4(2), by 1600 hours on the 13th business day of each reconciliation period. (clause 15.11(b))

Audit observation

The registry list and NSP table were reviewed.

Audit commentary

Paua is not a grid connected generator, therefore compliance was not assessed.

Audit outcome

Not applicable

12.7. Accuracy of submission information (Clause 15.12)

Code reference

Clause 15.12

Code related audit information

If the reconciliation participant has submitted information and then subsequently obtained more accurate information, the participant must provide the most accurate information available to the reconciliation manager or participant, as the case may be, at the next available opportunity for submission (in accordance with clauses 15.20A, 15.27, and 15.28).

Audit observation

Processes to ensure the accuracy of submission information were reviewed, and the submission data itself was reviewed in **sections 11.2, 11.3** and **11.4**.

Alleged breaches during the audit period were reviewed to determine whether any reconciliation submissions were late.

Audit commentary

AV090 and AV140 files are generated from the HHR data management system based on actual and estimated data for each trading period. Aggregation factors are determined from a current date ranged registry list. Volumes are included in the submissions for all trading periods where the ICP has active status on the registry. Volumes are reviewed prior to submission as discussed in **section 9.6**.

The accuracy of the HHR aggregates and HHR volumes files is discussed in **section 11.4**. Vacant and disconnected ICPs will continue to receive readings, if provided by the MEP, but ICPs will only be included in submission data if their status is active for the period with consumption. Prior to the audit there was no process in place to identify consumption during inactive periods.

As described in **section 3.9**, inactive consumption for three ICPs were not included in submission due to a combination of incorrect statuses and status event dates.

The estimation process was reviewed in **section 9.4** and for ICP 0000126746TR077 the estimated interval data for 11 April 2022 did not align with the calculated consumption between the supplied midnight reads.

The correction process was reviewed in **section 8.2** and some HHR consumption volume was not accounted for during a HHR meter change for ICP 0000121079TR333.

There was one alleged breach raised in relation to the accuracy of a single trading period within the R14 Dec 2020 AV-090 submission file. Paua's investigation as to the cause of this identified some corrupt internal data was the cause and a revised final revision file was produced and submitted. Non compliance is recorded here and in **section 12.2**

Audit outcome

Non-compliant

Non-compliance	0	Description		
Audit Ref: 12.7 With: Clause 15.12	Three ICPs where consumption occur under submission of HHR volumes.	red during an ina	ctive period resulting in	
	The estimation performed for ICP 0000126746TR077 did not match the consumption calculated from the supplied midnight reads by 11 kWh.			
	Some HHR consumption volume not accounted for during a HHR meter change for ICP 0000121079TR333.			
	AV-090 Submission file for December trading period	2020 R14 include	ed corrupt data for one	
	Potential impact: Low			
	Actual impact: Low			
	Audit history: Multiple times			
	Controls: Strong			
From: 01-Mar-21	Breach risk rating: 1			
To: 30-Sep-22				
Audit risk rating	Rationale	for audit risk rati	ing	
Low	Controls are assessed as strong as:			
	 there is an automated process to alert users where inactive consumption occurs and the exceptions occurred during the period the action hub within the HHR data management system was offline to enable a system upgrade to be implemented, and 			
	the estimation process has a midnight reads where these	•	ensure volumes align with	
	The impact is low because the volume	e affected is small	l.	
Actions tak	en to resolve the issue	Completion date	Remedial action status	
See previous commentary.		Cleared	Identified	
Preventative actions tak	Preventative actions taken to ensure no further issues will occur			
Our system has many chec alert an operator for a fix.	ks to identify potential issues and	Implemented		

12.8. Permanence of meter readings for reconciliation (Clause 4 Schedule 15.2)

Code reference

Clause 4 Schedule 15.2

Code related audit information

Only volume information created using validated meter readings, or if such values are unavailable, permanent estimates, has permanence within the reconciliation processes (unless subsequently found to be in error).

The relevant reconciliation participant must, at the earliest opportunity, and no later than the month 14 revision cycle, replace volume information created using estimated readings with volume information created using validated meter readings.

If, despite having used reasonable endeavours for at least 12 months, a reconciliation participant has been unable to obtain a validated meter reading, the reconciliation participant must replace volume information created using an estimated reading with volume information created using a permanent estimate in place of a validated meter reading.

Audit observation

Review of the registry list with history confirmed that all ICPs supplied by Paua have HHR metering and submission type.

Audit commentary

Estimates are only applied where actual readings are not available or estimate readings have been applied for switching purposes.

Due to the nature of the AMI read process it is highly unlikely reads that have not been able to be retrieved for the previous 14 months, would be retrieved after more than 14 months. However Paua does not escalate any outstanding data gaps to the relevant MEP in an attempt to replace a previous estimated period once communications has been re-established. I recommend that Paua implements a process where all outstanding gaps in interval data are identified and escalated to the relevant MEP in a timely manner to ensure all available data has been provided to Paua before it is determined that the data gap is unrecoverable and the interim estimation becomes permanent.

Description	Recommendation	Audited party comment	Remedial action
Permanence of meter readings for reconciliation	Paua to implement a process where all outstanding gaps in interval data are identified and escalated to the relevant MEP in a timely manner to ensure all available data has been provided to Paua before it is determined that the data gap is unrecoverable, and the interim estimation becomes permanent.	We are looking into the viability of doing this	Investigating

Paua could not recall any ICPs where readings became available after revision 14; therefore all estimates were effectively permanent by revision 14.

Audit outcome

Compliant

12.9. Reconciliation participants to prepare information (Clause 2 Schedule 15.3)

Code reference

Clause 2 Schedule 15.3

Code related audit information

If a reconciliation participant prepares submission information for each NSP for the relevant consumption periods in accordance with the Code, such submission information for each ICP must comprise the following:

- half hour volume information for the total metered quantity of electricity for each ICP notified in accordance with clause 11.7(2) for which there is a category 3 or higher metering installation (clause 2(1)(a))for each ICP about which information is provided under clause 11.7(2) for which there is a category 1 or category 2 metering installation (clause 2(1)(b)):
 - a) any half hour volume information for the ICP; or
 - b) any non half hour volumes information calculated under clauses 4 to 6 (as applicable).
 - c) unmetered load quantities for each ICP that has unmetered load associated with it derived from the quantity recorded in the registry against the relevant ICP and the number of days in the period, the distributed unmetered load database, or other sources of relevant information. (clause 2(1)(c))
- to create non half hour submission information a reconciliation participant must only use information that is dependent on a control device if (clause 2(2)):
 - a) the certification of the control device is recorded in the registry; or
 - b) the metering installation in which the control device is location has interim certification.
- to create submission information for a point of connection the reconciliation participant must apply to the raw meter data (clause 2(3):
 - a) for each ICP, the compensation factor that is recorded in the registry (clause 2(3)(a))
 - b) for each NSP the compensation factor that is recorded in the metering installations most recent certification report. (clause 2(3)(b)).

Audit observation

Aggregation and content of reconciliation submissions was reviewed.

Audit commentary

Compliance with this clause was assessed:

- all Paua's ICPs have metering category 1, and are submitted as HHR,
- no ICPs with unmetered load are supplied,
- no profiles requiring a certified control device are used,
- no loss or compensation arrangements are required, and
- aggregation of the AV090 and AV140 reports is compliant.

Audit outcome

Compliant

12.10. Historical estimates and forward estimates (Clause 3 Schedule 15.3)

Code reference

Clause 3 Schedule 15.3

Code related audit information

For each ICP that has a non-half hour metering installation, volume information derived from validated meter readings, estimated readings, or permanent estimates must be allocated to consumption periods using the following techniques to create historical estimates and forward estimates (clause 3(1)).

Each estimate that is a forward estimate or a historical estimate must clearly be identified as such (clause 3(2)).

If validated meter readings are not available for the purpose of clauses 4 and 5, permanent estimates may be used in place of validated meter readings (clause 3(3)).

Audit observation

Review of the registry list with history confirmed that all ICPs supplied by Paua have HHR metering and submission type.

Audit commentary

All ICPs have submission type HHR, and this clause does not apply.

Audit outcome

Not applicable

12.11. Historical estimate process (Clause 4 and 5 Schedule 15.3)

Code reference

Clause 4 and 5 Schedule 15.3

Code related audit information

The methodology outlined in clause 4 of Schedule 15.3 must be used when preparing historic estimates of volume information for each ICP when the relevant seasonal adjustment shape is available.

If a seasonal adjustment shape is not available, the methodology for preparing an historical estimate of volume information for each ICP must be the same as in clause 4, except that the relevant quantities kWh_{Px} must be prorated as determined by the reconciliation participant using its own methodology or on a flat shape basis using the relevant number of days that are within the consumption period and within the period covered by kWh_{Px} .

Audit observation

Review of the registry list with history confirmed that all ICPs supplied by Paua have HHR metering and submission type.

Audit commentary

All ICPs have submission type HHR, and this clause does not apply.

Audit outcome

Not applicable

12.12. Forward estimate process (Clause 6 Schedule 15.3)

Code reference

Clause 6 Schedule 15.3

Code related audit information

Forward estimates may be used only in respect of any period for which an historical estimate cannot be calculated.

The methodology used for calculating a forward estimate may be determined by the reconciliation participant, only if it ensures that the accuracy is within the percentage of error specified by the Authority.

Audit observation

Review of the registry list with history confirmed that all ICPs supplied by Paua have HHR metering and submission type.

Audit commentary

All ICPs have submission type HHR, and this clause does not apply.

Audit outcome

Not applicable

12.13. Compulsory meter reading after profile change (Clause 7 Schedule 15.3)

Code reference

Clause 7 Schedule 15.3

Code related audit information

If the reconciliation participant changes the profile associated with a meter, it must, when determining the volume information for that meter and its respective ICP, use a validated meter reading or permanent estimate on the day on which the profile change is to take effect.

The reconciliation participant must use the volume information from that validated meter reading or permanent estimate in calculating the relevant historical estimates of each profile for that meter.

Audit observation

Review of the registry list with history confirmed that all ICPs supplied by Paua have HHR profile.

Audit commentary

Paua only uses the HHR profile, and no profile changes have occurred or are expected to occur.

Audit outcome

13. SUBMISSION FORMAT AND TIMING

13.1. Provision of submission information to the RM (Clause 8 Schedule 15.3)

Code reference

Clause 8 Schedule 15.3

Code related audit information

For each category 3 of higher metering installation, a reconciliation participant must provide half hour submission information to the reconciliation manager.

For each category 1 or category 2 metering installation, a reconciliation participant must provide to the reconciliation manager:

- Half hour submission information; or
- Non half hour submission information; or
- A combination of half hour submission information and non half hour submission information

However, a reconciliation participant may instead use a profile if:

- The reconciliation participant is using a profile approved in accordance with clause Schedule 15.5; and
- The approved profile allows the reconciliation participant to provide half hour submission information from a non half hour metering installation; and
- The reconciliation participant provides submission information that complies with the requirements set out in the approved profile.

Half hour submission information provided to the reconciliation manager must be aggregated to the following levels:

- NSP code
- reconciliation type
- profile
- loss category code
- flow direction
- dedicated NSP
- trading period

The non half hour submission information that a reconciliation participant submits must be aggregated to the following levels:

- NSP code
- reconciliation type
- profile
- loss category code
- flow direction
- dedicated NSP
- consumption period or day

Audit observation

Processes to ensure that information used to aggregate the reconciliation reports is consistent with the registry were reviewed in **section 2.1**.

Aggregation of HHR volumes is discussed in section 11.4.

Audit commentary

AV090 and AV140 files are generated from the HHR data management system based on actual and estimated data for each trading period. Aggregation factors are determined from a current date ranged registry list. Volumes are included in the submissions for all trading periods where the ICP has active status on the registry.

Submission information is provided to the reconciliation manager in the appropriate format and is aggregated to the following level:

- NSP code,
- reconciliation type,
- profile,
- loss category code,
- flow direction,
- dedicated NSP, and
- consumption period.

The previous audit issue relating to incorrect NSP assignment has been cleared.

Audit outcome

Compliant

13.2. Reporting resolution (Clause 9 Schedule 15.3)

Code reference

Clause 9 Schedule 15.3

Code related audit information

When reporting submission information, the number of decimal places must be rounded to not more than two decimal places.

If the unrounded digit to the right of the second decimal place is greater than or equal to five, the second digit is rounded up, and if the digit to the right of the second decimal place is less than five, the second digit is unchanged.

Audit observation

I reviewed 19 AV090 half hour volumes reports and 19 AV140 half hour aggregates reports to confirm how rounding occurs.

Audit commentary

Review of 19 AV090 and 9 AV140 reports confirmed that submission information is appropriately rounded to two decimal places.

Audit outcome

13.3. Historical estimate reporting to RM (Clause 10 Schedule 15.3)

Code reference

Clause 10 Schedule 15.3

Code related audit information

By 1600 hours on the 13th business day of each reconciliation period the reconciliation participant must report to the reconciliation manager the proportion of historical estimates per NSP contained within its non half hour submission information.

The proportion of submission information per NSP that is comprised of historical estimates must (unless exceptional circumstances exist) be:

- at least 80% for revised data provided at the month 3 revision (clause 10(3)(a))
- at least 90% for revised data provided at the month 7 revision (clause 10(3)(b))
- 100% for revised data provided at the month 14 revision (clause 10(3)(c)).

Audit observation

Review of the registry list with history confirmed that all ICPs supplied by Paua have HHR metering and submission type.

Audit commentary

All ICPs have submission type HHR, and this clause does not apply.

Audit outcome

Not applicable

CONCLUSION

Paua supplies HHR AMI ICPs with metering category 1, and HHR submission type. No ICPs with unmetered load are supplied, and one ICP with distributed generation is supplied.

Paua's bespoke HHR data management system began to be used for HHR meter data processes from 30 November 2020, following the material change audit. It was fully implemented for importing and exporting registry data, estimation, correction, and submission from 23 March 2021.

Paua's registry management and switching processes are robust and the overall data accuracy was found to be high. Eight of the non compliances identified relate to the implementation of an upgrade to Pauas HHR data management system which resulted in a number of automated processes being offline for a period of time. Paua has taken a number of learnings from this upgrade to ensure any future system upgrades do not have similar impacts.

Three alleged breaches occurred during the audit period and these related to the availability of key personnel during these time critical timelines. The resourcing issues have been resolved and no recent alleged breaches have occurred since.

Paua continues to supply HHR AMI customers only and relies on AMI reads provided by MEPs. Compliant processes are in place for estimation and correction, and revised submission data is now consistently provided.

This audit identified 15 non-compliances and makes four recommendations. The audit risk rating is 15 indicating that the next audit should be due in 18 months. While this is a slight reduction on compliance since the last audit, the majority of non compliance stem from two specific events around a system upgrade and temporary resource issues.

The date of the next audit is determined by the Electricity Authority and is dependent on the level of compliance during this audit. The table below provides some guidance on this matter, and I have considered this result in conjunction with Paua's responses and also their progress in resolving 11 of the non compliance identified in this report with the remaining identified non compliances are just awaiting submission revisions to complete the remedial actions. My recommendation for the next audit date is 24 months

PARTICIPANT RESPONSE

We note the audit risk rating is up slightly but are confident that our system now fully implemented will ensure we remain highly compliant going forward.

As a micro retailer, Paua to the People remains concerned at the cost ratio of compliance to margin. While we support the need for and learning opportunities presented by audits, Paua to the People believe that the audit cycle for small and micro independents is far too short. The impact that Paua to the People has on the New Zealand market is miniscule. For example, this audit found that under reporting by Paua to the People over the last 18 months was ~20 kWh or 0.0006% of our sales volumes.

We urge the Electricity Authority to consider a 24-month period before our next audit.