Compliance Plan NZTA Waimakariri DUML 2021

Deriving submission information				
Non-compliance	Description			
Audit Ref: 2.1 With: Clause 11(1) of	Estimated 274,918.08 kWh of under submission since switching to the CTCS profrom October 2020 up to February 2021.			
Schedule 15.3	Potential impact: High			
	Actual impact: High			
	Audit history: Once			
From: 28-May-19	Controls: None			
To: 28-Feb-21	Breach risk rating: 12			
Audit risk rating	Rationale for audit risk rating			
High	The controls were rated as none, because they were not sufficient to ensure that submission data is calculated accurately.			
	The impact is assessed to be high due to the level of submission inaccuracy.			
Actions taken to resolve the issue		Completion date	Remedial action status	
Under submissions related to Simply Energy's systems for unmetered management were corrected straight after the Material change audit was completed in August 2021.		31/8/21	Identified	
Submission issues relating to poor database management continue to exist as no data has been submitted by NZTA since Mainpower ceased management of the lights in their network.		Unknown		
Preventative actions taken to ensure no further issues will occur		Completion date		

Location of each item of load			
Non-compliance	Description		
Audit Ref: 2.3 With: Clause 11(2)(b) of	Location information insufficient to locate at least 51 items of load. Potential impact: Low		
Schedule 15.3	Actual impact: Low		
From: 28-May-19 To: 01-Apr-21	Audit history: Twice Controls: Weak Breach risk rating: 3		
Audit risk rating	Rationale for audit risk rating		
Low	The controls are recorded as weak because there are still many lights without sufficient information to locate them.		
	The impact is minor; therefore, the audit risk rating is low.		
Actions taken to resolve the issue		Completion date	Remedial action status
Unfortunately, this issue continues to exist as no data has been submitted by NZTA since Mainpower ceased management of the lights in their network.		Unknown	Investigating
Preventative actions taken to ensure no further issues will occur		Completion date	

Description and capacity of load			
Non-compliance	Description		
Audit Ref: 2.4	41 lights with no wattage recorded resulting in under submission of 28,047 kWh.		
With: Clause 11(2)(c)	Potential impact: Low		
and (d) of Schedule 15.3	Actual impact: Low		
	Audit history: None		
From: 28-May-19	Controls: Moderate		
To: 01-Apr-21	Breach risk rating: 2		
Audit risk rating	Rationale for audit risk rating		
Low	The controls are recorded as moderate because they mitigate risk most of the time but there is room for improvement. The impact on settlement and participants is minor; therefore, the audit risk rating is low.		
Actions taken to resolve the issue		Completion date	Remedial action status
Unfortunately, this issue continues to exist as no data has been submitted by NZTA since Mainpower ceased management of the lights in their network. We will update our current and historic submissions to match the values found by Veritek in their audit process as this is likely to be more accurate than the values we have been using (*in lieu of regular files from NZTA)		Unknown	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	

Database accuracy			
Non-compliance	Description		
Audit Ref: 3.1 With: Clause 15.2 and	41 lights with no wattage recorded resulting in under submission of 28,047 kWh [based on burn 4271 burn hours].		
15.37B(b)	Ten lamps have ballast added where this is not required, resulting in a very minor estimated under submission of 40W or 171 kWh p.a. based on 4,271 burn hours.		
	51 items of load with insufficient information to locate these.		
	Load changes no longer tracked in the Mainpower database.		
	Potential impact: High		
	Actual impact: Low		
From: 28-May-19	Audit history: None		
To: 01-Apr-21	Controls: None		
10. 01 Apr 21	Breach risk rating: 5		
Audit risk rating	Rationale for audit risk rating		
Low	Controls are rated as none as this databa	ase is no longer be	eing maintained.
	The impact is assessed to be low, based on the potential kWh variances detail above but this will increase until an alternative database is found to manage load.		
Actions t	aken to resolve the issue	Completion date	Remedial action status
Unfortunately, these issue continues to exist as no data has been submitted by NZTA since Mainpower ceased management of the lights in their network. We will update our current and historic submissions to match the values found by Veritek in their audit process as this is likely to be more accurate than the values we have been using (*in lieu of regular files from NZTA)		Unknown	Investigating
Preventative actions tak	en to ensure no further issues will occur	Completion date	

Volume information accuracy			
Non-compliance	Description		
Audit Ref: 3.2 With: Clause 15.2 and	Estimated 274,918.08 kWh of under submission since switching to the CTCS profile from October 2020 up to February 2021.		
15.37B(c))	Potential impact: High		
	Actual impact: High		
	Audit history: Once		
From: 28-May-19	Controls: None		
To: 28-Feb-21	Breach risk rating: 12		
Audit risk rating	Rationale for audit risk rating		
High	The controls were rated as none, because they were not sufficient to ensure that submission data is calculated accurately.		
	The impact is assessed to be high due to	the level of subm	ission inaccuracy.
Actions taken to resolve the issue		Completion date	Remedial action status
Under submissions related to Simply Energy's systems for unmetered management were corrected straight after the Material change audit was completed in August 2021.		31/8/21	Identified
Submission issues relating to poor database management continue to exist as no data has been submitted by NZTA since Mainpower ceased management of the lights in their network.		Unknown	
Preventative actions taken to ensure no further issues will occur		Completion date	