Compliance plan for The Embedded Network Company Reconciliation Participant Audit 2022

Relevant information					
Non-compliance	Description				
Audit Ref: 2.1 With: Clause 15.2(1)(a)	Inaccurate information was provided to the RM resulting in under submission of 64,029.20 kWh for NSP TGN0011.				
	Potential impact: High				
	Actual impact: High				
From: 19-Oct-21	Audit history: None				
To: 21-Oct-21	Controls: Weak				
	Breach risk rating: 9				
Audit risk rating	Rationale for audit risk rating				
High	The controls are recorded as weak as such a discrepancy should have been investigated and corrected before submission. The impact on settlement and participants was high and the RM breached TENCO in relation to this event.				
Actions taken to resolve the issue		Completion date	Remedial action status		
On the 21/10/2021 following a query of the incorrect submission in the R3 file Tenco worked with EMS to resubmit a revised R3 file.		21/10/2021	Identified		
Preventative actions taken to ensure no further issues will occur		Completion date			
For this instance, in both the R7 and R14 submissions Tenco via EMS will estimate the unavailable quantities based on retailer submissions.		Ongoing			
To avoid this on a go forward Tenco will not notify a new embedded network until we have proof the metering is installed. This does slow down our process, but we understand market impact of this.					
Tenco has developed a new data warehouse. One of the measures and KPIs we have put in place is monitoring the differences between retailer submissions, NSPVOLs and metered kWh.					

Submission accuracy					
Non-compliance	Description				
Audit Ref: 12.7 With: Clause 15.12	Inaccurate information was provided to the RM resulting in under submission o 64,029.20 kWh for NSP TGN0011.				
With Gladge 13:12	Potential impact: High				
	Actual impact: High				
From: 19-Oct-21	Audit history: None				
To: 21-Oct-21	Controls: Weak				
	Breach risk rating: 9				
Audit risk rating	Rationale for audit risk rating				
High	The controls are recorded as weak as such a discrepancy should have been investigated and corrected before submission.				
	The impact on settlement and participants was high and the RM breached TENCO in relation to this event.				
Actions taken to resolve the issue		Completion date	Remedial action status		
On the 21/10/2021 following a query of the incorrect submission in the R3 file Tenco worked with EMS to resubmit a revised R3 file.		21/10/2021	Identified		
Preventative actions taken to ensure no further issues will occur		Completion date			
For this instance, in both the R7 and R14 submissions Tenco via EMS will estimate the unavailable quantities based on retailer submissions.		Ongoing			
To avoid this on a go forward Tenco will not notify a new embedded network until we have proof the metering is installed. This does slow down our process, but we understand market impact of this.					
Tenco has developed a new data warehouse. One of the measures and KPIs we have put in place is monitoring the differences between retailer submissions, NSPVOLs and metered kWh.					