Compliance Plan SMRT Distributor 2023

| Provision of information | | | | |
|--|---|-----------------|------------------------|--|
| Non-compliance | Description | | | |
| Audit Ref: 2.2 With: 15.35 | Failure to submit data to the reconciliation manager NSP OWS0011-SMRT by business day four. | | | |
| | Potential impact: High Actual impact: Medium | | | |
| From: 01-Jun-22 | Audit history: None Controls: Strong | | | |
| To: 30-Jun-22 | Breach risk rating:2 | | | |
| Audit risk rating | Rationale for audit risk rating | | | |
| Medium | The controls are recorded as strong as the process controls have been strengthened since this incident to prevent this occurring again in the future. | | | |
| | The impact on settlement and participants was significant enough to raise a breach; therefore, the audit risk rating is medium. | | | |
| Actions taken to resolve the issue | | Completion date | Remedial action status | |
| Data was submitted around 5pm on the due date. | | 7/6/22 | Identified | |
| Preventative actions taken to ensure no further issues will occur | | Completion date | | |
| Although this event was unusual due to changes of staff, a more robust process has been put in place, as covered by the self-breach. | | ongoing | | |

| Arrangements for metering equipment provision | | | | |
|--|--|-----------------|------------------------|--|
| Non-compliance | Description | | | |
| Audit Ref: 2.13 | MEP not recorded for NSP OWS0011. | | | |
| With: 10.36 | Potential impact: High | | | |
| | Actual impact: Medium | | | |
| | Audit history: None | | | |
| From: 28-May-22 | Controls: Moderate | | | |
| To: 31-Dec-22 | Breach risk rating:2 | | | |
| Audit risk rating | Rationale for audit risk rating | | | |
| Low | The controls are recorded as moderate because they mitigate risk most of the time but there is room for improvement. There is no impact on settlement or participants, therefore the audit risk rating is | | | |
| Actions to | low. aken to resolve the issue | Completion date | Remedial action status | |
| Details were updated on the day we received them; a delay in receiving paperwork along with delays in livening meant that we didn't have a certification date to enter and hence no MEP was entered. | | 9/3/2023 | Identified | |
| Preventative actions taken to ensure no further issues will occur | | Completion date | | |
| Obtaining paperwork is an ongoing issue. We currently request repeatedly until we get it. | | Ongoing | | |

| Provision of NSP submission information | | | | | |
|--|--|-----------------|------------------------|--|--|
| Non-compliance | Description | | | | |
| Audit Ref: 12.5 With: 15.10 | Failure to submit data to the reconciliation manager NSP OWS0011-SMRT by business day four. Potential impact: High Actual impact: Medium Audit history: None | | | | |
| From: 01-Jun-22 To: 30-Jun-22 | Controls: Strong Breach risk rating:2 | | | | |
| Audit risk rating | Rationale for audit risk rating | | | | |
| Medium | The controls are recorded as strong as the process controls have been strengthened since this incident to prevent this occurring again in the future. The impact on settlement and participants was significant enough to raise a breach; therefore, the audit risk rating is medium. | | | | |
| Actions taken to resolve the issue | | Completion date | Remedial action status | | |
| Data was submitted around 5pm on the due date | | 7/6/22 | Identified | | |
| Preventative actions taken to ensure no further issues will occur | | Completion date | | | |
| Although this event was unusual due to changes of staff, a more robust process has been put in place, as covered by the self-breach. | | ongoing | | | |