Compliance plan for Waipa Network Distributor Audit 2023

Requirement to provide complete and accurate information				
Non-compliance	De	Description		
Audit Ref: 2.1	Registry information not complete an	d accurate in all ir	nstances.	
With: Clauses 11.2(1)	Potential impact: Low			
and 10.6(1)	Actual impact: Low			
	Audit history: Multiple times			
From: 01-Jun-22	Controls: Moderate			
To: 15-May-23	Breach risk rating: 2			
Audit risk rating	Rationale for audit risk rating			
Low	Controls are rated as moderate and will move to strong once the dashboard reporting includes dates.			
	The risk rating is assessed to be low as the number of ICPS affected is small in relation to the number of ICPs overall.			
Actions ta	Actions taken to resolve the issue Completion Remedial action state			
The team will run AC020 report weekly until reporting update is made in ARC		Current- already actioned	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
ARC Dashboard reporting update will provide visibility of data inaccuracies 31/08 /23				

Requirement to correct errors				
Non-compliance	Des	scription		
Audit Ref: 2.2	Errors not corrected as soon as praction	cable.		
With: Clauses 11.2(2)	Potential impact: Low			
and 10.6(2)	Actual impact: Low			
	Audit history: Multiple times			
From: 01-Jun-22	Controls: Moderate			
To: 15-May-23	Breach risk rating: 2			
Audit risk rating	Rationale for audit risk rating			
Low	Controls are rated as moderate and will move to strong once the dashboard reporting includes dates. The risk rating is assessed to be low as the number of ICPS affected is small in relation to the number of ICPs overall.			
Actions ta	Actions taken to resolve the issue Completion Remedial action statu			
The team will run AC020 report weekly until reporting update is made in ARC		Current- already actioned	Identified	
Preventative actions taken to ensure no further issues will Completion occur date				
ARC Dashboard reporting inaccuracies	g update will provide visibility of data	31/08/23		

Timeliness of ICP Information to the registry manager			
Non-compliance	Description		
Audit Ref: 3.4	Two ICPs not updated to "ready" prior to electricity being traded.		
With: Clauses 7(2) of	Potential impact: Low		
Schedule 11.1	Actual impact: Low		
	Audit history: Three times previously		
From: 25-Oct-22	Controls: Strong		
To: 01-May-23	Breach risk rating: 1		
Audit risk rating	Rationale for audit risk rating		
Low	Controls are rated as strong as ARC has robust controls to mitigate risk to an acceptable level.		
	The risk rating is low as the number of	ICPs affected is s	mall.
Actions taken to resolve the issue Completion Remedial action state			Remedial action status
of audit sample submissi	stem was newly implemented at time on. Staff have received further ure they understand the process in	Current- already actioned	Identified
Preventative actions to	aken to ensure no further issues will	Completion	

date

Current-

already

actioned

occur

identify system-related issues and report these in dashboard $% \left(\mathbf{r}\right) =\left(\mathbf{r}\right)$

ARC ICP Management system recently implemented will

reporting

Timeliness of initial electrical connection date				
Non-compliance	Description			
Audit Ref: 3.5	80 initial electrical connection dates not updated within ten business days.			
With: Clause 7(2A) of	Potential impact: Low			
schedule 11.1	Actual impact: Low			
5 04 4 00	Audit history: Multiple times previous	ly		
From: 01-Jun-22	Controls: Moderate			
To: 15-May-23	Breach risk rating: 2			
Audit risk rating	Rationale for audit risk rating			
Low	Controls are rated as moderate and will move to strong once the dashboard reporting includes dates.			
	The risk rating is low this has no direct impact on reconciliation.			
Actions tal	Actions taken to resolve the issue Completion Remedial action stat			
We have provided further training to staff in the new ICP Management system to ensure the use of 'event date' is already understood by the team.		already	Identified	
Preventative actions taken to ensure no further issues will Completion date				
ARC ICP Management system recently implemented will identify system-related issues and report these in dashboard		Current- already		
reporting. Prioritising on	reporting. Prioritising on dates is under development in ARC. actioned			

Monitoring of "new" & "ready" statuses			
Non-compliance	Description		
Audit Ref: 3.14 With: Clauses 15 of Schedule 11.1	Four of the five ICPs at "new" or "ready" for more than 24 months not confirmed as required.		
Scriedule 11.1	Potential impact: Low Actual impact: Low		
	Audit history: None		
From: 01-Jun-22	Controls: Moderate		
To: 15-May-23	Breach risk rating: 2		
Audit risk rating	Rationale for audit risk rating		
Low	Controls are rated as moderate as the quick reports do not contain dates to be able to identify those ICPs needing to be confirmed.		
	The risk rating is low as the number of ICPs affected is small.		
Actions taken to resolve the issue		Completion date	Remedial action status
The Audit Compliance report AC020 will be used as an interim tool to identify ICP creation statuses until ARC dashboard reporting is updated.		Current- already actioned	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
date, and date prioritisa	rd reporting to include ICP creation tion are in development and will entify anomalies in with ICP	31/08/23	

Timeliness of registry updates			
Non-compliance	Description		
Audit Ref: 4.1	12 late address updates.		
With: Clause 8 One late price update of the sample of ten ICPs.			
Schedule 11.1 96 late decommissioning status updates.			
	87 late distributed generation updates	S.	
	One late NSP change.		
	Potential impact: Low		
	Actual impact: Low		
	Audit history: Multiple		
From: 01-Jun-22	Controls: Strong		
To: 15-May-23	Breach risk rating: 1		
Audit risk rating	Rationale for audit risk rating		
Low	Controls are rated as strong as the controls in ARC will mitigate risk to an acceptable level.		
	The risk rating is low as the volume of	ICPs affected are	small.
Actions tal	Actions taken to resolve the issue Completion Remedial action statu		
Team have been reminded of the timeliness of registry updates and trained to ensure data input into ARC is accurate. ARC will resolve this issue going forward, as it flags these on our dashboard.		Current – already actioned	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
ARC ICP management system provides additional checks and reporting to help minimise any late notifications within our control		Current – already actioned	

Notice of NSP for each ICP				
Non-compliance	Des	Description		
Audit Ref: 4.2	One ICP mapped to wrong NSP and balancing area.			
With: Clause 7(1),(4) &	Potential impact: Low			
(5) Schedule 11.1	Actual impact: Low			
	Audit history: None			
From: 29-Jun-22	Controls: Moderate			
To: 19-Jun-23	Breach risk rating: 1			
Audit risk rating	Rationale fo	r audit risk rating		
Low	Controls are rated as moderate as development is still required to manage NSP changes effectively.			
	The risk rating is assessed to be low as Waipa operate two distinct network areas and the ICP affected was due to human error and has been corrected.			
Actions ta	Actions taken to resolve the issue Completion Remedial action stat			
Report AC020 will be used to monitor NSP changes and discrepancies. ICP in question has been corrected.		Current – already actioned	Cleared	
Preventative actions taken to ensure no further issues will occur		Completion date		
[Digital Stock to implement one of two possible solutions based on data available from GIS. Each solution will require manual approval before events are sent.]				

ICP location address			
Non-compliance	Des	scription	
Audit Ref: 4.4 With: Clause 2 Schedule 11.1 From: 01-Jun-22 To: 15-May-23	Approximately 620 ICPs with addressed Potential impact: Low Actual impact: Low Audit history: Multiple times Controls: Strong Breach risk rating: 1	es that are not rea	dily locatable.
Audit risk rating	Rationale fo	r audit risk rating	
Low	Controls are rated as strong going forward as the controls in ARC will mitigate risk to an acceptable level. The audit risk rating is low as this has no direct impact on reconciliation.		
Actions ta	ken to resolve the issue	Completion	Remedial action status

Actions taken to resolve the issue	Completion date	Remedial action status
We have done desk-based work to identify addresses and duplicates, however many of the ICPs identified require site visits which we intend to work through as resourcing allows. We will also work to identify ICPs where address information has been recorded correctly but in a different field of the record to improve accuracy of location.	Current – already actioned	Identified
Preventative actions taken to ensure no further issues will occur	Completion date	
[ARC ICP Management won't allow duplicate addresses and makes all the required registry address fields compulsory so incomplete addresses will be minimised.]	Current – already actioned	

Distributor to provide ICP information			
Non-compliance	Description		
Audit Ref: 4.6 With: Clause 7(1)	Chargeable capacity incorrectly recorded on the registry when it is being derived from the retailer billing files.		
Schedule 11.1	Two ICPs with the incorrect distributed generation details recorded of the sample of 28 ICPs checked.		
	Four ICPs with an incorrect initial elec	trical connection (date populated.
	One ICP with a "known" unmetered lo	oad not recorded	on the registry.
	Potential impact: Low		
	Actual impact: Low		
	Audit history: Multiple times		
From: 01-Jun-22	Controls: Strong		
To: 15-May-23	Breach risk rating: 1		
Audit risk rating	Rationale for audit risk rating		
Low	Controls are rated as strong with ARC in place as controls will mitigate risk to an acceptable level.		
	The risk rating is assessed to be low as	s data accuracy ov	verall is high.
Actions tal	ken to resolve the issue	Completion date	Remedial action status
Capacities have been amended and event stacking has been reversed. ICP 0001132003WA6F3 is still undergoing investigation to see if generation is recorded on the correct ICP.		31/08/2023	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
Monitoring the High-Risk database as well as checking the report EIEP1 & 3 to pick up any discrepancies. ARC has a separate field for separate storage of Chargeable Capacity values, which will not be sent up to the registry.		Ongoing and actioned.	