Compliance plan for Waitaki DC DUML Meridian 2022

Deriving submission info	ormation			
Non-compliance	Description			
Audit Ref: 2.1 With: Clause 11(1) of Schedule 15.3	The field audit found that database accuracy was not within the allowable +/- 5% threshold. This will be resulting in an estimated under submission of approximately 6,700 kWh per annum.			
Schedule 19.9	The monthly database extract provided does not track changes at a daily basis and is provided as a snapshot.			
	Potential impact: Low			
	Actual impact: Low			
	Audit history: Three times previously			
From: 18- Mar -20	Controls: Strong			
To: 12-Sep-22	Breach risk rating: 1			
Audit risk rating	Rationale for audit risk rating			
Low	Controls are rated as strong, the small number of exceptions indicated that controls are sufficient to ensure that all lamps are recorded in the database most of the time.			
	The impact is assessed to be low due to the small number of additional lights found in the field in relation to the overall count of the items of load.			
Actions taken to resolve the issue		Completion date	Remedial action status	
Discrepancies identified during the field audit will be provided to Network Waitaki for resolution and regularly follow up to ensure these are actioned.		30 Nov 22	Identified	
We have assessed our processes and tools to account for historic lamp installations and changes to the database at a daily level. There are checks in place comparing month to month snapshot data to identify any material changes and confirm details/dates for these. These are accounted for in monthly submission.		Ongoing		
Preventative actions taken to ensure no further issues will occur		Completion date		
Existing process controls for maintenance of the database will continue.		Ongoing		
Meridian will continue to work with database holders to request that monthly data extracts include the detail of changes.		Ongoing		

All load recorded in the database				
Non-compliance	Description			
Audit Ref: 2.5 With: Clause 11(2A) of Schedule 15.3	Three additional lights found in the field of 260 items of load sampled (1% error rate). Potential impact: Low			
	Actual impact: Low			
From: 18- Mar -20	Audit history: None			
To: 12-Sep-22	Controls: Strong			
	Breach risk rating: 1			
Audit risk rating	Rationale for audit risk rating			
Low	Controls are rated as strong, the small number of exceptions indicated that controls are sufficient to ensure that all lamps are recorded in the database most of the time.			
	The impact is assessed to be low due to three additional lights found in the field in relation to the overall count of the items of load.			
Actions taken to resolve the issue		Completion date	Remedial action status	
Discrepancies identified during the field audit will be provided to Network Waitaki for resolution and regularly follow up to ensure these are actioned.		30 Nov 22	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
Existing process controls for maintenance of the database will continue.		Ongoing		

Database accuracy				
Non-compliance	Description			
Audit Ref: 3.1 With: Clause 15.2 and 15.37B(b)	The field audit found that database accuracy was not within the allowable +/- 5% threshold. This will be resulting in an estimated under submission of approximately 6,700 kWh per annum.			
	Potential impact: Low			
From: 18- Mar -20	Actual impact: Low			
To: 12-Sep-22	Audit history: Three times previously			
·	Controls: Strong			
	Breach risk rating: 1			
Audit risk rating	Rationale for audit risk rating			
Low	Controls are rated as strong, the small number of exceptions indicated that controls are sufficient to ensure that all lamps are recorded in the database most of the time.			
	The impact is expected to be low base	ed on the kWh variar	ices identified.	
Actions taken to resolve the issue		Completion date	Remedial action status	
Discrepancies identified during the field audit will be provided to Network Waitaki for resolution and regularly follow up to ensure these are actioned.		30 Nov 22	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
Existing process controls for maintenance of the database will continue.		Ongoing		

Volume information accuracy				
Non-compliance	Description			
Audit Ref: 3.2 With: Clause 15.2 and 15.37B(c)		I that database accuracy was not within the allowable +/- 5% will be resulting in an estimated under submission of bkWh per annum.		
	The monthly database extract provided does not track changes at a daily basis and is provided as a snapshot.			
	Potential impact: Low			
	Actual impact: Low			
	Audit history: Three times previously			
From: 18- Mar -20	Controls: Strong			
To: 12-Sep-22	Breach risk rating: 1			
Audit risk rating	Rationale for audit risk rating			
Low	Controls are rated as strong, the small number of exceptions indicated that controls are sufficient to ensure that all lamps are recorded in the database most of the time. The impact is assessed to be low due to the small number of additional lights found in the field in relation to the overall count of the items of load.			
Actions taken to resolve the issue		Completion date	Remedial action status	
Discrepancies identified during the field audit will be provided to Network Waitaki for resolution and regularly follow up to ensure these are actioned.		30 Nov 22	Identified	
We have assessed our processes and tools to account for historic lamp installations and changes to the database at a daily level. There are checks in place comparing month to month snapshot data to identify any material changes and confirm details/dates for these. These are accounted for in monthly submission.		Ongoing		
Preventative actions taken to ensure no further issues will occur		Completion date		
Existing process controls for maintenance of the database will continue.		Ongoing		
Meridian will continue to work with database holders to request that monthly data extracts include the detail of changes.		Ongoing		