Compliance Plan Waterloo Park DUML 2022

Deriving submission information				
Non-compliance	Description			
Audit Ref: 2.1 With: Clause 11(1) of Schedule 15.3	Database accuracy is outside the allowable +/-5% threshold. Field audit findings indicate that there is 22% more load in the field than recorded in the database resulting in an estimated under submission of 3,118 kWh per annum.			
	The data used for submission does not track changes at a daily basis and is provided as a snapshot.			
Fuerra 42 May 20	Potential impact: Low			
From: 12-May-20	Actual impact: Low			
To: 04-Apr-22	Audit history: None			
	Controls: Weak			
	Breach risk rating: 3			
Audit risk rating	Rationale for audit risk rating			
Low	The controls are recorded as weak as the database used for submission has a lanumber of discrepancies.			
	The impact on settlement and particip is low.	ants is minor; therefo	ore, the audit risk rating	
Actions taken to resolve the issue		Completion date	Remedial action status	
Meridian has advised ORION of the inaccuracies and they now confirm that they have been corrected.		3/5/22	Identified	
We are considering how we can redesign our processes to incorporate the calculation of volumes at a daily level rather than a monthly snapshot.		Ongoing		
Preventative actions taken to ensure no further issues will occur		Completion date		
The majority of inaccuracies were due to lack of notification from the contractor (Connetics) regarding new installations and variations from initial designs.		5/8/22		
Meridian will work with Connetics to provide Orion with the install updates and changes to maintain the database in a timely manner				

All load recorded in database				
Non-compliance	Description			
Audit Ref: 2.5	Twelve additional lights found in the field (17% error rate).			
With: Clause 11(2A) of	Potential impact: Low			
Schedule 15.3	Actual impact: Medium			
	Audit history: Once			
From: 12-May-20	Controls: Weak			
To: 04-Apr-22	Breach risk rating: 6			
Audit risk rating	Rationale for audit risk rating			
Medium	The controls are recorded as weak as the database used for submission has a large number of discrepancies.			
	The impact is assessed to be medium due to the number of additional lights found in the field in relation to the overall count of the items of load.			
Actions taken to resolve the issue		Completion date	Remedial action status	
Meridian has advised ORION of the inaccuracies and they confirm that they have been corrected.		3/5/22	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
The majority of inaccuracies were due to lack of notification from the contractor (Connetics) regarding new installations and variations from initial designs.		5/8/22		
Meridian will work with Connetics to provide Orion with the install updates and changes to maintain the database in a timely manner				

Database accuracy				
Non-compliance	Description			
Audit Ref: 3.1 With: Clause 15.2 and 15.37B(b)	Database accuracy is outside the allowable +/-5% threshold. Field audit findings indicate that there is 22% more load in the field than recorded in the database resulting in an estimated under submission of 3,118 kWh per annum. Potential impact: Low			
From: 12-May-20	Actual impact: Low			
To: 04-Apr-22	Audit history: None			
	Controls: Weak			
	Breach risk rating: 3			
Audit risk rating	Rationale for audit risk rating			
Low	The controls are recorded as weak as the database used for submission has a large number of discrepancies The impact is expected to be low based on the kWh variances identified.			
Actions taken to resolve the issue		Completion date	Remedial action status	
Meridian has advised ORION of the inaccuracies and they confirm that they have been corrected.		3/5/22	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
The majority of inaccuracies were due to lack of notification from the contractor (Connetics) regarding new installations and variations from initial designs.		5/8/22		
Meridian will work with Connetics to provide Orion with the install updates and changes to maintain the database in a timely manner				

Volume information accuracy				
Non-compliance	Description			
Audit Ref: 3.2 With: Clause 15.2 and 15.37B(c)	Database accuracy is outside the allowable +/-5% threshold. Field audit findings indicate that there is 22% more load in the field than recorded in the database resulting in an estimated under submission of 3,118 kWh per annum. The data used for submission does not track changes at a daily basis and is provided			
	as a snapshot.			
From: 12-May-20	Potential impact: Low			
To: 04-Apr-22	Actual impact: Low			
	Audit history: None			
	Controls: Weak			
	Breach risk rating: 3			
Audit risk rating	Rationale for audit risk rating			
Low	The controls are recorded as weak as the database used for submission has a large number of discrepancies. The impact on settlement and participants is minor; therefore, the audit risk rating is low.			
Actions taken to resolve the issue		Completion date	Remedial action status	
Meridian has advised ORION of the inaccuracies and they confirm that they have been corrected.		3/5/22	Identified	
We are considering how we can redesign our processes to incorporate the calculation of volumes at a daily level rather than a monthly snapshot.		Ongoing		
Preventative actions taken to ensure no further issues will occur		Completion date		
The majority of inaccuracies were due to lack of notification from the contractor (Connetics) regarding new installations and variations from initial designs.		5/8/22		
Meridian will work with Connetics to provide Orion with the install updates and changes to maintain the database in a timely manner				