Compliance plan for Marlborough Lines DUML audit for Genesis Energy– 2021

Deriving submission information				
Non-compliance	Des	scription		
Audit Ref: 2.1 Clause 11(1) of	SST profile incorrectly applied to ICP 0004450157ML277 resulting in the incorrect burn hours being used to calculate submissions.			
Schedule 15.3	Submitted values do not match the database values resulting in an estimated under submission of 31,968 kWh per annum.			
	The monthly wattage report provided does not track changes on a daily basis and is provided as a snapshot.			
	Potential impact: Medium			
From: 24-Oct-20	Actual impact: Medium			
To: 14-Oct-21	Audit history: Multiple times			
	Controls: Moderate			
	Breach risk rating: 4			
Audit risk rating	Rationale for audit risk rating			
Medium	The controls are rated as moderate as processes to manage change capture most changes. The impact is assessed to be medium based on the submission values detailed above.			
Actions taken to resolve the issue		Completion date	Remedial action status	
Genesis has been using the summation details provided by Marlborough DC when reconciling the volumes. This has now been changed to using the raw data provided in order to calculate actual volumes used and is currently in the process of reviewing the consumption submitted in the last 14 months.		01/01/2022	Identified	
Genesis has discussed with council the importance of tracking of change which will increase the database accuracy level.		01/06/2022		
Regarding the profile of SST that was incorrectly assigned to ICP 0004450157ML277, this has now been rectified and updated to CST and backdated to Genesis gain date of the 01/04/2017.		01/01/2022		
Preventative actions t	aken to ensure no further issue will occur	Completion date		
Genesis will continue to develop tracking of change requirements with the council to enable compliance to be achieved.		Continuous improvement		

All load recorded in the database			
Non-compliance	Description		
Audit Ref: 2.5	Two additional items of load found in the field of the 470 items of load sampled.		
With: Clause 11(2A) of	Potential impact: Low		
Schedule 15.3	Actual impact: Low		
	Audit history: Once		
From: 24-Oct-20	Controls: Strong		
To: 14-Oct-21	Breach risk rating: 1		
Audit risk rating	Rationale for audit risk rating		
Low	The controls are rated as strong as Marlborough Lines have robust processes to ensure that changes are tracked, and this is reflected in the high level of accuracy found in the database. The impact is assessed to be low as the database was found to be within the allowable accuracy threshold as detailed in section 3 .1.		
Actions taken to resolve the issue		Completion date	Remedial action status
Genesis has discussed the audit findings with the council with the intent the council makes every effort to ensure the exceptions are rectified.		Continuous improvement	Identified
Preventative actions taken to ensure no further issue will occur		Completion date	
No comments provided.			

Tracking of load change			
Non-compliance	Description		
Audit Ref: 2.6	Changes not tracked.		
Clause 11(3) of	Potential impact: Low		
Schedule 15.3	Actual impact: Low		
	Audit history: Twice previously		
From: 24-Oct-20	Controls: Weak		
To: 14-Oct-21	Breach risk rating: 3		
Audit risk rating	Rationale for audit risk rating		
Low	The controls are rated as weak as whilst the processes for updating the database are robust, it was not proven that the database is able to meet the requirements of the code.		
	The audit risk rating is low as the volume of changes is not high.		
Actions taken to resolve the issue		Completion date	Remedial action status
Genesis has discussed with council the importance of tracking of change which will increase the database accuracy level.		Continuous improvement	Investigating
Preventative actions taken to ensure no further issue will occur		Completion date	
Genesis will continue to develop tracking of change requirements with the council to enable compliance to be achieved.		Continuous improvement	

Audit trails			
Non-compliance	Description		
Audit Ref: 2.7	Audit trail not visible.		
Clause 11(4) of	Potential impact: Low		
Schedule 15.3	Actual impact: Low		
5 04 0 4 40	Audit history: Twice previously		
From: 24-Oct-18	Controls: Weak		
To: 30-Sep-20	Breach risk rating: 3		
Audit risk rating	Rationale for audit risk rating		
Low	The controls are rated as weak as whilst the processes for updating the database are robust, it was not proven that the database is able to meet the requirements of the code.		
	The audit risk rating is low as the vol	ume of changes is n	ot high.
Actions taken to resolve the issue		Completion date	Remedial action status
Genesis has discussed with council the importance of tracking of change which will increase the database accuracy level.		Continuous improvement	Investigating
Preventative actions taken to ensure no further issue will occur		Completion date	
Genesis will continue to develop tracking of change requirements with the council to enable compliance to be achieved.		Continuous improvement	

Volume information accuracy			
Non-compliance	Description		
Audit Ref: 3.2 Clause 15.2 and	SST profile incorrectly applied to ICP 0004450157ML277 resulting in the incorrect burn hours being used to calculate submissions.		
15.37B(c)	Submitted values do not match the database values resulting in an estimated under submission of 31,968 kWh per annum.		
	The monthly wattage report provided does not track changes on a daily basis and is provided as a snapshot.		
	Potential impact: Medium		
	Actual impact: Medium		
	Audit history: Multiple times		
From: 24-Oct-20	Controls: Moderate		
To: 14-Oct-21	Breach risk rating: 4		
Audit risk rating	Rationale for audit risk rating		
Medium	The controls are rated as moderate as processes to manage change capture most changes.		
	The impact is assessed to be medium based on the submission values detailed above.		
Actions tak	en to resolve the issue	Completion date	Remedial action status
Genesis has been using the summation details provided by Marlborough DC when reconciling the volumes. This has now been changed to using the raw data provided in order to calculate actual volumes used and is currently in the process of reviewing the consumption submitted in the last 14 months.		01/01/2022	Identified
Regarding the profile of SST that was incorrectly assigned to ICP 0004450157ML277, this has now been rectified and updated to CST and backdated to Genesis gain date of the 01/04/2017.		01/01/2022	
	vith the council the importance of h will increase the database	01/06/2022	
Preventative actions	taken to ensure no further issue will occur	Completion date	
	develop tracking of change council to enable compliance to be		

achieved.