Compliance plan for Meridian MC HHR and UNM August 2022

Relevant information					
Non-compliance	Description				
Audit Ref: 2.1 With: Clause 11.2	Incorrect NHH submission flag and profile in the registry for C&I ICPs with associated unmetered load. Potential impact: Low				
From: 17-Aug-22 To: 17-Aug-22	Audit history: None				
	Controls: Strong Breach risk rating: 1				
Audit risk rating	Rationale for audit risk rating				
Low	The controls are recorded as strong because they mitigate risk to an acceptable level taking into account that this matter only has a impact on five ICPs. There is no impact on settlement; therefore the audit risk rating is low.				
Actions taken to resolve the issue		Completion date	Remedial action status		
Significant system development is required to enable an ICP to be recognised simultaneously as both HHR and NHH which would be required for the relevant NHH related Registry information to be maintained. Due to the very low numbers of ICPs where this is the case (currently 5) and lack of any market impact, it is not practical for this development to be undertaken.		N/A	Investigating		
Preventative actions taken to ensure no further issues will occur		Completion date			

Provision of information to the registry manager					
Non-compliance	Description				
Audit Ref: 3.5 With: Clause 9 of schedule 11.1	Incorrect NHH submission flag and profile in the registry for C&I ICPs with associated unmetered load. Potential impact: Low Actual impact: Low				
From: 17-Aug-22	Audit history: None				
To: 17-Aug-22	Controls: Strong				
	Breach risk rating: 1				
Audit risk rating	Rationale for audit risk rating				
Low	The controls are recorded as strong because they mitigate risk to an acceptable level taking into account that this matter only has a impact on five ICPs.				
	There is no impact on settlement; therefore the audit risk rating is low.				
Actions taken to resolve the issue		Completion date	Remedial action status		
Significant system development is required to enable an ICP to be recognised simultaneously as both HHR and NHH which would be required for the relevant NHH related Registry information to be maintained. Due to the very low numbers of ICPs where this is the case (currently 5) and lack of any market impact, it is not practical for this development to be undertaken.		N/A	Investigating		
Preventative actions taken to ensure no further issues will occur		Completion date			

Calculation of ICP days					
Non-compliance	Description				
Audit Ref: 11.2	NHH ICP days not submitted for the associated unmetered load for C&I ICPs.				
With: Clause 15.6	Potential impact: Low				
	Actual impact: Low				
From: 17-Aug-22	Audit history: None				
To: 17-Aug-22	Controls: Strong				
	Breach risk rating: 1				
Audit risk rating	Rationale for audit risk rating				
Low	The controls are recorded as strong because they mitigate risk to an acceptable level taking into account that this matter only has a impact on five ICPs. There is no impact on settlement; therefore the audit risk rating is low.				
Actions taken to resolve the issue		Completion date	Remedial action status		
Significant system development is required to enable an ICP to be recognised simultaneously as both HHR and NHH which would be required for NHH ICP days to be calculated and submitted. Due to the very low numbers of ICPs where this is the case (currently 5) and lack of any market impact, it is not practical for this development to be undertaken.		N/A	Investigating		
Preventative actions taken to ensure no further issues will occur		Completion date			