Compliance plan for Waikato DC DUML 2022

Deriving submission information				
Non-compliance	Description			
Audit Ref: 2.1 With: Clause 11(1) of	In absolute terms, total annual consumption is estimated to be 24,900 kWh higher than the DUML database indicates.			
Schedule 15.3	Submission is based on a snapshot and does not consider historic changes.			
	Potential impact: High			
	Actual impact: Medium			
	Audit history: Multiple times			
From: 16-Dec-21	Controls: Moderate			
To: 12-Oct-22	Breach risk rating: 4			
Audit risk rating	Rationale fo	r audit risk rating	:	
Medium	The controls are rated as moderate overall, but the new connection process requires improvement to move this to strong. The impact is assessed to be medium, based on the kWh differences.			
Actions taken to resolve the issue		Completion date	Remedial action status	
Meridian has advised of the inaccuracies identified and comments are in the relevant sections.		23/11/2022	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
We have assessed our processes and tools to account for historic lamp installations and changes to the database at a daily level. There are checks in place comparing month to month data to identify any material changes and confirm details for these. These are accounted for in monthly submission.		Ongoing		

All load recorded in database				
Non-compliance	Description			
Audit Ref: 2.5 With: Clause 11(2A) of Schedule 15.3	Nine items of load of a sample of 254 items checked in the field are missing from the database. Potential impact: Medium Actual impact: Low			
F 16 D 24	Audit history: Multiple times previously			
From: 16-Dec-21	Controls: Moderate			
To: 12-Oct-22	Breach risk rating: 2			
Audit risk rating	Rationale for audit risk rating			
Low	The controls are rated as moderate overall, but the new connection process requires improvement to move this to strong. The impact is assessed to be low, based on the quantity of additional lights.			
Actions taken to resolve the issue		Completion date	Remedial action status	
We have advised the Waikato District Alliance and Odyssey of the extra lights. They have advised that they are not yet the responsibility of the council. We will investigate and confirm who is responsible for them.		Ongoing	Identified	
We have advised Odyssey of the inaccuracies for the 4 missing lights and the 21 incorrect wattages in the database		23/11/2022		
Preventative actions taken to ensure no further issues will occur		Completion date		
Odyssey will be correcting the database for the 4 missing lights and the 21 incorrect wattages over the next 2 weeks.		23/12/2022		
Meridian will follow up with Odyssey to ensure the corrections are completed.		23/12/2022		

Database accuracy			
Non-compliance	Description		
Audit Ref: 3.1 With: Clause 15.2 and	In absolute terms, total annual consumption is estimated to be 24,900 kWh higher than the DUML database indicates.		
15.37B(b)	Potential impact: High		
	Actual impact: Medium		
	Audit history: Multiple times previously		
From: 16-Dec-21	Controls: Moderate		
To: 12-Oct-22	Breach risk rating: 4		
Audit risk rating	Rationale for audit risk rating		
Medium	The controls are rated as moderate as the processes in place to manage change are sufficient to mitigate risk most of the time. The impact is assessed to be medium, based on the kWh value above.		
Actions taken to resolve the issue		Completion date	Remedial action status
Meridian has advised of the inaccuracies identified and comments are in the relevant sections.		23/11/2022	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
No comments provided			

Volume information accuracy				
Non-compliance	Description			
Audit Ref: 3.2 With: Clause 15.2 and	In absolute terms, total annual consumption is estimated to be 24,900 kWh higher than the DUML database indicates.			
15.37B(c)	Submission is based on a snapshot and does not consider historic changes.			
	Potential impact: High			
	Actual impact: Medium			
	Audit history: Multiple times			
From: 16-Dec-21	Controls: Moderate			
To: 12-Oct-22	Breach risk rating: 4			
Audit risk rating	Rationale for audit risk rating			
Medium	The controls are rated as moderate overall, but the new connection process requires improvement to move this to strong.			
	The impact is assessed to be medium, based on the kWh differences.			
Actions taken to resolve the issue		Completion date	Remedial action status	
Meridian has advised of the inaccuracies identified and comments are in the relevant sections.		23/11/2022	Identified	
Preventative actions taken to ensure no further issues will occur		Completion date		
We have assessed our processes and tools to account for historic lamp installations and changes to the database at a daily level. There are checks in place comparing month to month data to identify any material changes and confirm details for these. These are accounted for in monthly submission.		Ongoing		