

The Authority's draft determinations of causers

Draft determinations of the causers of the 11 and 15 June 2017 under-frequency events

Consultation paper

Submissions close: 5 pm 7 November 2017

10 October 2017

Executive summary

Two under-frequency events occurred in June 2017

The Electricity Industry Participation Code 2010 (Code) requires the Electricity Authority (Authority) to determine the causer of an under-frequency event (UFE), and prescribes the process for making its determination (clause 8.61).

The purpose of this paper is to:

- (a) set out the Authority's draft determinations of the causers of the 11 and 15 June 2017 UFEs
- (b) consult with interested parties on the Authority's draft determinations.

The draft determinations on the June 2017 UFEs are being consulted on in conjunction due to the close timing and similar nature of the events.

The Authority's draft determinations of the causers

The Authority's draft determinations under clause 8.61 of the Code is that Contact Energy Limited (Contact), as the asset owner, was the causer of the UFEs on 11 June 2017 and 15 June 2017.

The Authority's reasons for these draft determinations are, in both cases:

- (a) the system operator has investigated the UFEs (in accordance with clause 8.60 of the Code), and has reported to the Authority that:
 - (b) the interruptions/reductions of energy occurred at the Taranaki Combined Cycle (Stratford) power station, which belongs to Contact
 - (c) no other asset was identified as having caused or potentially caused these UFEs
 - (d) in the system operator's view, Contact is the causer of both UFEs
- (e) Contact has accepted that it was the causer of both UFEs
- (f) having considered the system operator's reports and the relevant elements of the Code, the Authority (based on the information available to it at this time) concurs with the system operator's findings.

Submissions are invited from interested parties

The Authority must consult with interested parties before making its final determinations. Interested parties are invited to make a submission on the Authority's draft determinations by 5 pm on Tuesday 7 November 2017.

The Authority will consider all submissions received, and make a final determination on each UFF

The Authority also invites comment on the system operator's calculation of the megawatts (MW) lost during the event, which the system operator uses for calculating the UFE charge.

Contents

Exe	ecutive sumr	nary	i
1	What you need to know to make a submission What this consultation paper is about How to make a submission When to make a submission		
2	2 The Authority's draft determinations Contact was the causer of both UFEs		5 5
3	How the Authority reached these draft determinations The system operator investigated the causer The Authority has considered the system operator's report		
4	The Authority will consider submissions and make two final determinations		
5	The system operator has calculated the MW lost during the event based on its investigations		
App	oendix A	Format for submissions	g
App	oendix B	Under Frequency Event 11 June 2017 Causation Report	11
Apr	oendix C	Under Frequency Event 15 June 2017 Causation Report	12

1 What you need to know to make a submission

What this consultation paper is about

- 1.1 The purpose of this paper is to consult with interested parties on the Authority's draft determinations that:
 - (a) Contact was the causer of the 11 June 2017 UFE at 02:21 hours, when the frequency dropped to 49.09 Hz in the North Island, and 49.17 Hz in the South Island
 - (b) Contact was the causer of the 15 June 2017 UFE at 09:51 hours, when the frequency dropped to 49:17 in the North Island.

How to make a submission

- 1.2 The Authority's preference is to receive submissions in electronic format (Microsoft Word) in the format shown in Appendix A. Submissions in electronic form should be emailed to submissions@ea.govt.nz with "Consultation Paper—Draft determinations of the causers of the 11 and 15 June 2017 under-frequency events" in the subject line.
- 1.3 If you cannot send your submission electronically, post one hard copy to either of the addresses below, or fax it to 04 460 8879.

Postal address
Submissions
Electricity Authority
PO Box 10041
Wellington 6143
Electricity Authority
Level 7, ASB Bank Tower
2 Hunter Street
Wellington

- 1.4 Please note the Authority wants to publish all submissions it receives. If you consider we should not publish any part of your submission, please:
 - (a) indicate which part you do not want published
 - (b) explain why you consider we should not publish that part
 - (c) provide a version of your submission that we can publish (if we agree not to publish your full submission).
- 1.5 If you indicate there is part of your submission that should not be published, we will discuss with you before deciding whether to not publish that part of your submission.
- 1.6 However, please note that all submissions we receive, including any parts that we do not publish, can be requested under the Official Information Act 1982. This means we would be required to release material that we did not publish unless good reason existed under the Official Information Act to withhold it. We would normally consult with you before releasing any material that you said should not be published.

When to make a submission

- 1.7 Please deliver your submissions by **5 pm** on **7 November 2017**.
- 1.8 The Authority will acknowledge receipt of all submissions electronically. Please contact the Submissions' Administrator if you do not receive electronic acknowledgement of your submission within two business days.

2 The Authority's draft determinations

Contact was the causer of both UFEs

- 2.1 The Authority's draft determinations under clause 8.61 of the Code are that Contact was the causer of the UFEs that occurred on 11 June 2017 at 02:21 hours and on 15 June 2017 at 09:51 hours.
- 2.2 The system operator has investigated the UFEs and reported to the Authority that:
 - (a) a UFE occurred when frequency fell to 49.09 Hz in the North Island and 49.17 Hz in the South Island following a 325.6 MW reduction of electricity injected from the Stratford power station on 11 June 2017
 - (b) a UFE occurred when frequency fell to 49.17 Hz in the North Island following a 293.5 MW reduction of electricity injected from the Stratford power station on 15 June 2017.
 - (c) no other asset was identified as having caused or potentially caused either of the UFEs
 - (d) in the system operator's view, Contact was the causer of both UFEs
 - (e) Contact has accepted that it was the causer of both events.
- 2.3 Having considered the system operator's reports and the relevant elements of the Code, the Authority (based on the information available to it at this time) concurs with the system operator's findings.

3 How the Authority reached these draft determinations

The system operator investigated the causer

- 3.1 Clause 8.60 of the Code requires the system operator to investigate the causer of a UFE and provide a report to the Authority.
- 3.2 The system operator has fulfilled its obligations under clause 8.60. The system operator's reports to the Authority (dated August 2017) are attached as Appendix B and Appendix C.
- 3.3 The circumstances described in the reports for the UFEs are summarised in paragraphs 3.4 and 3.5.
- 3.4 In relation to the causation report on the 11 June 2017 UFE:
 - (a) On 11 June 2017 at 02:21 an interruption or reduction of energy occurred at the Stratford grid injection point (SFD). The frequency drop was arrested at 49.09 Hz in the North Island and 49.17 Hz in the South Island.
 - (b) The HVDC link and reserves operated and frequency was restored to the normal band quickly with no significant frequency overshoot.
 - (c) No other event was identified as contributing to or causing the UFE.
 - (d) The loss of injection of electricity into the grid was assessed by the system operator to be 325.6 MW.
 - (e) Copies of the following correspondence with Contact are included in the report:

- (i) the system operator wrote to Contact (26 June 2017) setting out its view that the event was initiated at the Stratford power station resulting in a loss of injection, and seeking any information Contact could provide
- (ii) in a reply to the system operator (19 July 2017) Contact agreed it was the causer of the event, and with the assessment of injection lost made by the system operator (Contact did not provide any further information).
- 3.5 In relation to the causation report on the 15 June 2017 UFE:
 - (a) On 15 June 2017 at 09:51 an interruption or reduction of energy occurred at the Stratford grid injection point (SFD). The frequency drop was arrested at 49.17 Hz in the North Island.
 - (b) Frequency was restored to the normal band quickly with no significant frequency overshoot.
 - (c) No other event was identified as contributing or causing the UFE.
 - (d) The loss of injection of electricity into the grid was assessed by the system operator to be 293.5 MW.
 - (e) Copies of the following correspondence with Contact are included in the report:
 - (i) the system operator wrote to Contact (19 July 2017) setting out its view that the event was initiated at the Stratford power station resulting in a loss of injection, and seeking any information Contact could provide
 - (ii) in a reply to the system operator (17 August 2017) Contact agreed it was the causer of the event, and with the assessment of injection lost made by the system operator (Contact did not provide any further information).

The Authority has considered the system operator's report

- 3.6 Clause 8.61(2) of the Code requires the Authority to publish a draft determination that states whether the UFE was caused by a generator or grid owner, and, if so, the identity of the causer. Clause 8.61(3) of the Code requires the Authority to give reasons for its findings in the draft determination.
- 3.7 The Authority has considered the system operator's reports and liaised directly with system operator staff in relation to the system operator's investigation and report.
- 3.8 Based on the information available to it, the Authority concurs with the system operator's findings that Contact was the causer of the UFEs on 11 and 15 June 2017. The Authority's draft determinations and reasons are set out above.
- Q1. Do you agree with the Authority's draft determination that Contact was the causer of the 11 June 2017 UFE? If not, please state your alternative view on the causer and give your reasons.
- Q2. Do you agree with the Authority's draft determination that Contact was the causer of the 15 June 2017 UFE? If not, please state your alternative view on the causer and give your reasons.

4 The Authority will consider submissions and make two final determinations

- 4.1 Clause 8.61(4) of the Code requires the Authority to consult every generator, grid owner and other participant substantially affected by a UFE in relation to a draft determination.
- 4.2 The Authority has allowed a consultation period of four weeks for these draft determinations. Accordingly, the deadline for submissions is 5 pm on Tuesday 7 November 2017.
- 4.3 The Authority will consider submissions received, and publish its final determinations.
- 4.4 Clauses 8.62 and 8.63 of the Code set out provisions relating to any disputes regarding Authority determinations.

5 The system operator has calculated the MW lost during the event based on its investigations

- 5.1 Clause 8.64 of the Code prescribes how the system operator must calculate the event charge payable by the causer of a UFE. This in turn enables calculation of the rebates paid for UFEs (clause 8.65 of the Code).
- 5.2 Central to the event charge calculation is determining the MW of injection lost at one or more grid injection points as a result of the UFE.
- 5.3 The system operator determines the MW lost as part of its investigations into a UFE.
- 5.4 The system operator has followed its published procedure *PR-RR-017 Calculating the Amount of MW lost* to determine the MW value provided to the clearing manager for the purposes of calculating the UFE charge. This procedure includes a factor of 95 % applied to the MW lost value to account for any margin of error.
- Based on its investigations and the application of its procedure, the system operator has determined that the loss of injection into the grid as a result of the:
 - (a) 11 June event was 325.6 MW at the Stratford grid injection point, resulting in an event charge of \$332,000
 - (b) 15 June event was 293.5 MW at the Stratford grid injection point, resulting in an event charge of \$291,819.
- The system operator's calculation of the MW lost during the UFE for the purposes of calculating the UFE charge is included in its report. Note this calculation does not form part of the Authority's draft determinations (refer clause 8.61 of the Code). However, the Authority acknowledges that the calculation is central to determining the UFE charge payable by the causer, and therefore also to the rebates paid for UFEs.
- 5.7 Accordingly, the Authority invites comment on the system operator's calculation of the MW lost, as set out in the system operator's report to the Authority.

.

The Authority discusses its approach to setting consultation periods for draft determinations in its consultation on the 8 September 2016 UFE.

- Q3. Do you agree with the system operator's calculation that, for the purposes of calculating the UFE charge, 325.6 MW was lost at the Stratford grid injection point as a result of the 11 June 2017 UFE? If not, please state your alternative view on the MW lost and give your reasons.
- Q4. Do you agree with the system operator's calculation that, for the purposes of calculating the UFE charge, 293.5 MW was lost at the Stratford grid injection point as a result of the 15 June 2017 UFE? If not, please state your alternative view on the MW lost and give your reasons.

Appendix A Format for submissions

Submitter	Submitter
-----------	-----------

Question		Comment
Q1.	Do you agree with the Authority's draft determination that Contact was the causer of the 11 June 2017 UFE? If not, please state your alternative view on the causer and give your reasons.	
Q2.	Do you agree with the Authority's draft determination that Contact was the causer of the 15 June 2017 UFE? If not, please state your alternative view on the causer and give your reasons.	
Q3.	Do you agree with the system operator's calculation that, for the purposes of calculating the UFE charge, 325.6 MW was lost at the Stratford grid injection point as a result of the 11 June 2017 UFE? If not, please state your alternative view on the MW lost and give your reasons.	

Q4. Do you agree with the system operator's calculation that, for the purposes of calculating the UFE charge, 293.5 MW was lost at the Stratford grid injection point as a result of the 15 June 2017 UFE? If not, please state your alternative view on the MW lost and give your reasons.	
---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--

Appendix B Under Frequency Event 11 June 2017 Causation Report

Under-Frequency Event - 11 June 2017 Causation Report

System Operator Event 3434

August 2017

Keeping the energy flowing









TRANSPOWER



Version	Date	Change
01	18 Aug 2017	

	Position	Date
Prepared By:	Hamish McKinnon, Compliance Advisor System Operations	24 Aug 2017
Reviewed By:	Scott Avery, Risk and Compliance Manager, System Operations	24 Aug 2017

IMPORTANT

Disclaimer

The information in this document is provided in good-faith and represents the opinion of Transpower New Zealand Limited, as the System Operator, at the date of publication. Transpower New Zealand Limited does not make any representations, warranties or undertakings either express or implied, about the accuracy or the completeness of the information provided. The act of making the information available does not constitute any representation, warranty or undertaking, either express or implied. This document does not, and is not intended to; create any legal obligation or duty on Transpower New Zealand Limited. To the extent permitted by law, no liability (whether in negligence or other tort, by contract, under statute or in equity) is accepted by Transpower New Zealand Limited by reason of, or in connection with, any statement made in this document or by any actual or purported reliance on it by any party. Transpower New Zealand Limited reserves all rights, in its absolute discretion, to alter any of the information provided in this document.

Copyright

The concepts and information contained in this document are the property of Transpower New Zealand Limited. Reproduction of this document in whole or in part without the written permission of Transpower New Zealand is prohibited.

Contact Details

Address: Transpower New Zealand Ltd

96 The Terrace PO Box 1021 Wellington New Zealand

Telephone: +64 4 495 7000 Fax: +64 4 498 2671

Email: <u>system.operator@transpower.co.nz</u>

Website: http://www.transpower.co.nz

Purpose.		. 4
	equency Event Details	
	on of MW Lost	
_	1: System Operations Correspondence	
	Confirmation of Event Notice	
1.2	Prior Notification of Causer	. 0
Appendix	2: Contact Energy Correspondence	11
2.1	Contact Energy Response	11
Appendix	3: Charts	12
3.1	Island Frequencies	12
3.2	Loss of Stratford (SPL) Generation	13

PURPOSE

- 1. At 02:21 on 11 June an interruption or reduction of energy occurred in the power system. The frequency fell to 49.09 Hz in the North Island and 49.17 Hz in the South Island.
- 2. As the frequency fell to below 49.25 Hz and as per clause 8.60 of the Electricity Industry Participation Code ('the Code') Transpower, as system operator, investigated this event to assist the Electricity Authority in determining the causer of the under-frequency event.
- **3.** The result of this investigation is this report prepared under clause 8.60(5) of the Code, provided to the Authority, and includes:
 - Whether in Transpower's view the UFE was caused by the grid owner or a generator and identifies that potential causer;
 - The reasons for forming this view; and
 - The information considered in reaching this view.

4

5

UNDER FREQUENCY EVENT DETAILS

- 4. On 11 June 2017 at 02:21 an interruption or reduction of energy occurred into the grid. In response the HVDC link and reserves operated to prevent a substantial fall in the frequency. The frequency was arrested at 49.09 Hz in the North Island and 49.17 Hz in the South Island.
- 5. The frequency was restored to the normal band quickly with no significant frequency overshoot.
- 6. Excursion Notices were sent immediately following the event

North Island

Date	Time	Minimum Hz	Island
11-Jun-2017	02:21:23	49.096	North

Date	Time	Maximum Hz	Island
11-Jun-2017	02:21:33	50.457	North

South Island

Date	Time	Minimum Hz	Island
11-Jun-2017	02:21:23	49.174	South

Date	Time	Maximum Hz	Island
11-Jun-2017	02:21:32	50.633	South

- 7. On 12 June 2017 Transpower published a 'Confirmation of Event' notice. (see appendix 1.1).
- 8. Analysis identified that the interruption/reduction in energy occurred at the Stratford grid injection point (SFD). No other event was identified as contributing or causing the under-frequency event.
- 9. On 26 June a letter was sent (see appendix 1.2) that outlined the details of the event and asked Contact Energy Ltd:
 - Whether Contact Energy considered itself to be the "causer" of the under-frequency event as defined in the Code;
 - whether Contact Energy agreed with the assessment of the loss of injection of electricity to the grid for the event was 325.6 MW (342.8 MW × 95% to account for the margin of error); and
 - any additional information to support their views.
- 10. On 19 July Contact Energy responded (see appendix 2.1) and accepted that due to the tripping of the Taranaki Combined Cycle power plant (TCC) they were the causer of the event and the assessed MW value of 325.6MW. No further information was provided.

CALCULATION OF MW LOST

- 11. To determine the MW value provided to the clearing manager for the purposes of calculating the under-frequency event charge. Transpower, as system operator, follows procedure PR-RR-017 "Calculating the Amount of MW lost".
- 12. This procedure follows the formula set out under section 8.64 of the Code for evaluating an event charge.

The **event charge** payable by the **causer** of an **under-frequency event** (referred to as "Event e" below) must be calculated in accordance with the following formula:

$$EC = ECR * (\sum y (INTye \text{ for all } y) - INJd)$$

where

EC is the **event charge** payable by the causer

ECR is \$1,250 per **MW**

INJd is 60MW

INTye is the electric power (expressed in **MW**) lost at point y by reason of Event e (being the net reduction in the **injection** of **electricity** (expressed in **MW**) experienced at point Y by reason of Event e) excluding any loss at point y by reason of secondary Event e

- y is a **point of connection** or the **HVDC injection point** at which the **injection** of **electricity** was interrupted or reduced by reason Event e
- 13. As the ECR and INJd values are constants the values to calculate and complete the formula are Y and INTye.
- 14. On 11 June the tripping of the TCC plant resulted in an interruption of energy into the grid at the Stratford grid injection point (GIP).
- 15. To establish the amount of MW lost SCADA data was extracted for the 60 seconds prior to the frequency reaching 49.25 Hz for generation behind the Stratford bus. After evaluation, the amount of MW lost causing the frequency to fall below 49.25Hz was determined to be 342.8 MW. For this event the loss of MW was virtually instantaneous and the 342.8 MW of generation passing through the Stratford bus into the network was completely lost when the frequency reached 49.25 Hz.
- 16. A factor of 95% is the applied to the MW lost value to account for any margin of error, reducing the MW lost value to 325.6 MW.
- 17. As a result, the final formula is as follows

EC = ECR * $(\nabla y (INTye \text{ for all } Y) - INJd)$

EC = \$1250 * (1 * (325.6MW) - 60MW)

EC = \$332,000

7

FINDING

- 18. Initial analysis identified the interruption or reduction of energy on 11 June 2017 occurred at the Stratford grid injection point, as a result of a tripping of the Taranaki Combined Cycle power plant. This asset belongs to Contact Energy Ltd.
- 19. In the response of 19 July 2017, Contact Energy Ltd. accepted that they were the causer of the event on 11 June 2017.
- 20. No other asset was identified as having caused or potentially causing the under-frequency event.
- 21. As such, Transpower, as the system operator, recommends that Contact Energy Ltd. be determined the causer of the under-frequency event on 11 June 2017.

Appendix 1: System Operations Correspondence

1.1 CONFIRMATION OF EVENT NOTICE



Monina Sta Romana Tel: (04) 590 6615 Fax: (04) 495 7154

8

Transpower House 96 The Terrace PO Box 1021 Wellington 6140 New Zealand P 64 4 495 7000 F 64 4 495 7100 www.transpower.co.nz


Date: 12 June 2017

To: Market Participants
cc: Clearing Manager
From: System Operator

Under-Frequency Event Confirmation

The System Operator wishes to advise market participants of the under-frequency event which occurred in both the North Island and South Island on 11 June 2017.

Rected Islands: North Island and South Island
North Island Minimum Frequency: 49.10 Hz
Time (start of UFE): 02:21:22
Time (of min. frequency): 02:21:24
South Island Minimum Frequency: 49.17 Hz
Time (start of UFE): 02:21:22
Time (of min. Frequency): 02:21:23



Market Operations Transpower NZ Ltd P.O. Box 1021, Wellington, New Zealand

Telephone : 04 590 7470 Facsimile : 04 495 7154

Keeping the energy (flowing

9

1.2 PRIOR NOTIFICATION OF CAUSER



Monina Sta Romana Tel: (04) 590 6615 Fax: (04) 495 7154

26 June 2017

Gerard Demler Contact Energy Limited P.O. Box 10742 Wellington Transpower House 96 The Terrace PO Box 1021 Wellington 6140 New Zealand P 64 4 495 7000 F 64 4 495 7100 www.transpower.co.nz

Dear Gerard,


11 June 2017 North Island and South Island Under-Frequency Event

On 11 June 2017, an under-frequency event occurred in the North Island and South Island at 02:21. Based on the information available we believe that the event was initiated at a Stratford generator resulting in a loss of injection from the Stratford power stations.

In order to report to the Electricity Authority as required by clause 8.60 of the Electricity Industry Participation Code 2010. We would appreciate any information you can provide around this event, and whether you accept Contact Energy Limited is the causer of the underfrequency event.

We have also calculated the loss of injection of electricity to the grid for the event as 325.6 MW (342.8 MW × 95% - to account for the margin of error). If you have a view on the amount of electricity lost during this event, please include that information in your response.

After receipt of your information Transpower, as the system operator will prepare a report for the Electricity Authority including whether the under-frequency was caused by a generator or grid owner, the identity of the potential causer, the reasons for and all the information considered in reaching our view.



Resping the decryy flowing Transmit New Training Call Transmit New Training Call Transmit New Training Carl

Could you please respond to the System Operator with your information relating to this event no later than 19 July 2017.

Return email address: market.operations@transpower.co.nz

Regards,

Monina Sta Romana

Market Analyst, Market Security Services

CC Hamish McKinnon (System Operator)

esping the energy (lowing Transporant New Zoolean) Intl The Androne God

10

Appendix 2: Contact Energy Correspondence

2.1 CONTACT ENERGY RESPONSE

Hi Monina,

We accept that Contact Energy's TCC plant was the causer of the 02:21 11 June under frequency event and agree on the amount of electricity lost at the time.

Regards


Gerard

Gerard Demler Transmission Manager Trading, Development, and Geothermal Resources

11

Appendix 3: CHARTS


3.1 ISLAND FREQUENCIES



12

3.2 Loss of Stratford (SPL) GENERATION

Loss of SPL Generation on 11 June 2017



13

Appendix C Under Frequency Event 15 June 2017 Causation Report

Under-Frequency Event - 15 June 2017 Causation Report

System Operator Event 3435

August 2017

Keeping the energy flowing









TRANSPOWER



Version	Date	Change
01	25 Aug 2017	

	Position	Date
Prepared By:	Hamish McKinnon, Compliance Advisor, System Operations	25 Aug 2017
Reviewed By:	Scott Avery, Risk and Compliance Manager, System Operations	25 Aug 2017

IMPORTANT

Disclaimer

The information in this document is provided in good-faith and represents the opinion of Transpower New Zealand Limited, as the System Operator, at the date of publication. Transpower New Zealand Limited does not make any representations, warranties or undertakings either express or implied, about the accuracy or the completeness of the information provided. The act of making the information available does not constitute any representation, warranty or undertaking, either express or implied. This document does not, and is not intended to; create any legal obligation or duty on Transpower New Zealand Limited. To the extent permitted by law, no liability (whether in negligence or other tort, by contract, under statute or in equity) is accepted by Transpower New Zealand Limited by reason of, or in connection with, any statement made in this document or by any actual or purported reliance on it by any party. Transpower New Zealand Limited reserves all rights, in its absolute discretion, to alter any of the information provided in this document.

Copyright

The concepts and information contained in this document are the property of Transpower New Zealand Limited. Reproduction of this document in whole or in part without the written permission of Transpower New Zealand is prohibited.

Contact Details

Address: Transpower New Zealand Ltd

96 The Terrace PO Box 1021 Wellington New Zealand

Telephone: +64 4 495 7000 Fax: +64 4 498 2671

Email: <u>system.operator@transpower.co.nz</u>

Website: http://www.transpower.co.nz

Purpose	. 4
Under Frequency Event Details	.5
Calculation of MW Lost	.6
Finding	.7
Appendix 1: System Operations Correspondence	.8
1.2 Prior Notification of Causer	
Appendix 2: Contact Energy Correspondence	11 11
Appendix 3: Charts	

PURPOSE

- 1. At 09:51 on 15 June an interruption or reduction of energy occurred in the power system. The frequency fell to 49.17 Hz in the North Island and 49.29 Hz in the South Island.
- 2. As the frequency fell to below 49.25 Hz in the North Island and per clause 8.60 of the Electricity Industry Participation Code ('the Code') Transpower, as system operator, investigated this event to assist the Electricity Authority in determining the causer of the under-frequency event.
- **3.** The result of this investigation is this report prepared under clause 8.60(5) of the Code, provided to the Authority, and includes:
 - Whether in Transpower's view the UFE was caused by the grid owner or a generator and identifies that potential causer;
 - The reasons for forming this view; and
 - The information considered in reaching this view.

4

5

UNDER FREQUENCY EVENT DETAILS

- 4. On 15 June 2017 at 09:51 an interruption or reduction of energy occurred into the grid. In response the HVDC link and reserves operated to prevent a substantial fall in the frequency. The frequency was arrested at 49.17 Hz in the North Island.
- 5. The frequency was restored to the normal band quickly with no significant frequency overshoot.
- 6. Excursion Notices were sent immediately following the event

North Island

Date	Time	Minimum Hz	Island
15-Jun-2017	09:51:53	49.17	North

Date	Time	Maximum Hz	Island
15-Jun-2017	09:52:19	50.232	North

- 7. On 21 June 2017 Transpower published a 'Confirmation of Event' notice. (see appendix 1.1).
- 8. Analysis identified that the interruption/reduction in energy occurred at the Stratford grid injection point (SFD). No other event was identified as contributing or causing the under-frequency event.
- 9. On 19 July a letter was sent (see appendix 1.2) that outlined the details of the event and asked Contact Energy Ltd:
 - Whether Contact Energy considered itself to be the "causer" of the under-frequency event as defined in the Code;
 - whether Contact Energy agreed with the assessment of the loss of injection of electricity to the grid for the event was 293.5 MW (308.9 MW × 95% to account for the margin of error); and
 - any additional information to support their views.
- 10. On 17 August Contact Energy responded (see appendix 2.1) and accepted that due to the tripping of the Taranaki Combined Cycle power plant (TCC) they were the causer of the event and the assessed MW value of 293.5 MW. No further information was provided.

CALCULATION OF MW LOST

- 11. To determine the MW value provided to the clearing manager for the purposes of calculating the under-frequency event charge. Transpower, as system operator, follows procedure PR-RR-017 "Calculating the Amount of MW lost".
- 12. This procedure follows the formula set out under section 8.64 of the Code for evaluating an event charge.

The **event charge** payable by the **causer** of an **under-frequency event** (referred to as "Event e" below) must be calculated in accordance with the following formula:

$$EC = ECR * (\sum y (INTye \text{ for all } y) - INJd)$$

where

EC is the **event charge** payable by the causer

ECR is \$1,250 per **MW**

INJd is 60MW

INTye is the electric power (expressed in **MW**) lost at point y by reason of Event e (being the net reduction in the **injection** of **electricity** (expressed in **MW**) experienced at point Y by reason of Event e) excluding any loss at point y by reason of secondary Event e

- y is a **point of connection** or the **HVDC injection point** at which the **injection** of **electricity** was interrupted or reduced by reason Event e
- 13. As the ECR and INJd values are constants the values to calculate and complete the formula are Y and INTye.
- 14. On 15 June the tripping of the TCC plant resulted in an interruption of energy into the grid at the Stratford grid injection point (GIP).
- 15. To establish the amount of MW lost SCADA data was extracted for the 60 seconds prior to the frequency reaching 49.25 Hz for generation behind the Stratford bus. After evaluation, the amount of MW lost causing the frequency to fall below 49.25Hz was determined to be 308.9 MW. For this event the loss of MW was virtually instantaneous and the 308.9 MW of generation passing through the Stratford bus into the network was completely lost when the frequency reached 49.25 Hz.
- 16. A factor of 95% is the applied to the MW lost value to account for any margin of error, reducing the MW lost value to 293.5 MW.
- 17. As a result, the final formula is as follows

 $EC = ECR * (\sum y (INTye \text{ for all } Y) - INJd)$

EC = \$1250 * (1 * (293.5MW) - 60MW)

EC = \$291,819

7

FINDING

- 18. Initial analysis identified the interruption or reduction of energy on 15 June 2017 occurred at the Stratford grid injection point, as a result of a tripping of the Taranaki Combined Cycle power plant. This asset belongs to Contact Energy Ltd.
- 19. In the response of 17 August 2017, Contact Energy Ltd. accepted that they were the causer of the event on 15 June 2017.
- 20. No other asset was identified as having caused or potentially causing the under-frequency event.
- 21. As such, Transpower, as the system operator, recommends that Contact Energy Ltd. be determined the causer of the under-frequency event on 15 June 2017.

Appendix 1: System Operations Correspondence

1.1 CONFIRMATION OF EVENT NOTICE



TRANSPOWER

Customer Advice Notice

To: CAN NZ Participants, cmanager@nzx.com,

NCC Ops Managers, Robynne Purdy, Manli

Chin

Sent: 21-jun-2017 16:44

Ref: 2459096069

From: The system operator

Telephone: 0800 488 500


Email: NMData@transpower.co.nz

Revision of:

Under-Frequency Event Confirmation

The System Operator wishes to advise market participants of the under-frequency event which occurred in the North Island on 15 June 2017.





A revision of this notice will be issued if there is any change to the situation above.

Limitation Of Liability/Disclaimer

Transpower make no representation or warranties with respect to the accuracy of the information contained in this document. Unless it is not lawfully permitted to do so. Transpower specifically disclaims any implied warranties of merchantability of fitness for any particular purpose and shall in no event be liable for, any loss of profit or any other commercial damage including but not limited to special incidental, consequential or other damages.

1.2 **PRIOR NOTIFICATION OF CAUSER**



Charles Chrystall

Tel: (04) 590 6739

Transpower House 96 The Terrace PO Box 1021 Wellington 6140 New Zealand P 64 4 495 7000 F 64 4 495 7100 www.transpower.co.nz

19 July 2017

Gerard Demler Contact Energy Ltd PO Box 10742 Wellington

Dear Gerard

Under frequency event 15 June 2017

On 15 June 2017, an under-frequency event occurred in the North Island at 09:51. Based on the information available we believe that this event was potentially caused by the Stratford Combined Cycle Gas Turbine Power Station.

In order to report to the Electricity Authority as required by clause 8.60 of the Electricity Industry Participation Code we would appreciate any information you can provide around this event, and whether you believe Contact Energy is the causer of this under-frequency event.

We have also calculated the loss of injection of electricity to the grid for the event as 293.5 MW (308.9 MW × 95% - to account for the margin of error). If you have a view on the amount of electricity lost during this event, please include that information in your response.

After receipt of your information Transpower (as system operator) will prepare and send a report to the Electricity Authority with our view on whether the under-frequency was caused by a generator or grid owner, the identity of the causer, the reasons for our view and all of the information considered in reaching our view.





Please respond to Transpower (as system operator) with your information relating to this event no later than 16 August 2017.

Regards,

Charles Chrystall Market Analyst

CC Hamish McKinnon (System Operator)

Septing the energy flowing Transport New Distance List The Mallored List

Appendix 2: Contact Energy Correspondence

2.1 CONTACT ENERGY RESPONSE

From: Gerard Demler [mailto:Gerard.Demler@contactenergy.co.nz]

Sent: Thursday, 17 August 2017 8:43 AM

To: Charles Chrystall < Charles.Chrystall@transpower.co.nz > Subject: RE: prior notification of causer (15 June UFE)

Hi Charles,

Yes we do accept that Contact's TCC generator was the causer of this event, and agree on the pre-event output generation amount.

Regards

Gerard

Gerard Demler

Transmission Manager Trading, Development, and Geothermal Resources

ph: 64 4 463 1890 mob: 027 704 5859

11

Appendix 3: CHARTS

3.1 ISLAND FREQUENCIES AND LOSS OF STRATFORD GENERATION

